## NDCRS ARCHITECTURAL FORM PAGE 1

Field Code Greatstone	School #2	Ş	SITS# 32 ML <sub>_</sub>	1402
Map Quad Horseshoe Valle Map Quad	у	Site Name Grea		
LTL T149 _ N., R8′ LTL T N., R LTL T N., R LTL T N., R LTL T N., R NAD1983 UTM NAD1983 UTM City: Street Number: Street Name:19th Ave N	M., Sec. 26 Q W., Sec. Q W., Sec. Q W., Sec. Q 5284392 Z 350436	QQ 5 of the QQ 5 QQ of the QQ Q QQ of the QQ Q QQ of the QQ  Zone 14N	of the Q 6 of the Q of the Q of the Q of the Q	Subsection 1 = N½ 2 = E½
Urban Legal Description:				
Total Number of Architectu	ıral Features:1	<u> </u>		
Fieldwork Date:05/31	/2021			
Reconnaissance Survey	<u></u>	itensive Survey		
Project & Principal Investiga Country School House Proje Kathy Wilner 366 43rd Ave SE, Bowdon, N	ct			
Contracting Firm or Agency	Completing the Forr	m:		
Additional Information:				
SHSND USE  Component  Component	Study Unit	Verified Site	_ CR Type	
Recorded By:	Kathy Wilner	Date R	ecorded:	06/06/2021

## NDCRS ARCHITECTURAL FORM PAGE 2 – Feature Data

Field Code Greatstone	School #2	;	SITS# 32	ML	1402
Complete one Page 2 for ea	ach architectural feature	at the site.			
Architectural Feature #1	_				
Construction Date					
Feature Date1880-1900					
Structural System Wood	Frame				
Original Owner's Ethnicity	_				
Feature Type 9 - School; Ch	urch school				
Context Education					
Primary Exterior Wood, I	lorizontal Siding				
Secondary Exterior					
Condition Fair					
Plan Shape Rectangular					
Style Other Style					
Architect/Builder					
Foundation Poured concre					
- 4/2 · Oakla					
Window Double hung oper	ings, some framing and no	glass			
Dating Method(s)Estimate	}				
Miscellaneous Information					
Feature Preservation Reco					
Individual nomination	. , .	7,			
Contributes to a pote	ntial district				
No nomination poten	tial				
Will not contribute to	a district				
Potential district—fea	ture would be a contributi	ng element if ot	her propert	ies co	onstitute a district
Thematic nomination	potential				
Component of a histo	oric site or landscape				
	scape, and spatial relation				period; b) recreates original with neighboring structures; o
Historical association	s require further investiga	tion			
Recorded By:	Kathy Wilner	Date F	Recorded	:	06/06/2021

## NDCRS ARCHITECTURAL FORM PAGE 3 – Feature Data

SITS# 32 ML 1402

Complete one Page 3 for each architectural feature at the site.

1. Feature Description, Integrity, Eligibility:

This feature is a one room prairie school on a poured concrete foundation. The gable roof of the school is mostly covered with wood shakes. Remnants of metal capping are seen at the peak. A red brick chimney sits at the peak near the east end of the roof. The soffits are closed. The building measures about 20 feet east to west and 18 feet north to south.

The siding begins with a rake board under the eaves at the peak ends of the school. All other siding is 6 inch wood lap with 6 inch corner trim. On the south wall there is a fuel door near the east end of the building. A double hung window opening, near the east end of the school on the north side, is located in the coatroom. A bank of 5 double hung window openings is located on the south side with a bit of framing and no glass. There is a single concrete step leading to the entry door opening, the door is gone. A small, covered transom sits above the entry door. Inside the entry there is a fuel storage room to the left and coat room to the right. A 5 panel wood door leads into that coat room from a small vestibule. Another opening on the west wall of the entry leads into the school room, the door lays on the floor inside the school room. The ceiling of the entry has lathe and plaster while the ceiling in the school room was finished with wallboard panels. Much of the ceiling has fallen in. The walls are wallboard. There are blackboards on the north half of the west and west half of the north wall. Wainscot can be seen on all walls in the school room. The floor is tongue and groove hardwood. I wonder if the building was used for grain storage at some point, a small opening on the south side at floor level could have been used to get grain out. There is also evidence of ropes and board lumber that held the walls together north to south. No evidence that electricity was ever used here.

2. Owner's Contact Information:

Albert Klain 1364 20th St NW Ruso ND 58778

Recorded By	: Kathy Wilner	Date Recorded:	06/06/2021

## NDCRS ARCHITECTURAL FORM

PAGE 4 – Site Description				
Fi	ield Code Greatstone School #2	SITS# 32 ML 1402		
3.	Site Area (ft²):			
4.	Description of Access and Site Setting:			
	This school is located along a gravel road north of a large so northeast and farm land all directions. To reach this school 11 miles to 18th St NW. Turn left (west) onto 18th St NW a NW. Turn right (north) and go 1 1/2 miles on 19th Ave NW side of the road.	go north of Turtle Lake about nd drive 4 miles to 19th Ave		
5.	Summary of ALL Site Features and Evaluation of Significance:			
6	References/Comments:			
б.	Kathy Wilner 366 43rd Ave SE Bowdon ND 58418			



North Side

Greatstone Township School

5/31/2021

Kathy Wilner

 $\mathsf{ML}$ 

West Side





South Side

**Greatstone Township School** 

5/31/2021

Kathy Wilner

ML



East Side



Imagery ©2021 CNES / Airbus, Maxar Technologies, USDA Farm Service Agency, Map data 200 ft ©2021 Feature