

NDCRS ARCHITECTURAL FORM

PAGE 1

UPDATE

Field Code \_\_\_\_\_

SITS# 32 MN 869 \_\_\_\_\_

Map Quad \_\_\_\_\_

Site Name \_\_\_\_\_

Map Quad \_\_\_\_\_

Site Name \_\_\_\_\_

LTL \_\_\_ T. \_\_\_ N., R. \_\_\_ W., Sec. \_\_\_ QQQ \_\_\_ of the QQ \_\_\_ of the Q \_\_\_

LTL \_\_\_ T. \_\_\_ N., R. \_\_\_ W., Sec. \_\_\_ QQQ \_\_\_ of the QQ \_\_\_ of the Q \_\_\_

LTL \_\_\_ T. \_\_\_ N., R. \_\_\_ W., Sec. \_\_\_ QQQ \_\_\_ of the QQ \_\_\_ of the Q \_\_\_

LTL \_\_\_ T. \_\_\_ N., R. \_\_\_ W., Sec. \_\_\_ QQQ \_\_\_ of the QQ \_\_\_ of the Q \_\_\_

NAD \_\_\_\_\_ UTM \_\_\_\_\_ Zone \_\_\_\_\_

NAD \_\_\_\_\_ UTM \_\_\_\_\_

City: \_\_\_\_\_

Subsection
1 = N½
2 = E½
3 = S½
4 = W½
5 = NE¼
6 = SE¼
7 = SW¼
8 = NW¼

Street Number: \_\_\_\_\_

Street Name: \_\_\_\_\_

Urban Legal Description: \_\_\_\_\_

Total Number of Architectural Features: \_\_\_\_\_

Fieldwork Date: \_\_\_\_\_

Reconnaissance Survey \_\_\_\_\_

Intensive Survey \_\_\_\_\_

Project & Principal Investigator: \_\_\_\_\_

Contracting Firm or Agency Completing the Form:

SHSND

Additional Information:

based on map checks by Kathy Wilner and aerial imagery

**SHSND USE**

Component \_\_\_\_\_ Study Unit \_\_\_\_\_ Verified Site \_\_\_\_\_ CR Type \_\_\_\_\_

Component \_\_\_\_\_

Component \_\_\_\_\_

Recorded By: Lorna Meidinger Date Recorded: 02/02/2022

Form instructions: (1) Download; (2) Save A Copy; (3) Submit a paper copy of the form to the SHSND and upload the PDF version of the form and corresponding GIS shapefiles to the ND SHPO-run FTP site.

**NDCRS ARCHITECTURAL FORM  
PAGE 2 – Feature Data**

**UPDATE**

**Field Code** \_\_\_\_\_

**SITS# 32 MN 869** \_\_\_\_\_

**Complete one Page 2 for each architectural feature at the site.**

Architectural Feature # 1

Construction Date \_\_\_\_\_

Feature Date \_\_\_\_\_

Structural System \_\_\_\_\_

Original Owner's Ethnicity \_\_\_\_\_

Feature Type \_\_\_\_\_

Context \_\_\_\_\_

Primary Exterior \_\_\_\_\_

Secondary Exterior \_\_\_\_\_

Condition Destroyed

Plan Shape \_\_\_\_\_

Style \_\_\_\_\_

Architect/Builder \_\_\_\_\_

Foundation \_\_\_\_\_ Stories \_\_\_\_\_

Roof/Cornice \_\_\_\_\_

Window \_\_\_\_\_

Dating Method(s) \_\_\_\_\_

Miscellaneous Information \_\_\_\_\_

**Feature Preservation Recommendation(s) (Check all that apply):**

Individual nomination

Contributes to a potential district

No nomination potential

Will not contribute to a district

Potential district—feature would be a contributing element if other properties constitute a district

Thematic nomination potential

Component of a historic site or landscape

Moved (specify all applicable choices)—a) relocation occurred within a historic period; b) recreates original site, orientation, landscape, and spatial relationships; c) compatible in context with neighboring structures; d) relocation has damaged eligibility

Historical associations require further investigation

**Recorded By:** Lorna Meidinger **Date Recorded:** 02/02/2022

**NDCRS ARCHITECTURAL FORM**

**PAGE 3 – Feature Data**

**UPDATE**

**Field Code** \_\_\_\_\_

**SITS# 32 MN 869** \_\_\_\_\_

**Complete one Page 3 for each architectural feature at the site.**

1. Feature Description, Integrity, Eligibility:

Based on aerial imagery available online from the ND Historical Map & Aerial Photography Dissemination Service, the school was removed between 7/25/2016 and 9/28/2017.

2. Owner's Contact Information:

**Recorded By:** \_\_\_\_\_ **Lorna Meidinger** \_\_\_\_\_ **Date Recorded:** \_\_\_\_\_ **02/02/2022** \_\_\_\_\_

**NDCRS ARCHITECTURAL FORM**

**PAGE 4 – *Site Description***

**UPDATE**

**Field Code** \_\_\_\_\_

**SITS# 32 MN 869** \_\_\_\_\_

3. Site Area (ft<sup>2</sup>):

4. Description of Access and Site Setting:

5. Summary of ALL Site Features and Evaluation of Significance:

6. References/Comments:

<http://aerial.swc.nd.gov/>

**Recorded By:** \_\_\_\_\_ **Lorna Meidinger** \_\_\_\_\_ **Date Recorded:** \_\_\_\_\_ **02/02/2022** \_\_\_\_\_

Form instructions: (1) Download; (2) Save A Copy; (3) Submit a paper copy of the form to the SHSND *and* upload the PDF version of the form and corresponding GIS shapefiles to the ND SHPO-run FTP site.

### NDCRS ARCHITECTURAL SITE FORM

PAGE 1

Field Code MAC-H8-HS2

SITS# 32 MN 869

#### SITE IDENTIFICATION

Map Quad Beldon SE Site Name \_\_\_\_\_  
Map Quad \_\_\_\_\_ Site Name \_\_\_\_\_

LTL	TWP	<u>153</u>	R	<u>91</u>	SEC	<u>2835</u>	QQQ	<u>88</u>	QQ	<u>88</u>	Q	<u>88</u>
LTL	TWP	_____	R	_____	SEC	_____	QQQ	_____	QQ	_____	Q	_____
LTL	TWP	_____	R	_____	SEC	_____	QQQ	_____	QQ	_____	Q	_____
LTL	TWP	_____	R	_____	SEC	_____	QQQ	_____	QQ	_____	Q	_____

UTM \_\_\_\_\_ 5323614 \_\_\_\_\_ N ZONE 13N  
UTM \_\_\_\_\_ 697355 \_\_\_\_\_ E NAD 1927  NAD 1983 \_\_\_\_\_

Subsection:
1 = N½
2 = E½
3 = S½
4 = W½
5 = NE¼
6 = SE¼
7 = SW¼
8 = NW¼

City: \_\_\_\_\_

Street Number: \_\_\_\_\_

Street Name: 43rd St NW

Urban Legal Description: \_\_\_\_\_

#### SITE DATA

Total # Architectural Features: 2

Fieldwork Date: 4/27/2011

Reconnaissance Survey \_\_\_\_\_ Intensive Survey

Project Title & Supervisor:  
NDDOT-HWY 8 FW-2011 - Debra Green

Report Title & Author(s):  
Highway 8: A Class III Cultural Resources Inventory in Mountrail County, North Dakota - Ed Stine

Additional Information: \_\_\_\_\_

#### SHSND USE

Area of Significance	<u>2</u>	Ecozone	<u>21</u>	Verified Site	<u>1</u>	CR Type	<u>2</u>
Area of Significance	<u>3</u>	Ecozone	<u>21</u>	Non-Site	_____		
Area of Significance	_____	Ecozone	_____				

Recorded By Debra Green Date Recorded 4/27/2011  
(First Name & Last Name) (mm/dd/year)

Instructions to complete a digital version of this form: (1) Download a copy to your hard drive; (2) Open the saved blank copy; (3) Fill out the form; (4) Use the Save As command to rename the form appropriately and save; (5) Print and submit to SHSND.

**NDCRS ARCHITECTURAL SITE FORM  
PAGE 2—Feature Data**

Field Code MAC-H8-HS2 SITS# 32 MN  
 Complete one Page 2 for each architectural feature at the site.

Architectural Feature # 1

Construction Date \_\_\_\_\_ Feature Type 9 Condition 3  
 Feature Date \_\_\_\_\_ Context 7 Plan Shape 2  
 Structural System X 25 Primary Exterior 26 Style \_\_\_\_\_  
 Original Owner's Ethnicity \_\_\_\_\_ Secondary Exterior \_\_\_\_\_ Architect/Builder \_\_\_\_\_

Other Information:

Old school house converted into the Crane Creek Township hall

Foundation Concrete Stories 1

Window Boarded up

Roof/Cornice Gable

Dating Method(s): \_\_\_\_\_

**Feature Preservation Recommendation(s) (Check all that apply):**

- Individual nomination
- Contributes to a potential district
- No nomination potential
- Will not contribute to a district
- Potential district—feature would be a contributing element if other properties constitute a district
- Thematic nomination potential
- Component of a historic site or landscape
- Moved (specify all applicable choices)—a) relocation occurred within a historic period; b) recreates original site, orientation, landscape, & spatial relationships; c) compatible in context with neighboring structures; d) relocation has damaged eligibility
- Historical associations require further investigation

Recorded By Debra Green Date Recorded 4/27/2011  
 (First Name & Last Name) (mm/dd/year)

*Instructions to complete a digital version of this form:* (1) Download a copy to your hard drive; (2) Open the saved blank copy; (3) Fill out the form; (4) Use the Save As command to rename the form appropriately and save; (5) Print and submit to SHSND.

**NDCRS ARCHITECTURAL SITE FORM**  
**PAGE 3—Feature Data**

Field Code MAC-H8-HS2 SITS# 32 MN

**1. Feature Description, Integrity, Eligibility:**

The feature is an abandoned school house/township hall. It is a single story feature with three attached rooms. It has a wood frame with horizontal wood planked siding and shingle roofing and is on a stone-concrete foundation. The structure measures approximately 10 meters north-south x 12 meters east-west. The attached front entry porch faces west and measures 3 meters north-south x 2 meters east-west. An attached smaller room faces the south and measures 5 meters north-south x 3 meters east-west. The third room is attached to the west side and measures 4 meters north-south x 2 meters east-west.

The structure is in poor condition. Much of the exterior paint is peeled off from weathering; a back entry door is broken off its hinges; all of the windows are boarded up with plywood. Most of the shingled roof is intact. Due to the lack of maintenance over time and long exposure to the elements, the site has deteriorated and lacks original feeling, design, materials, workmanship, and association.

It is recommended as ineligible for the National Register of Historic Places (NRHP).

Recorded By Debra Green Date Recorded 4/27/2011  
(First Name & Last Name) (mm/dd/year)

*Instructions to complete a digital version of this form: (1) Download a copy to your hard drive; (2) Open the saved blank copy; (3) Fill out the form; (4) Use the Save As command to rename the form appropriately and save; (5) Print and submit to SHSND.*

### NDCRS ARCHITECTURAL SITE FORM PAGE 2—Feature Data

Field Code MAC-H8-HS2 SITS# 32 MN

Complete one Page 2 for each architectural feature at the site.

Architectural Feature # 2

Construction Date _____	Feature Type <u>50</u>	Condition <u>3</u>
Feature Date _____	Context <u>7</u>	Plan Shape <u>6</u>
Structural System <del>X</del> <u>25</u>	Primary Exterior <u>26</u>	Style _____
Original Owner's Ethnicity _____	Secondary Exterior _____	Architect/Builder _____

Other Information:

Foundation Concrete Stories 1

Window Intact but in poor condition

Roof/Cornice Gable

Dating Method(s): \_\_\_\_\_

**Feature Preservation Recommendation(s) (Check all that apply):**

- Individual nomination
- Contributes to a potential district
- No nomination potential
- Will not contribute to a district
- Potential district—feature would be a contributing element if other properties constitute a district
- Thematic nomination potential
- Component of a historic site or landscape
- Moved (specify all applicable choices)—a) relocation occurred within a historic period; b) recreates original site, orientation, landscape, & spatial relationships; c) compatible in context with neighboring structures; d) relocation has damaged eligibility
- Historical associations require further investigation

Recorded By Debra Green Date Recorded 4/27/2011  
(First Name & Last Name) (mm/dd/year)

Instructions to complete a digital version of this form: (1) Download a copy to your hard drive; (2) Open the saved blank copy; (3) Fill out the form; (4) Use the Save As command to rename the form appropriately and save; (5) Print and submit to SHSND.



**NDCRS ARCHITECTURAL SITE FORM**  
**PAGE 3—Feature Data**

Field Code MAC-H8-HS2SITS# 32 MN**1. Feature Description, Integrity, Eligibility:**

Feature 2 is a privy associated with Feature 1. The feature is constructed of horizontal wood siding with a flat shingled roof. Four square windows, approximately 30 cm x 30 cm diameter are situated on the east and west sides of the structure with a row of smaller openings along the upper north wall. The entryway faces south.

The structure is intact, but in poor condition. Due to the lack of maintenance over time and long exposure to the elements, the site has deteriorated and lacks original feeling, design, materials, workmanship, and association.

The site is recommended as ineligible for the National Register of Historic Places (NRHP).

Recorded By Debra Green  
(First Name & Last Name)

Date Recorded 4/27/2011  
(mm/dd/year)

*Instructions to complete a digital version of this form: (1) Download a copy to your hard drive; (2) Open the saved blank copy; (3) Fill out the form; (4) Use the Save As command to rename the form appropriately and save; (5) Print and submit to SHSND.*

**NDCRS ARCHITECTURAL SITE FORM  
PAGE 4—SITE DESCRIPTION**Field Code MAC-H8-HS2SITS# 32 MN**Complete one Page 4 for the entire site.**

2. Owner's Contact Information:

3. Access (to rural areas):

From the town of Belden, travel south on Highway 8 for eight miles. The site is situated along the east side of Highway 8 at the corner of 43rd Street NW.

4. Site Area (ft<sup>2</sup>): 1,3005. *Site* Description:

The site is an abandoned standing structure situated on a high point within the rolling plains. The surrounding landscape is comprised of recently plowed agricultural fields. The site consists of two standing structures: a school house/township hall and an outhouse; and two historic features: a concrete foundation of a second outhouse; and a concrete water well.

Recorded By Debra Green Date Recorded 4/27/2011  
(First Name & Last Name) (mm/dd/year)

*Instructions to complete a digital version of this form:* (1) Download a copy to your hard drive; (2) Open the saved blank copy; (3) Fill out the form; (4) Use the Save As command to rename the form appropriately and save; (5) *Print* and submit to SHSND.

**NDCRS ARCHITECTURAL SITE FORM  
PAGE 5—SITE DESCRIPTION**Field Code MAC-H8-HS2SITS# 32 MN**6. Summary of All Site Features & Evaluation of Site Significance:**

The site is recommended as ineligible for the National Register of Historic Places (NRHP) under Criteria A, B, C, and D and no further work is necessary. The site consists of a standing school house structure, a standing outhouse, a concrete foundation of another outhouse, and a concrete well.

On April 7, 2011 Susan Quinnell, Review and Compliance Officer at the State Historical Society of North Dakota provided NDDOT and MAC with information that she had gathered pertaining to the site. She was able to verify a school at the location in the atlas of 1917 on land owned by Oscar Monson. More recent reports are unclear as to the name of the school with the strongest possibility being Crane Creek Township #145. Information from this school was found in the School Inspector's Annual reports from 1929. An abandoned well pad in the school yard is inscribed with the date 1948.

The site is ineligible under Criterion A in that it cannot at this time be associated with events that have made a significant contribution to the broad patterns of our history. Criterion B states that the site is eligible for the National Register of Historic Places (NRHP) if it can be associated with the lives of persons significant in our past. No records pertaining to who may have taught or attended school at this building could be identified; therefore, it is impossible to link the structure with a person who may have been historically significant so that the site is ineligible according to Criterion B. The structure itself is in poor condition with many key elements missing or destroyed. A majority of the exterior paint is gone and the windows are all missing and boarded over. The only truly intact feature of the school is the shingled roof. The site would not be eligible under Criterion C as it no longer embodies the distinctive characteristics of a type, period, or method of construction, or that represents the work of a master, or that possess high artistic values. The site also cannot be linked to any significant or distinguishable entity whose components have individual distinction, which is an additional component of Criterion C. Finally, there is no research program that deals with rural school buildings in deteriorated condition. The site would therefore not be eligible under Criterion D as is not likely to yield information important in prehistory or history.

The site fails to meet any of the criteria set for eligibility to the NRHP by the standards of the Secretary of the Interior's standards and guidelines. No further work is recommended for the site.

**7. References/Comments:**

National Register Bulletin #16. How to Apply the National Register Criteria for Evaluation. 1995. United States Department of the Interior. National Park Service.

Recorded By Debra Green  
(First Name & Last Name)Date Recorded 4/27/2011  
(mm/dd/year)

*Instructions to complete a digital version of this form: (1) Download a copy to your hard drive; (2) Open the saved blank copy; (3) Fill out the form; (4) Use the Save As command to rename the form appropriately and save; (5) Print and submit to SHSND.*

## NDCRS HISTORICAL ARCHEOLOGICAL SITE FORM PAGE 1

Field Code MAC-H8-HS2

SITS# 32 MN 869

**SITE IDENTIFICATION**

Map Quad Beldon SE Site Name \_\_\_\_\_  
 Map Quad \_\_\_\_\_ Site Name \_\_\_\_\_

LTL     TWP 153 R 91 SEC 35 QQQ 8 QQ 8 Q 8  
 LTL     TWP     R     SEC     QQQ     QQ     Q      
 LTL     TWP     R     SEC     QQQ     QQ     Q      
 LTL     TWP     R     SEC     QQQ     QQ     Q    

UTM 5323614 N ZONE 13N  
 UTM 697355 E NAD 1927  NAD 1983    

Subsection:  
 1 = N½  
 2 = E½  
 3 = S½  
 4 = W½  
 5 = NE¼  
 6 = SE¼  
 7 = SW¼  
 8 = NW¼

**SITE DATA**

<b>FEATURE TYPE</b>	<b>CULTURAL MATERIAL</b>	
<u>   </u> CM Scatter	<u>   </u> Bone	<u>9</u> Site Type
<u>   </u> Chimney	<u>   </u> Ceramics	<u>7</u> Context
<u>   </u> Depression	<u>   </u> Charcoal	<u>30</u> Site Area (m²)
<u>   </u> Dump	<u>   </u> Cloth	<u>1</u> Cultural Depth
<u>   </u> Earthworks	<u>   </u> Faunal Remains	<u>4</u> Depth Indicator
<u>   </u> Fortification	<u>   </u> Fire-Cracked Rock	<u>1</u> Basis for Dating
<u>1</u> Foundation	<u>   </u> Floral Remains	Occupation Date(s)
<u>   </u> Grave	<u>   </u> Glass	<u>   </u> Begin
<u>   </u> Hearth	<u>   </u> Hide, Hair, Fur	<u>   </u> End
<u>   </u> Machinery	<u>   </u> Human Remains	<u>5</u> CM Density
<u>   </u> Quarry/Mine	<u>1</u> Masonry	<u>   </u> Isolated Find
<u>   </u> Rock Art	<u>   </u> Metal	
<u>   </u> Trail	<u>   </u> Plastic	
<u>   </u> Wreck	<u>   </u> Rubber	
<u>   </u> Other	<u>   </u> Shell	
	<u>1</u> Wood	
	<u>   </u> Other	

**ENVIRONMENT**

Landform 1 1 Landform 2 9 Slope/Exposure 10 Ecosystem 7  
 Landform 1     Landform 2     Slope/Exposure     Ecosystem      
 Elevation 2.130 m Drainage System Missouri River  
 View Degree 4 View Distance 2  
 Distance to Permanent Water 8.000 m Permanent Water Type 1  
 Distance to Seasonal Water 1.800 m Seasonal Water Type 4

**CRM**

Ownership 3 Fieldwork Date 4/27/2011 Test/Probe     Excavation      
 Site Condition 3 Collection 1 Management Recommendation 1

Additional Information: Concrete privy foundation and cement water well pad/base

**SHSND USE**

Area of Significance 3 Ecozone 21 Verified Site 1 CR Type 1  
 Area of Significance 2 Ecozone 21 Non-Site      
 Area of Significance     Ecozone    

Recorded By Debra Green Date Recorded 4/27/2011  
 (First Name & Last Name) (mm/dd/year)

*Instructions to complete a digital version of this form: (1) Download a copy to your hard drive; (2) Open the saved blank copy; (3) Fill out the form; (4) Use the Save As command to rename the form appropriately and save; (5) Print and submit to SHSND.*



**NDCRS HISTORICAL ARCHEOLOGICAL SITE FORM**  
**PAGE 2—Descriptive Section**

Field Code MAC-H8-HS2SITS# 32 MN

## 1. Access:

From the town of Belden, travel south on Highway 8 for eight miles. The site is situated along the east side of Highway 8 at the corner of 43rd Street NW.

## 2. Site Description (include features):

The site consists of two standing structures: Feature 1, a school house/township hall, Feature 2, an outhouse; and two historic features: Feature 3, a concrete foundation of a second outhouse, and Feature 4 a concrete water well slab/base. Feature 3 is a square concrete foundation of a possible privy with an associated scatter of wood planks. The foundation is the same size as that of a standing privy (F2). Feature 4 is an approximately 1 meter square cement slab/base for a water well. A steel pipe extends into the ground at the center of the base. Of interest the date May 3 1948 was drawn into the wet cement. A 12 gauge shot shell base and a 32 caliber center-fire cartridge were also embedded into the concrete. The date may be associated with the school/town hall construction or may be the date that the well pad was installed.

3. Description of *Cultural Material* (quantify & identify artifacts, not features):

Approximately 25 pieces of lumber along with the odd piece of metal were noted.

25 # of Artifacts

0 # of Artifacts Collected

## 4. Artifact Repository:

Recorded By Debra Green Date Recorded 4/27/2011  
(First Name & Last Name) (mm/dd/year)

*Instructions to complete a digital version of this form: (1) Download a copy to your hard drive; (2) Open the saved blank copy; (3) Fill out the form; (4) Use the Save As command to rename the form appropriately and save; (5) Print and submit to SHSND.*

**NDCRS HISTORICAL ARCHEOLOGICAL SITE FORM**  
**PAGE 3—Descriptive Section**

Field Code MAC-H8-HS2

SITS# 32 MN

5. Description of Subsurface Testing:  
 N/A

6. Field Conditions:  
 Wet \_\_\_ Dry  Windy  Rainy \_\_\_  
 Snowy \_\_\_ Overcast \_\_\_ Sunny  Twilight \_\_\_

7. Technique(s) Used to Estimate Site Area:  
 Transit \_\_\_ Tape Measure \_\_\_ Paced  Visual Estimate \_\_\_  
 GPS  Other (Explain) \_\_\_\_\_

8. Rationale for Site Boundary Determination:  
 Surface Cultural Materials \_\_\_ Features  Topography \_\_\_  
 Continuous Stratigraphic Exposure \_\_\_ Systematic Subsurface Probing \_\_\_  
 Subsurface Testing \_\_\_ Other (Explain) \_\_\_\_\_

9. Current Use of Site: \_\_\_\_\_

10. Landowner Contact Information: \_\_\_\_\_

11. Vegetation: Tall grasses

12. Vegetation Cover (% of visible ground): 10

13. Snow Cover (% of ground obscured by snow/ice): 0

14. Person-Hours Spent at Site: 4

15. Project Title & Principal Investigator:  
 NDDOT-HWY 8 FW-2011 - Debra Green

Recorded By Debra Green Date Recorded 4/27/2011  
(First Name & Last Name) (mm/dd/year)

*Instructions to complete a digital version of this form: (1) Download a copy to your hard drive; (2) Open the saved blank copy; (3) Fill out the form; (4) Use the Save As command to rename the form appropriately and save; (5) Print and submit to SHSND.*

**NDCRS HISTORICAL ARCHEOLOGICAL SITE FORM**  
**PAGE 4—*Descriptive Section***

Field Code MAC-H8-HS2SITS# 32 MN

## 16. Report Title &amp; Author(s):

Highway 8: A Class III Cultural Resources Inventory in Mountrail County, North Dakota - Ed Stine

## 17. Description of Collection(s) Observed &amp; Contact Information:

## 18. Statement of Integrity:

Feature 3, the privy structure is destroyed. All that remains is the concrete foundation. Due to the lack of maintenance over time and long exposure to the elements, the feature has deteriorated and lacks original feeling, design, materials, workmanship, and association. The well, Feature 4, lacks the pump housing..

## 19. Statement of Significance:

The entire site is recommended as ineligible for the National Register of Historic Places (NRHP) under Criteria A, B, C, and D.

## 20. References Cited/Comments:

The site is proposed to be razed for increased Highway 8 ROW.

Recorded By Debra Green Date Recorded 4/27/2011  
(First Name & Last Name) (mm/dd/year)

*Instructions to complete a digital version of this form:* (1) Download a copy to your hard drive; (2) Open the saved blank copy; (3) Fill out the form; (4) Use the Save As command to rename the form appropriately and save; (5) *Print* and submit to SHSND.

## NDCRS SITE FORM ATTACHMENTS SECTION

Field Code    MAC-H8-HS2

SITS# 32MN

Complete one *Attachments Section* for the entire site. Include: Topographic map (with quad name and legal description), sketch map, photographs, and any other attachments.



Figure 2: View of MAC-H8-HS2; Feature 1 looking northwest (Photo #330).

Recorded By Debra Green  
(First Name & Last Name)

Date Recorded    4/27/2011  
(mm/dd/year)

*Instructions to complete a digital version of this form:* (1) Download a copy to your hard drive; (2) Open the saved blank copy; (3) Fill out the form; (4) Use the Save As command to rename the form appropriately and save; (5) *Print* and submit to SHSND.



## NDCRS SITE FORM ATTACHMENTS SECTION

Field Code    MAC-H8-HS2

SITS# 32MN

Complete one *Attachments Section* for the entire site. Include: Topographic map (with quad name and legal description), sketch map, photographs, and any other attachments.



**Figure 3: View of MAC-H8-HS2; Feature 2 looking east (Photo #348).**

**Recorded By** Debra Green  
(First Name & Last Name)

**Date Recorded** 4/27/2011  
(mm/dd/year)

*Instructions to complete a digital version of this form:* (1) Download a copy to your hard drive; (2) Open the saved blank copy; (3) Fill out the form; (4) Use the Save As command to rename the form appropriately and save; (5) *Print* and submit to SHSND.

## NDCRS SITE FORM ATTACHMENTS SECTION

Field Code    MAC-H8-HS2

SITS# 32MN

Complete one *Attachments Section* for the entire site. Include: Topographic map (with quad name and legal description), sketch map, photographs, and any other attachments.



**Figure 4: View of MAC-H8-HS2; Feature 3 looking east (Photo #327).**

**Recorded By** Debra Green  
(First Name & Last Name)

**Date Recorded** 4/27/2011  
(mm/dd/year)

*Instructions to complete a digital version of this form:* (1) Download a copy to your hard drive; (2) Open the saved blank copy; (3) Fill out the form; (4) Use the Save As command to rename the form appropriately and save; (5) *Print* and submit to SHSND.



## NDCRS SITE FORM ATTACHMENTS SECTION

Field Code    MAC-H8-HS2

SITS# 32MN

Complete one *Attachments Section* for the entire site. Include: Topographic map (with quad name and legal description), sketch map, photographs, and any other attachments.



Figure 5: View of MAC-H8-HS2; Feature 4 (Photo #351).

**Recorded By** Debra Green  
(First Name & Last Name)

**Date Recorded** 4/27/2011  
(mm/dd/year)

*Instructions to complete a digital version of this form:* (1) Download a copy to your hard drive; (2) Open the saved blank copy; (3) Fill out the form; (4) Use the Save As command to rename the form appropriately and save; (5) *Print* and submit to SHSND.