

**NDCRS ARCHITECTURAL SITE FORM
PAGE 1**

SITS# 32 MN 00879

SITE IDENTIFICATION

Field Code Rugland School Site Name Rugland School

Map Quad Palermo Site Name _____
Map Quad _____

LTL ___ TWP 155 R 90 SEC 11 QQQ 7 QQ 7 Q 8
LTL ___ TWP _____ R _____ SEC _____ QQQ _____ QQ _____ Q _____
LTL ___ TWP _____ R _____ SEC _____ QQQ _____ QQ _____ Q _____
LTL ___ TWP _____ R _____ SEC _____ QQQ _____ QQ _____ Q _____

UTM _____ N ZONE _____
UTM _____ E NAD 1927 ___ NAD 1983 ___

City: Palermo

Street Number: _____

Street Name: 74th Ave NW

Urban Legal Description: _____

Subsection:
1 = N $\frac{1}{2}$
2 = E $\frac{1}{2}$
3 = S $\frac{1}{2}$
4 = W $\frac{1}{2}$
5 = NE $\frac{1}{4}$
6 = SE $\frac{1}{4}$
7 = SW $\frac{1}{4}$
8 = NW $\frac{1}{4}$

SITE DATA

Total # *Architectural* Features: 1

Fieldwork Date: 7/10/2017

Reconnaissance Survey Intensive Survey

Project Title & Supervisor:
Country Schoolhouse Project

Report Title & Author(s):

Additional Information: _____

SHSND USE

Area of Significance 2 Ecozone 21 Verified Site _____ CR Type 2
Area of Significance _____ Ecozone _____ Non-Site _____
Area of Significance _____

Recorded By Kathy Wilner Date Recorded 7/12/2017
(First Name & Last Name) (mm/dd/year)

Instructions to complete a digital version of this form: (1) Download a copy to your hard drive; (2) Open the saved blank copy; (3) Fill out the form; (4) Use the Save As command to rename the form appropriately and save; (5) Print and submit to SHSND.

**NDCRS ARCHITECTURAL SITE FORM
PAGE 2—Feature Data**

Field Code Rugland SchoolSITS# 32 MN 00879**Complete one Page 2 for each architectural feature at the site.****Architectural Feature #** 1

Construction Date _____

Feature Type 9Condition 6Feature Date 3Context 7Plan Shape 5Structural System 25Primary Exterior 26Style Other Style

Original Owner's Ethnicity _____

Secondary Exterior _____

Architect/Builder _____

Other Information:

Foundation Concrete block Stories 1Roof/Cornice GableWindow Double hung, two over two, with some glassDating Method(s): Estimate**Feature Preservation Recommendation(s) (Check all that apply):** Individual nomination Contributes to a potential district No nomination potential Will not contribute to a district Potential district—feature would be a contributing element if other properties constitute a district Thematic nomination potential Component of a historic site or landscape

Moved (specify all applicable choices)—a) relocation occurred within a historic period; b) recreates original site, orientation, landscape, & spatial relationships; c) compatible in context with neighboring structures; d) relocation has damaged eligibility

 Historical associations require further investigation

Recorded By Kathy Wilner Date Recorded 7/12/2017
(First Name & Last Name) (mm/dd/year)

Instructions to complete a digital version of this form: (1) Download a copy to your hard drive; (2) Open the saved blank copy; (3) Fill out the form; (4) Use the Save As command to rename the form appropriately and save; (5) Print and submit to SHSND.

NDCRS ARCHITECTURAL SITE FORM
PAGE 3—Feature DataField Code Rugland SchoolSITS# 32 MN 00879**Complete a Page 3 for each feature.****1. Feature Description, Integrity, Eligibility:**

The feature is a one room prairie school on a foundation of concrete block. The school has wood shakes on the roof of the main body, metal capping with finials, and the entry is roofed with asphalt shingles. There is a red brick chimney at the east end of the roof peak. The soffits of the school are closed. The building measures 18 feet north to south and 24 feet east to west, I do not think that includes the entry.

The siding has a wide trim board under the peak of the roof at both ends of the school with the remainder of the siding 6 inch wood lap with 4 inch corner trim. The entry door, located on the south side, is a broken 5 panel wood door. There is a small window in the entry on the west wall, all glass is gone. There is a bank of 5 double hung, 2 over 2, windows facing south with about half of the glass missing. The interior walls and ceiling are wallboard. The floor is tongue and groove hardwood. There are blackboards in the school as well as wainscot. There is no electricity. Heating was a coal burning stove.

There are two outhouses to the east of the school building.

Recorded By Kathy Wilner Date Recorded 7/12/2017
(First Name & Last Name) (mm/dd/year)

Instructions to complete a digital version of this form: (1) Download a copy to your hard drive; (2) Open the saved blank copy; (3) Fill out the form; (4) Use the Save As command to rename the form appropriately and save; (5) Print and submit to SHSND.

**NDCRS ARCHITECTURAL SITE FORM
PAGE 4—SITE DESCRIPTION**Field Code Rugland SchoolSITS# 32 MN 00879**Complete one Page 4 for the entire site.**

2. Owner's Contact Information:

Greg Rugland
PO Box 53
Geysers MT 59447-0053

3. Access (to rural areas):

The school is located about 5 1/2 miles south of Palermo on 74th Ave NW. It is on the east side of the road.

4. Site Area (ft²): _____5. Description of **SETTING**:

There is a farm site to the north and all directions are pasture and farm fields.

Recorded By Kathy Wilner Date Recorded 7/12/2017
(First Name & Last Name) (mm/dd/year)

Instructions to complete a digital version of this form: (1) Download a copy to your hard drive; (2) Open the saved blank copy; (3) Fill out the form; (4) Use the Save As command to rename the form appropriately and save; (5) *Print* and submit to SHSND.

**NDCRS ARCHITECTURAL SITE FORM
PAGE 5—SITE DESCRIPTION**

Field Code Rugland School

SITS# 32 MN 00879

6. Summary of ALL Site Features & Evaluation of Significance:

7. References/Comments:

Kathy Wilner
366 43rd Ave SE
Bowdon ND 58418

Pictures and information submitted by Bonnie Eliason

Recorded By Kathy Wilner Date Recorded 7/12/2017
(First Name & Last Name) (mm/dd/year)

Instructions to complete a digital version of this form: (1) Download a copy to your hard drive; (2) Open the saved blank copy; (3) Fill out the form; (4) Use the Save As command to rename the form appropriately and save; (5) Print and submit to SHSND.



West Side

Rugland School

7/10/2017

Kathy Wilner

MN

North Side



Submitted by
Bonnie
Eliason



South Side

Rugland School

7/10/2017

Kathy Wilner

MN

East Side



Submitted by
Bonnie
Eliason

7/10/2017

Bing Maps - Directions, trip planning, traffic cameras & more

bing maps

Notes
Rugland School

7/10/2017

Kathy Wilner

MN

Feature

bing

© 2017 Microsoft Corporation © 2017 HERE

