State Historical Society of North Dakota



NDCRS ARCHITECTURAL SITE FORM PAGE 1 SITS# 32 MN

	PAGE 1	SITS# 32_	1N 1041
SITE IDENTIFICATION		0110# 52	
Field Code Farmvale School			
Map Quad <u><i>Ting a SE</i></u> Map Quad	Site Name <u>Moh</u>	m School	-
LTL TWP R SEC LTL TWP R SEC	7 QQQ 5 2 QQQ 2 2 QQQ 2 2 QQQ 2 2 QQQ 2	QQ QQ	Q <u>5</u> Q Q Q
UTMN UTME	ZONE _ NAD 19	NAD 1983	Subsection: $1 = N\frac{1}{2}$
City:			$2 = E\frac{1}{2}$ $3 = S\frac{1}{2}$
Street Number:			$4 = W\frac{1}{2}$ 5 = NE ¹ / ₄
Street Name: 101st Ave NW			6 = SE¼ 7 = SW¼
Urban Legal Description:			8 = NW ¹ ⁄ ₄
SITE DATA			
Total # <i>Architectural</i> Features:1			
Fieldwork Date: 6/15/2017			
Reconnaissance Survey Inte	nsive Survey		
Project Title & Supervisor: Country Schoolhouse Project			
Report Title & Author(s):			
Additional Information:			
SHSND USE Area of Significance Area of Significance Area of Significance	Verified Site Non-Site		2
Recorded By Kathy Will	ner	Date Recorded	6/29/2017
(First Name & Last Name)			(mm/dd/year)

NDCRS 2009

State Historical Society of North Dakota

NDCRS	ARCHITECTURAL SITE FOI	RM
	PAGE 2—Feature Data	

FAGE 2—Feature Data					
Field Code Farmvale School		SITS# 32_ <u>MN</u>			
Complete one Page 2 for each architectural feature at the site.					
Architectural Feature #1					
Construction Date	Feature Type <u>9</u>	Condition <u>6</u>			
Feature Date 3	Context 7	Plan Shape <u>5</u>			
Structural System 25	Primary Exterior <u>26</u>	StyleOther Style			
Original Owner's Ethnicity	Secondary Exterior	Architect/Builder			
Other Information:					
Foundation Poured concrete		Stories1			
Roof/Cornice_Gable					
Window Double hung, some glass					
Dating Method(s): Estimate					
Feature Preservation Recommendation(s) (Check all that apply):					
Individual nomination					
Contributes to a potential dist	rict				
No nomination potential					
Will not contribute to a distric	t				
Potential district—feature wo	uld be a contributing element if	other properties constitute a district			
Thematic nomination potentia	al				
Component of a historic site of	or landscape				
recreates original site, orienta	choices)—a) relocation occurre tion, landscape, & spatial relati l) relocation has damaged eligit	onships; c) compatible in context			
Historical associations require	e further investigation				

Recorded By	Kathy Wilner	Date Recorded	6/29/2017	
(First Name & Last Name)			(mm/dd/year)	

State Historical Society of North Dakota

NDCRS 2009

NDCRS ARCHITECTURAL SITE FORM PAGE 4—SITE DESCRIPTION

Field Code Farmvale School

SITS# 32_<u>MN</u>_____

Complete one Page 4 for the entire site.

2. Owner's Contact Information: Taxpayer: Corinne Redmond 7609 Hwy 40 Tioga ND 58852

3. Access (to rural areas):

This school is located on 101st Ave NW about 5 miles south of Highway 2. It is on the east side of the road.

4. Site Area (ft²):_____

5. Description of SETTING:

The school is in an area of rolling hills with trees and farm fields all directions. There is a farm site to the north.

Recorded By Kathy Wilner Date Recorded 6/29/2017 (First Name & Last Name) (mm/dd/year)

NDCRS 2009

NDCRS ARCHITECTURAL SITE FORM PAGE 3—Feature Data

Field Code Farmvale School

SITS# 32 MN

Complete a Page 3 for each feature.

1. Feature Description, Integrity, Eligibility:

The feature is a one room prairie school on a foundation of poured concrete. The gable roof of the school is covered with metal sheeting. There is a red brick chimney located at the north end of the peak of the roof. The soffits are closed. The school measures 24 feet north to south and 18 feet east to west with the entry measuring 14 feet east to west and 10 feet north to south.

The siding begins with a wide trim board under the peak end of the roof. The remainder of the siding is 6 inch wood lap with 4 inch corner trim. The paint appears to be very recent. Two concrete steps lead to a concrete platform that gives entry to the school. There is a 5 panel wood door with a covered opening at the top that was likely a transom window. There is one small fixed pane window on the east wall of the entry. The entry walls are finished with wood lap inside. Another wood door with decorative windows across the top gives entry to the school The walls inside the school room are finished with wallboard. The east wall has 5 double hung, one over one, windows with much of the glass remaining and all are covered with translucent plastic on the outside. The window trim is wide boards with a decorative finishing piece at the top of each window. The ceiling of the school room is beadboard covered with ceiling tiles. The ceiling is slanted to the walls on both the east and west sides. The floor is tongue and groove hardwood. There are blackboards on part of the west wall and also the south wall to the entry door. Electricity is present with wires and fixtures apparent.

Early 1940's the school was also called the Momb School.

Recorded By____

(First Name & Last Name)

Date Recorded

6/29/2017 (mm/dd/year)

State Historical Society of North Dakota

NDCRS 2009

NDCRS ARCHITECTURAL SITE FORM PAGE 5—SITE DESCRIPTION

Field Code Farmvale School

SITS# 32 MN

6. Summary of ALL Site Features & Evaluation of Significance:

7. References/Comments: Kathy Wilner 366 43rd Ave SE Bowdon ND 58418

Recorded By (First Name & Last Name) Kathy Wilner


____ Date Recorded

6/29/2017 (mm/dd/year)



Farmvale School

6/15/2017



мη



North Side



South Side

Farmvale School

6/15/2017

Kathy Wilner



West Side

