Area of Significance

Area of Significance _

(mm/dd/year)

NDCRS ARCHITECTURAL SITE FORM PAGE 1

SITS# 32 MN SITE IDENTIFICATION Field Code Bicker Township School Site Name _____ Site Name Map Quad White Map Quad LTL __ TWP __158 R___94___ SEC 29 QQQ 5 LTL___ TWP_____ R____ SEC _____ QQQ ____ LTL ___ TWP ___ SEC _____ QQQ ____ SEC _ QQQ_ LTL ___ TWP __ UTM ______N UTM _____E ZONE __ Subsection: NAD 1927 ___ NAD 1983 __ $1 = N\frac{1}{2}$ $2 = E\frac{1}{2}$ City:____ $3 = 5\frac{1}{2}$ $4 = W\frac{1}{2}$ Street Number: 5 = NE1/4 6 = SE1/4 Street Name: 74th St NW 7 = SW1/4 8 = NW1/4 Urban Legal Description: SITE DATA Total # Architectural Features: 1 Fieldwork Date: 8/22/2016 Reconnaissance Survey Intensive Survey ____ Project Title & Supervisor: Country Schoolhouse Project Report Title & Author(s): Additional Information: SHSND USE Area of Significance Ecozone __ Verified Site _

Instructions to complete a digital version of this form: (1) Download a copy to your hard drive; (2) Open the saved blank copy; (3) Fill out the form; (4) Use the Save As command to rename the form appropriately and save; (5) Print and submit to SHSND.

Non-Site _

Kathy Wilner ____ Date Recorded ___

Ecozone _____

NDCRS ARCHITECTURAL SITE FORM PAGE 2—Feature Data

Field Code Bicker Township School		SITS# 32	MN	
Complete one Page 2 for each architectural feature at the site.				
Architectural Featur	e#1			
Construction Date	Feature Type	9 Condition 6	3	
Feature Date 3	Context 7	Plan Shape	2	
Structural System 25	Primary Exteri	or 26 Style Other	Style	
Original Owner's Ethnic	ty Secondary Ex	terior Architect/Bu	uilder	
Other Information:				
Foundation Poured Con	crete	Stories1	ni radinara	
Roof/Cornice_Intersecting	g gable with half hip addition			
	lock, Double hung, small fixed			
Dating Method(s):	stimate			
Feature Preservation Recommendation(s) (Check all that apply): Individual nomination Contributes to a potential district No nomination potential Will not contribute to a district Potential district—feature would be a contributing element if other properties constitute a district Thematic nomination potential Component of a historic site or landscape Moved (specify all applicable choices)—a) relocation occurred within a historic period; b) recreates original site, orientation, landscape, & spatial relationships; c) compatible in context with neighboring structures; d) relocation has damaged eligibility Historical associations require further investigation				
indicated addoc	and to quite turner investiga			
Recorded By(First Nai	Kathy Wilner	Date Recorded_	2/1/2017 (mm/dd/year)	

Instructions to complete a digital version of this form: (1) Download a copy to your hard drive; (2) Open the saved blank copy; (3) Fill out the form; (4) Use the Save As command to rename the form appropriately and save; (5) Print and submit to SHSND.

MN

NDCRS ARCHITECTURAL SITE FORM PAGE 3—Feature Data

Field	Code Bicker Township School	SITS# 32

Complete a Page 3 for each feature.

1. Feature Description, Integrity, Eligibility:

The feature is a one room prairie school on a poured concrete basement. The gable roof of the main body, the intersecting entry, the pyramidal roof of the bell tower and the half hip of the east addition are covered with asphalt shingles. There is a red brick chimney at the east end of the peak. A bell tower sits on the peak of the entry, the base of the tower is wood with four wood posts holding the roof. The underside of the pyramidal roof is finished with beadboard. There is a bell in the tower and a flagpole at the peak of the tower top. The soffits are closed. The main body of the building measures 20 feet east to west and 28 feet north to south with the north addition measuring 12 feet east to west by 6 feet north to south. The west entry measures 8 feet by 20 feet.

There is a wide trim board on the exterior wall just under the soffits on the peak ends of the school as well as the half hip roof of the addition. The siding is 6 inch wood lap with 4 inch wood corner trim. There is waterboard near the bottom with another wide trim board to finish the siding. There are two covered window openings on the east wall of the bathroom addition. A small window is on the east wall of the entry at the point where the stairs go to the basement. A glass block window is most likely a replacement on the north wall of the entry and a diamond shaped opening above this window has no glass. There is a salt box porch roof extending from the entry to cover the open porch, one supporting pillar at the northwest corner. Entry to the school is up wooden steps from the north or a ramp along the school wall with wood railings. There are several 5 panel wood doors, one in the entry, one at the stairway in the entry, another into the school proper and two more on the east room leading to the bathrooms. The bathrooms are located off the east wall of the school. The south side has two vented glass block windows either side of another large block window, likely replacements. The interior walls are wallboard panels with wainscot in the school room and the entry/coatroom. The ceiling is wallboard tiles some of which are falling in. There are black and green boards on the entire west wall as well as much of the north wall. There is a curtain on a wire hanging toward the west end, likely for school plays. Guessing the furnace is in the basement. The floor is tongue and groove hardwood. Light fixtures and switches suggest electricity. There are benches, a table, a desk, books and papers strewn all over the school room with bird droppings as part of the mix.

Recorded By(First	Kathy Wilner	Date Recorded	2/1/2017
	(First Name & Last Name)	The control of the second of t	(mm/dd/year)

NDCRS ARCHITECTURAL SITE FORM PAGE 4—SITE DESCRIPTION

Field Code Bicker Township School	SITS#	32 MN
Complete one Page 4 for the enti	<u>re site</u> .	
2. Owner's Contact Information: Ricky and Brenda Kutter 77679 106th Ave NW McGregor ND 58755		
3. Access (to rural areas):		
From Tioga on Highway 40 north about 6 school on the right.	miles to 74th At NW and go east about	3 1/2 miles to see the
4. Site Area (ft²):		
5. Description of SETTING :		
There is a farm directly west, shelter belts directions.	northwest, church and cemetery east a	nd farm fields all
Recorded By Kathy W	ilner Date Recorde	d 2/1/2017
(First Name & Last Name)		(mm/dd/year)

Instructions to complete a digital version of this form: (1) Download a copy to your hard drive; (2) Open the saved blank copy; (3) Fill out the form; (4) Use the Save As command to rename the form appropriately and save; (5) Print and submit to SHSND.

NDCRS ARCHITECTURAL SITE FORM PAGE 5—SITE DESCRIPTION

Field Code Bicker Townshi	p School	SITS# 32_	MN	
6. Summary of ALL Site Features & Evaluation of Significance:				
7. References/Comments:				
Kathy Wilner 366 43rd Ave SE				
Bowdon ND 58418				
Recorded By(First Name & L	Kathy Wilner	Date Recorded	2/1/2017	

Instructions to complete a digital version of this form: (1) Download a copy to your hard drive; (2) Open the saved blank copy; (3) Fill out the form; (4) Use the Save As command to rename the form appropriately and save; (5) *Print* and submit to SHSND.



North Side

Bicker Township School

8/24/2016

Kathy Wilner

MN

West Side





South Side

Bicker Township School

8/22/2016

Kathy Wilner

MN

East Side



bing maps

Notes

Bicker Township School

8/21/2016

Kathy Wilner

MN



Feature

