NDCRS ARCHITECTURAL SITE FORM

| Field Code DIVISION School | AGE I | SITS# 32 MN | 1540 |
|--|----------------|-----------------------|-----------------------|
| | Site Name Divi | | |
| LTLTWP R SEC LTLTWP R SEC LTLTWP R SEC LTLTWP R SEC | QQQ _ | QQ | Q 6 Q Q Q |
| NAD 1983, UTM 5316022 N NAD 1983, UTM 265760 E | ZONE 14N | | Subsection: 1 = N½ |
| City: Parshall | | | 2 = E½ 3 = S½ |
| Street Number: 211 | | | 4 = W½ 5 = NE¼ |
| Street Name: 1st Ave NW | | | 6 = SE¼ 7 = SW¼ |
| Urban Legal Description: | | | 8 = NW1/4 |
| SITE DATA | | | |
| Total # Architectural Features: 1 | | | |
| Fieldwork Date: | | | |
| Reconnaissance Survey Intensive | e Survey | | |
| Project & Principal Investigator: | | | |
| Report Title & Author(s): | | | |
| Contracting firm or Agency completing the form: | | | |
| Additional Information: | | | |
| SHSND USE Area of Significance Ecozone | Verified | Site _L CR | Гуре <u>2</u> |
| Recorded By Kathy Wilner | | Date Recorded 7/5 | 5/2019 |
| (First Name & Last Name) | | Photo-roots Towns Co. | (mm/dd/year) |

NDCRS ARCHITECTURAL SITE FORM PAGE 2—Feature Data

| Field Code Division School | SITS# 32 ^{MN} | | | | |
|---|------------------------|--|--|--|--|
| Complete one Page 2 for each architectural feature at the site. | | | | | |
| Architectural Feature # | | | | | |
| Construction Date Feature Type | 9 Condition 5 | | | | |
| Feature Date 4 Context 7 | Plan Shape 5 | | | | |
| Structural System 25 Primary Exter | | | | | |
| Original Owner's Ethnicity ——— Secondary Ex | M/A | | | | |
| Original Owner 3 Editions | Achitect/Duilder | | | | |
| Other Information: | | | | | |
| Foundation Poured concrete | Stories 1 | | | | |
| Roof/Cornice Gable | | | | | |
| Window Covered | | | | | |
| Dating Method(s): Estimate | | | | | |
| | | | | | |
| Feature Preservation Recommendation(s) (Check all that apply): | | | | | |
| Individual nomination | | | | | |
| Contributes to a potential district | | | | | |
| No nomination potential | | | | | |
| Will not contribute to a district | | | | | |
| Potential district—feature would be a contributing element if other properties constitute a district | | | | | |
| Thematic nomination potential | | | | | |
| Component of a historic site or landscape | | | | | |
| Moved (specify all applicable choices)—a) relocation occurred within a historic period; b) | | | | | |
| recreates original site, orientation, landscape, & spatial relationships; c) compatible in context with neighboring structures; d) relocation has damaged eligibility | | | | | |
| Historical associations require further investigation | | | | | |
| | | | | | |
| Recorded By Kathy Wilner | Date Recorded 7/5/2019 | | | | |
| (First Name & Last Name) | (mm/dd/year) | | | | |

NDCRS ARCHITECTURAL SITE FORM PAGE 3—Feature Data

Complete a Page 3 for each feature.

1. Feature Description, Integrity, Eligibility:

The feature is a one room prairie school moved to the present location for use as a storage building. It was placed on a poured concrete slab. The roof is covered with metal sheeting. There is no chimney. There are decorative triangular brackets under the open soffits on the peak ends. The building measures 32 north to south and 24 east and west with an entry that measures 6 feet by 8 1/2 feet.

The siding of this building is a mixture. On the peak ends of the school, about the top 1/4 of the siding, is wood shakes. The next 1/3 of the peaked end walls is covered with 6 inch wood lap with 4 inch wood corner trim. The two long walls are 6 inch wood lap with 4 inch corner trim and the bottom 1/3 of all sides of the school have metal sheeting. A small entry at the south end of the building has similar siding to the larger peaked ends and the wood siding shows where the door opening was filled in. On the east side there is a metal sliding door to give entry to the school. The east wall originally had three sets of two windows, the middle windows were removed for the door installation. The two outer sets of windows are totally covered.

We did not go inside the school.

| Recorded B | Kathy Wilner | Date Recorded 7/5/2019 |
|------------|--------------------------|------------------------|
| | (First Name & Last Name) | (mm/dd/year) |

NDCRS ARCHITECTURAL SITE FORM PAGE 4—SITE DESCRIPTION

| Field Code Division School | SITS# 32 MN |
|--|---|
| Complete one Page 4 for the entire site. | |
| 2. Owner's Contact Information: Parshall Public School 501 North Main Street Parshall ND 58770 | |
| 3. Access (to rural areas): | |
| This school is located behind the Parshall element in Parshall. | ery School which is located at 211 1st Ave NW right |
| 4. Site Area (ft²): | |
| Description of SETTING: The school is in town, there is a school to the north buildings to the south. | n, house to the east, more houses west and other |
| | |
| | |
| | |
| | |
| | |
| | |
| | |
| | |
| | |
| Recorded By Kathy Wilner (First Name & Last Name) | Date Recorded 7/5/2019 |
| (First Name & Last Name) | (mm/dd/year) |

NDCRS ARCHITECTURAL SITE FORM PAGE 5—SITE DESCRIPTION

| Field Code Division School | SITS# 32 MN | | | |
|---|------------------------|--|--|--|
| 6. Summary of ALL Site Features & Evaluation of Significance: | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| 7. References/Comments: Kathy Wilner 366 43rd Ave SE | | | | |
| Bowdon ND 58418 | | | | |
| Recorded By Kathy Wilner | Date Recorded 7/5/2019 | | | |
| (First Name & Last Name) | (mm/dd/year) | | | |




East Side

Division School 6/26/2019 Kathy Wilner

MN

North Side





South Side


Division School

6/26/2019

Kathy Wilner

MN

West Side







magery ©2019 Google, Map data ©2019 200 ft

Feature