

### NDCRS ARCHITECTURAL SITE FORM

PAGE 1

Field Code Banner School #2

SITS# 32 MN 1541

**SITE IDENTIFICATION**

Map Quad Parshall NE Site Name Banner School #2

Map Quad \_\_\_\_\_ Site Name \_\_\_\_\_

LTL \_\_\_ TWP 151 R 89 SEC 5 QQQ 7 QQ 7 Q 7

LTL \_\_\_ TWP \_\_\_\_\_ R \_\_\_\_\_ SEC \_\_\_\_\_ QQQ \_\_\_\_\_ QQ \_\_\_\_\_ Q \_\_\_\_\_

LTL \_\_\_ TWP \_\_\_\_\_ R \_\_\_\_\_ SEC \_\_\_\_\_ QQQ \_\_\_\_\_ QQ \_\_\_\_\_ Q \_\_\_\_\_

LTL \_\_\_ TWP \_\_\_\_\_ R \_\_\_\_\_ SEC \_\_\_\_\_ QQQ \_\_\_\_\_ QQ \_\_\_\_\_ Q \_\_\_\_\_

NAD 1983, UTM 5312176 N  
NAD 1983, UTM 268032 E

ZONE 14N

Subsection:
1 = N½
2 = E½
3 = S½
4 = W½
5 = NE¼
6 = SE¼
7 = SW¼
8 = NW¼

City: Parshall

Street Number: \_\_\_\_\_

Street Name: 35th St NW

Urban Legal Description: \_\_\_\_\_

**SITE DATA**

Total # **Architectural** Features: 1

Fieldwork Date: \_\_\_\_\_

Reconnaissance Survey  Intensive Survey \_\_\_\_\_

Project & Principal Investigator: \_\_\_\_\_

Report Title & Author(s): \_\_\_\_\_

Contracting firm or Agency completing the form: \_\_\_\_\_

Additional Information: \_\_\_\_\_

**SHSND USE**

Area of Significance 2 Ecozone 21 Verified Site 1 CR Type 2

Area of Significance \_\_\_\_\_ Ecozone \_\_\_\_\_

Area of Significance \_\_\_\_\_ Ecozone \_\_\_\_\_

Recorded By Kathy Wilner

Date Recorded 7/5/2019

(First Name & Last Name)

(mm/dd/year)

Instructions to complete a digital version of this form: (1) Download a copy; (2) Open the saved blank copy; (3) Fill out the form; (4) Use the Save As command to rename the form appropriately, and save; (5) **Print** and submit to SHSND.

NDCRS ARCHITECTURAL SITE FORM
PAGE 2—Feature Data

Field Code Banner School #2

SITS# 32 MN

Complete one Page 2 for each architectural feature at the site.

Architectural Feature # 1

Construction Date

Feature Type 9

Condition 5

Feature Date 4

Context 7

Plan Shape 5

Structural System 25

Primary Exterior 26

Style Other Style

Original Owner's Ethnicity

Secondary Exterior N/A

Architect/Builder

Other Information:

Foundation Poured concrete slab

Stories 1

Roof/Cornice Crossed Gable

Window Double hung, some glass

Dating Method(s): History

Feature Preservation Recommendation(s) (Check all that apply):

- Individual nomination
Contributes to a potential district
No nomination potential
Will not contribute to a district
Potential district—feature would be a contributing element if other properties constitute a district
Thematic nomination potential
Component of a historic site or landscape
Moved (specify all applicable choices)—a) relocation occurred within a historic period; b) recreates original site, orientation, landscape, & spatial relationships; c) compatible in context with neighboring structures; d) relocation has damaged eligibility
Historical associations require further investigation

Recorded By Kathy Wilner
(First Name & Last Name)

Date Recorded 7/5/2019
(mm/dd/year)

**NDCRS ARCHITECTURAL SITE FORM****PAGE 3—Feature Data**Field Code SITS# 32 **Complete a Page 3 for each feature.****1. Feature Description, Integrity, Eligibility:**

The feature is a one room prairie school moved to this location from Section 9 of Banner Township.

The building was placed on a concrete slab. The roof is covered with asphalt shingles and there is not a chimney. The main part of the building measures 21 feet north to south and 32 feet east to west.

There is a shed/bathroom addition at the back, west side, of the school that measures 21 feet by 6 feet. At some point yet another small shed was attached to the west most addition. The roof on this addition is beginning to fall in and the shingles are in really bad shape. This small addition measures 8 feet by 6 feet and may have been used for storage. The entry measures 10 feet by 14 feet. Gable roofs cover the school and entry and a half hip roof is found on the shed/bathroom. The soffits are open with triangular shaped brackets lending support.

A rake board runs under the peak ends of the school and entry. The siding is 6 inch wood lap with 4 inch wood corner trim leading down to the waterboard and wide trim board at the bottom. There is an entry leading into the school with a 5 panel wood door. On the south side of the entry there is one one double hung window with glass. The floor in the entry is tongue and groove hard wood. At the west wall of the entry is a tall wood railing with a door opening to the left/south that used to lead to a basement in the school's past location. Walls in the entry and school are lathe and plaster with much of it falling away. A wide trim board runs around the rooms at the base of the wall. The east wall of the school has a double garage door to give access for a shop. Tongue and groove hard wood covers the floor in the main room of the school. There are three sets of multiply pane double hung windows on the north wall, some with some glass and most covered from the outside. Inside the school room two five panel wood doors can be seen at the west end, leading into the shed/bathroom addition. The south and east walls of the school room shows where the blackboard used to be, the chalk rail is still there. The ceiling is also lathe and plaster with much of the plaster fallen away. There is no wainscot in this school. The shed/bathroom on the west side has two 5 panel wood doors leading in to the little shed/lean-to. There are two small fixed pane windows to either side of that lean-to, both covered. The lean-to has a small opening on both the north and south sides, just under the eaves. There was no electricity, the hangers for lanterns are still hanging from the ceiling.

This school was built sometime between 1916 and 1921.

Recorded By 

(First Name &amp; Last Name)

Date Recorded 

(mm/dd/year)

**NDCRS ARCHITECTURAL SITE FORM  
PAGE 4—SITE DESCRIPTION**Field Code SITS# 32 **Complete one Page 4 for the entire site.**

## 2. Owner's Contact Information:

Craig Elton  
19 2nd St NE  
Parshall ND 58770

## 3. Access (to rural areas):

From Parshall drive 2 miles south of Parshall on 1804 to 35th Ave NW. Turn left and drive east about 1/2 mile to see the farm site on your left. The school is behind the bins, at the west edge of the farm yard.

4. Site Area (ft<sup>2</sup>): \_\_\_\_\_5. Description of **SETTING**:

The school sits in a farm yard. There are trees directly west, a large shed, a second school and more trees north, bins directly east and another shed to the south. There are farm fields all directions from the farm.

Recorded By   
(First Name & Last Name)Date Recorded   
(mm/dd/year)

*Instructions to complete a digital version of this form:* (1) Download a copy; (2) Open the saved blank copy; (3) Fill out the form; (4) Use the Save As command to rename the form appropriately, and save; (5) **Print** and submit to SHSND.

**NDCRS ARCHITECTURAL SITE FORM  
PAGE 5—SITE DESCRIPTION**

Field Code

SITS# 32

**6. Summary of ALL Site Features & Evaluation of Significance:**

7. References/Comments:

Kathy Wilner  
366 43rd Ave SE  
Bowdon ND 58418

Recorded By

(First Name & Last Name)

Date Recorded

(mm/dd/year)

*Instructions to complete a digital version of this form:* (1) Download a copy; (2) Open the saved blank copy; (3) Fill out the form; (4) Use the Save As command to rename the form appropriately, and save; (5) **Print** and submit to SHSND.



South Side

Banner School #2


6/26/2019

Kathy Wilner

MN

West Side





East Side

Banner School #2

6/26/2019

Kathy Wilner

MN

North Side



*Feature*



Imagery ©2019 Google, Map data ©2019 500 ft 