### NDCRS ARCHITECTURAL SITE FORM

Cottonus ad Caland	'AGE 1		
Field Code Cottonwood School		SITS# 32 MN	1554
SITE IDENTIFICATION	lo-11		
Map Quad Stan Cy Map Quad	Site Name Hau	onwood School	
		gilo cortoor	
LTLTWP156 R91 SEC	28 QQQ 6	QQ 7	Q 5
LTLTWP R SEC			
LTL _TWP R SEC _			
LTLTWP R SEC	QQQ _	QQ	_ Q
NAD 1983, UTM 5353725 N	ZONE 13N		Subsection:
NAD 1983, UTM 694165 E			1 = N½
City: Stanley			2 = E½
Oity.			$3 = 5\frac{1}{2}$ $4 = \frac{1}{2}$
Street Number: 405			5 = NE1/4
Street Name: 12th Ave SE			6 = SE1/4
Street Name: 12th Ave SE			7 = SW1/4
Urban Legal Description:			8 = NW1/4
•			
SITE DATA			
Total # Architectural Features: 1			
Fieldwork Date: 7/22/2019			
Reconnaissance Survey Intensiv	e Survey		
Project & Principal Investigator: Country Schoolhouse Project			
, (J.			
Report Title & Author(s):			
Contracting firm or Agency completing the form:			
Additional Information:			
SHSND USE			
Area of Significance 2	Verified	Site C	R Type <u>Z</u>
Area of Significance Ecozone Area of Significance Ecozone			
100000000000000000000000000000000000000			T-100/0040
Recorded By Kathy Wilner		Date Recorded	7/22/2019
(First Name & Last Name)			(mm/dd/year)

### NDCRS ARCHITECTURAL SITE FORM PAGE 2—Feature Data

Field Code Cottonwood School	SITS# 32 <sup>MN</sup>			
Complete one Page 2 for each architectural feature at the site.				
Architectural Feature #				
Construction Date Feature Type 9	Condition 7			
Feature Date 3 Context 7	Plan Shape 5			
Structural System 25 Primary Exterior 26	Style Other Style			
Original Owner's Ethnicity ——— Secondary Exterior N/A	Architect/Builder			
Other Information:  Concrete block	1			
Foundation	Stories			
Roof/Cornice Gable				
Window Double hung, glass intact				
Dating Method(s):				
Feature Preservation Recommendation(s) (Check all that a	pply):			
Individual nomination				
Contributes to a potential district				
No nomination potential				
Will not contribute to a district				
Potential district—feature would be a contributing element if other properties constitute a district				
Thematic nomination potential				
Component of a historic site or landscape				
Moved (specify all applicable choices)—a) relocation occurred within a historic period; b) recreates original site, orientation, landscape, & spatial relationships; c) compatible in contextwith neighboring structures; d) relocation has damaged eligibility				
Historical associations require further investigation				
Recorded By Kathy Wilner Date	e Recorded 7/22/2019			
(First Name & Last Name)	(mm/dd/year)			

### NDCRS ARCHITECTURAL SITE FORM PAGE 3—Feature Data

Field Code Cottonwood School SI	SITS# 32 MN
---------------------------------	-------------

#### Complete a Page 3 for each feature.

#### 1. Feature Description, Integrity, Eligibility:

The feature, also known as Hauglie School, is a one room prairie school sitting on concrete block foundation. It was moved to this area to be part of a pioneer village. The gable roof of the building is covered with asphalt shingles. The original wood shakes were replaced in the 1990's. There is a bell tower at the peak of the roof at the southwest end of the school. The bell tower is roofed with asphalt shingles and there is a flag pole at the peak and a bell in the tower. Another large school bell sits on the ground at the entry corner of the school. The soffits are closed. The building measures 36 feet long by 16 1/2 feet wide.

A rake board begins the siding under the roof at the peak ends of the school. Remainder of the siding is 6 inch wood lap with 6 inch wood corner trim. A new steel door, installed in 2019 to replace the old wood door, leads into the entry. A bank of 6 double hung vinyl windows are on the northwest wall. These windows replaced wood ones in 2018. All glass is intact and the windows have pull down shades with a curtain on the lower half. There is a double hung window in the entry and one more small, fixed pane window on the southeast side, also in the entry. Another door leads into the school proper. Blackboards fill the northeast and southeast walls inside the school. The walls are 4 inch wide wood boards running horizontally and this contines up the walls to ancurved finish, about a foot wide, to the beadboard ceiling. The floor is tongue and groove hardwood. There is no wainscote. There is electricity present. Heat was a coal stove. The school interior is much like it would have been when school was in session, complete with books, student desks, the teachers desk and much more.

Recorded By Kath	Kathy Wilner	Date Recorded 7/22/2019	
	(First Name & Last Name)	(mm/dd/year)	

# NDCRS ARCHITECTURAL SITE FORM PAGE 4—SITE DESCRIPTION

Field Code Cottonwood School		SITS#3	2 <sup>MN</sup>
Complete one Page 4 for the entire s	ite.		
2. Owner's Contact Information: Flickertail Village Museum 405 12th Ave SE Stanley ND 58784			
Access (to rural areas):     Flickertail Village Museum is located in the t     Highway 2.	own of Stanley. I	t is on the east side	e of town, north of
4. Site Area (ft²):			
<ol> <li>Description of SETTING:         This school is located in a pioneer village wigrassed area with well cared for buildings.     </li> </ol>	ith many buildings	s to the west, south	and southwest. It is a
			4
Vothy Wiles		] 1	7/22/2019
Recorded By (First Name & Last Name)		Date Recorded	(mm/dd/year)

# NDCRS ARCHITECTURAL SITE FORM PAGE 5—SITE DESCRIPTION

Field Code Cottonwood School		SITS# 32 <sup>™</sup>	IN
6. Summary of ALL Site Features & E	Evaluation of S	Significance:	
7. References/Comments: Kathy Wilner			
366 43rd Ave SE Bowdon ND 58418			
Information and pictures for this school was Museum.	submitted by Ger	ry Nelson with the Flic	kertail Village
Recorded By Kathy Wilner		Date Recorded 7/2	2/2019
(First Name & Last Name)		_4W 110001404	(mm/dd/year)



North-West Side


Cottonwood School

7/22/2019

Kathy Wilner

MN

North-East side





Southeast Side


**Cottonwood School** 


7/22/2019

Kathy Wilner

MN

Southwest Side





Imagery @2019 Google, Map data @2019 50 ft