

NDCRS ARCHITECTURAL FORM

PAGE 1

Field Code Oakland Township School

SITS# 32 MN 1601

Map Quad Epworth NW

Site Name Oakland Township School

Map Quad \_\_\_\_\_

Site Name \_\_\_\_\_

LTL    T. 154 N., R. 89 W., Sec. 20 QQQ 7 of the QQ 7 of the Q 7

LTL    T.    N., R.    W., Sec.    QQQ    of the QQ    of the Q   

LTL    T.    N., R.    W., Sec.    QQQ    of the QQ    of the Q   

LTL    T.    N., R.    W., Sec.    QQQ    of the QQ    of the Q   

NAD 1983 UTM 5335717 Zone 13N

NAD 1983 UTM 711442

City: \_\_\_\_\_

Subsection
1 = N½
2 = E½
3 = S½
4 = W½
5 = NE¼
6 = SE¼
7 = SW¼
8 = NW¼

Street Number: \_\_\_\_\_

Street Name: 50th St NW

Urban Legal Description: \_\_\_\_\_

Total Number of Architectural Features: 1

Fieldwork Date: 8/8/2020

Reconnaissance Survey

Intensive Survey

Project & Principal Investigator:

Kathy Wilner  
366 43rd Ave SE  
Bowdon ND 58418

Contracting Firm or Agency Completing the Form:

Additional Information:

**SHSND USE**  
 Component 2 Study Unit 21 Verified Site \_\_\_\_\_ CR Type 2  
 Component \_\_\_\_\_  
 Component \_\_\_\_\_

Recorded By: Kathy Wilner and Hunter Andes Date Recorded: 8/25/2020

Form instructions: (1) Download; (2) Save A Copy; (3) Submit a paper copy of the form to the SHSND and upload the PDF version of the form and corresponding GIS shapefiles to the ND SHPO-run FTP site.

**NDCRS ARCHITECTURAL FORM**  
**PAGE 2 – Feature Data**

Field Code Oakland Township SchoolSITS# 32 MN

Complete one Page 2 for each architectural feature at the site.

Architectural Feature # 1

Construction Date \_\_\_\_\_

Feature Date 1915-1930Structural System Wood Frame

Original Owner's Ethnicity \_\_\_\_\_

Feature Type 9 - School; Church schoolContext EducationPrimary Exterior Cementitious Siding

Secondary Exterior \_\_\_\_\_

Condition GoodPlan Shape IrregularStyle Other Style

Architect/Builder \_\_\_\_\_

Foundation Poured concrete Stories 2Roof/Cornice Gable/shedWindow Double hung, glassDating Method(s) Estimate

Miscellaneous Information \_\_\_\_\_

**Feature Preservation Recommendation(s) (Check all that apply):** Individual nomination Contributes to a potential district No nomination potential Will not contribute to a district Potential district—feature would be a contributing element if other properties constitute a district Thematic nomination potential Component of a historic site or landscape Moved (specify all applicable choices)—a) relocation occurred within a historic period; b) recreates original site, orientation, landscape, and spatial relationships; c) compatible in context with neighboring structures; d) relocation has damaged eligibility Historical associations require further investigationRecorded By: Kathy Wilner and Hunter Andes Date Recorded: 8/25/2020

Form instructions: (1) Download; (2) Save A Copy; (3) Submit a paper copy of the form to the SHSND and upload the PDF version of the form and corresponding GIS shapefiles to the ND SHPO-run FTP site.

**NDCRS ARCHITECTURAL FORM**  
**PAGE 3 – Feature Data**Field Code Oakland Township SchoolSITS# 32 MN

Complete one Page 3 for each architectural feature at the site.

## 1. Feature Description, Integrity, Eligibility:

This feature is noted as a school on the ND DOT maps. It is a house today. The gable roof of the building, as well as the gable roof of the west entry and the shed roof of the newer addition are covered with wood shakes with metal capping and finials at the peaks. The shakes are starting to fall off or blow away. There are cornice returns at the north and south corners at the eaves on the west side of the roof. One of the hints that this was the look of the school roof before the east addition was put on. There is a red brick chimney at the center of the roof peak. There is a metal pipe on the east slope of the roof near the north side. The soffits are closed.

The siding of this building is cementitious siding. There is a small entry on the west side of the building with a warped wood entry door. A piece of the siding is missing on the west wall and shows 6 inch wood lap siding hidden underneath. A small window opening on the west wall of the entry shows framing and little glass. There are several windows on the east and south walls of the building, all double hung with storm windows. Glass in these windows is mostly intact. Two windows, two over one, are located under the peak on the second floor. There is a single window below the two with a pair of windows located in the addition. Two more windows are located on the east side and are on either side of a wood entry door. No information about the interior. Light fixtures at both doors would indicate electricity.

## 2. Owner's Contact Information:

Cassie and Kevin Fjeldahl  
5085 71st Ave NW  
Stanley ND 58784

Recorded By: Kathy Wilner and Hunter Andes Date Recorded: 8/25/2020

**NDCRS ARCHITECTURAL FORM****PAGE 4 – Site Description****Field Code** Oakland Township School**SITS# 32** MN3. Site Area (ft<sup>2</sup>):

4. Description of Access and Site Setting:

**This building has a yard full of bee hives today. There are farms to the northwest and west. This area is farm fields all directions. This building is located 12 miles north of Highway 23 on Highway 8 to 51st St NW. Turn right (east) and drive 8 miles to 71st Ave NW. Turn right and go 1 mile south. The building is on the northwest corner of the intersection of 71st Ave NW and 50th St NW.**

5. Summary of ALL Site Features and Evaluation of Significance:

6. References/Comments:

**Recorded By:** Kathy Wilner and Hunter Andes **Date Recorded:** 8/25/2020

Form instructions: (1) Download; (2) Save A Copy; (3) Submit a paper copy of the form to the SHSND and upload the PDF version of the form and corresponding GIS shapefiles to the ND SHPO-run FTP site.



South Side

Oakland Township School

8/8/2020

Kathy Wilner

MN

West Side





East Side

Oakland Township School

8/8/2020

Kathy Wilner

MN



Imagery ©2020 CNES / Airbus, Maxar Technologies, USDA Farm Service Agency, Map data ©2020 200 ft

Feature