

NDCRS ARCHITECTURAL FORM

PAGE 1

UPDATE

Field Code Bull Flat School

SITS# 32MZ 2745

Map Quad Watford City NW

Site Name Bull Flat School

Map Quad

Site Name

LTL T. 152 N., R. 100 W., Sec. 33 QQQ 8 of the QQ 5 of the Q 5

LTL T. N., R. W., Sec. QQQ of the QQ of the Q

LTL T. N., R. W., Sec. QQQ of the QQ of the Q

LTL T. N., R. W., Sec. QQQ of the QQ of the Q

NAD 1983 UTM 5311790 Zone 13N

NAD 1983 UTM 613419

City:

Subsection	
1 = N½	
2 = E½	
3 = S½	
4 = W½	
5 = NE¼	
6 = SE¼	
7 = SW¼	
8 = NW¼	

Street Number:

Street Name: Cty Rd 29

Urban Legal Description:

Total Number of Architectural Features: 1

Fieldwork Date: 8/18/2021

Reconnaissance Survey

Intensive Survey

Project & Principal Investigator:

Country School House Project
Kathy Wilner
366 43rd Ave SE
Bowdon ND 58418

Contracting Firm or Agency Completing the Form:

Additional Information:

**SHSND USE**

Component Study Unit Verified Site CR Type

Component

Component

Recorded By: Kathy Wilner Date Recorded: 10/31/2021

Form instructions: (1) Download; (2) Save A Copy; (3) Submit a paper copy of the form to the SHSND and upload the PDF version of the form and corresponding GIS shapefiles to the ND SHPO-run FTP site.

**NDCRS ARCHITECTURAL FORM**  
**PAGE 2 – Feature Data**

Field Code Bull Flat SchoolSITS# 32 MZ 2745

Complete one Page 2 for each architectural feature at the site.

Architectural Feature # 1

Construction Date \_\_\_\_\_

Feature Date 1900-1915Structural System Wood Frame

Original Owner's Ethnicity \_\_\_\_\_

Feature Type 9 - School; Church schoolContext EducationPrimary Exterior Wood, Horizontal Siding

Secondary Exterior \_\_\_\_\_

Condition FairPlan Shape RectangularStyle Other Style

Architect/Builder \_\_\_\_\_

Foundation Concrete Stories 1Roof/Cornice GableWindow Double hung openings, no glass and some framingDating Method(s) Previous documentation estimate

Miscellaneous Information \_\_\_\_\_

**Feature Preservation Recommendation(s) (Check all that apply):** Individual nomination Contributes to a potential district No nomination potential Will not contribute to a district Potential district—feature would be a contributing element if other properties constitute a district Thematic nomination potential Component of a historic site or landscape Moved (specify all applicable choices)—a) relocation occurred within a historic period; b) recreates original site, orientation, landscape, and spatial relationships; c) compatible in context with neighboring structures; d) relocation has damaged eligibility Historical associations require further investigationRecorded By: Kathy Wilner Date Recorded: 10/31/2021

Form instructions: (1) Download; (2) Save A Copy; (3) Submit a paper copy of the form to the SHSND and upload the PDF version of the form and corresponding GIS shapefiles to the ND SHPO-run FTP site.

## NDCRS ARCHITECTURAL FORM

PAGE 3 – *Feature Data*Field Code Bull Flat SchoolSITS# 32 MZ 2745Complete one Page 3 for *each* architectural feature at the site.

## 1. Feature Description, Integrity, Eligibility:

The feature is a one room prairie school on a field stone and concrete foundation. The roof is covered with failing wood shakes with metal capping and one finial. There is a short yellow brick chimney at the peak of the roof near the north end. There is also a flag pole near the chimney. The soffits are closed and there are cornice returns at the eave ends. The building measures 16 feet east to west and 20 feet north to south.

The siding begins with a rake board under the eaves at the peak ends of the school. The remainder of the siding is 6 inch wood lap with 4 inch corner trim. A door opening with two small double hung window openings are located on the north side. A transom opening is seen above the door. A bank of 5 double hung windows is located on the east side. No glass and little framing. Walls and ceiling are finished with lathe and plaster. There is waniscot. There is a small blackboard in the southwest corner. The floor is tongue and groove hardwood.

## 2. Owner's Contact Information:

Helen Grimes Trust  
12201 Minnetonka Blvd #301  
Minnetonka MN 55305

Recorded By: Kathy Wilner Date Recorded: 10/31/2021

**NDCRS ARCHITECTURAL FORM**  
**PAGE 4 – Site Description****Field Code** Bull Flat School**SITS# 32** MZ 27453. Site Area (ft<sup>2</sup>):

4. Description of Access and Site Setting:

The school is east of Hwy 85, north of Alexander 11 miles to Cty Rd 29. Turn right and go east on Cty Rd 29 east 2 1/2 miles and then south and east about 7 1/2 miles to see the school on the right (south) side of the road. Rolling hills, coulees and farm fields are all directions around the school.

5. Summary of ALL Site Features and Evaluation of Significance:

6. References/Comments:

Kathy Wilner  
366 43rd Ave SE  
Bowdon ND 58418

**Recorded By:** Kathy Wilner **Date Recorded:** 10/31/2021

Form instructions: (1) Download; (2) Save A Copy; (3) Submit a paper copy of the form to the SHSND and upload the PDF version of the form and corresponding GIS shapefiles to the ND SHPO-run FTP site.



East Side

Bull Flat School

8/18/2021

Kathy Wilner

MZ



West Side



North Side

Bull Flat School

8/18/2021

Kathy Wilner

MZ



Imagery ©2021 Landsat / Copernicus, Maxar Technologies, USDA Farm Service Agency, Map data ©2021

2000 ft 

**Feature**

**NDCRS ARCHITECTURAL SITE FORM**  
**PAGE 1**

UPDATE

SITS# 32 MZ 2745

**SITE IDENTIFICATION**

Field Code \_\_\_\_\_ Site Name Bull Flat School  
Site Name \_\_\_\_\_

Map Quad Watford City NW  
Map Quad \_\_\_\_\_

LTL	TWP	<u>152</u>	R	<u>100</u>	SEC	<u>33</u>	QQQ	<u>8</u>	QQ	<u>5</u>	Q	<u>5</u>
LTL	TWP	_____	R	_____	SEC	_____	QQQ	_____	QQ	_____	Q	_____
LTL	TWP	_____	R	_____	SEC	_____	QQQ	_____	QQ	_____	Q	_____
LTL	TWP	_____	R	_____	SEC	_____	QQQ	_____	QQ	_____	Q	_____

UTM \_\_\_\_\_ 5311790 \_\_\_\_\_ N ZONE 13N  
UTM \_\_\_\_\_ 613419 \_\_\_\_\_ E NAD 1927 \_\_\_\_\_ NAD 1983

Subsection: 1 = N½ 2 = E½ 3 = S½ 4 = W½ 5 = NE¼ 6 = SE¼ 7 = SW¼ 8 = NW¼
---

City: \_\_\_\_\_  
Street Number: \_\_\_\_\_  
Street Name: \_\_\_\_\_  
Urban Legal Description: \_\_\_\_\_

**SITE DATA**

Total # *Architectural* Features: 1

Fieldwork Date: 6/15/2014

Reconnaissance Survey  Intensive Survey \_\_\_\_\_

Project Title & Supervisor:

Project Title: McKenzie County's McKenzie Northern Bypass  
Supervisor: Diana M. Barg

Report Title & Author(s):

Report Title: McKenzie Northern Bypass Roadway: A Class III Cultural Resource Inventory in McKenzie County, North Dakota. Author: Diana M. Barg

Additional Information: No changes observed.

**SHSND USE**

Area of Significance <u>2</u>	Ecozone <u>22</u>	Verified Site <u>1</u>	CR Type <u>2</u>
Area of Significance _____	Ecozone _____	Non-Site _____	
Area of Significance _____			

Recorded By D. Barg and P. Bauschard Date Recorded 11/20/2014  
(First Name & Last Name) (mm/dd/year)

*Instructions to complete a digital version of this form: (1) Download a copy to your hard drive; (2) Open the saved blank copy; (3) Fill out the form; (4) Use the Save As command to rename the form appropriately and save; (5) Print and submit to SHSND.*



**NDCRS ARCHITECTURAL SITE FORM  
PAGE 5—SITE DESCRIPTION**

UPDATE

Field Code \_\_\_\_\_

SITS# 32 MZ 2745**6. Summary of ALL Site Features & Evaluation of Significance:**

Additional research revealed that the one room schoolhouse was Bull Flat School, which was open as early as the 1920s, if not earlier.

A deed search demonstrated a lack of associative significance with any event or person; the site does not qualify for inclusion in the National Register of Historic Places (NRHP) under Criterion A or B. Although one of the landowners, Charles Losk, was once the mayor of Watford City and a prominent citizen for many years, this alone is not enough to qualify the site as eligible. The building is not architecturally significant, unusual, distinctive, or representative of a regional vernacular or ethnic construction tradition, and therefore does not qualify under Criterion C. The site is not viewed as having the ability to yield important information about prehistory or history; it therefore does not meet Criterion D. This site is recommended as "not eligible" for the NRHP, with no avoidance necessary.

**7. References/Comments:**

Watford City Golden Jubilee, Watford City, North Dakota: 50 Years of Progress, 1914-1964.

Arnegard Diamond Jubilee: A History of Arnegard and Surrounding Communities, 1913-1988.

Recorded By D. Barg and P. Bauschard Date Recorded 11/20/2014  
(First Name & Last Name) (mm/dd/year)

*Instructions to complete a digital version of this form:* (1) Download a copy to your hard drive; (2) Open the saved blank copy; (3) Fill out the form; (4) Use the Save As command to rename the form appropriately and save; (5) *Print* and submit to SHSND.

## NDCRS SITE FORM ATTACHMENTS SECTION

Field Code MAC

SITS# 32MZ2745UPDATE

<b>Table 1: Deed Search Results*</b>				
<b>Grantor</b>	<b>Grantee</b>	<b>Date of Original Signing</b>	<b>Document Type/Transfer Type</b>	<b>Comments</b>
USA	Charles Losk/Charles W Hagner	October 24, 1913	Indenture	
Charles Losk	Moses Losk	May 11, 1917	Warranty Deed	
Moses Losk	Jens Furstad	April 10, 1929	Indenture	
Jens Furstad	Helen Joan Furstad	March 15, 1960	Warranty Deed	
Helen J. Grimes	Helen J. and Vernon E. Grimes	July 23, 2008	Warranty Deed	

\*The deeds search was completed at McKenzie County Courthouse in Watford City, North Dakota. The names were compared with the North Dakota Biography Index database and, when appropriate, names and documents were also searched at the University of North Dakota, Chester Fritz Library in Grand Forks.

Project: HDR – McKenzie Northern Bypass  
 Site Number: 32MZ2745    Legal Location: T 152N/R 100W Section 33 NW ¼ NW ¼ of the NE ¼  
 Date of Deed Search: 11/20/2014  
 Names: Lynsee Langsdon and Gwendolyn Kristy

**UPDATE**

**NDCRS ARCHITECTURAL SITE FORM  
PAGE 1**

SITS# 32 MZ 2745

**SITE IDENTIFICATION**

Field Code QCRS-LJ071314-ASH Site Name \_\_\_\_\_  
Site Name \_\_\_\_\_

Map Quad Watford City NW, ND  
Map Quad \_\_\_\_\_

LTL	TWP	<u>152</u>	R	<u>100</u>	SEC	<u>33</u>	QQQ	<u>8</u>	QQ	<u>5</u>	Q	<u>5</u>
LTL	TWP	_____	R	_____	SEC	_____	QQQ	_____	QQ	_____	Q	_____
LTL	TWP	_____	R	_____	SEC	_____	QQQ	_____	QQ	_____	Q	_____
LTL	TWP	_____	R	_____	SEC	_____	QQQ	_____	QQ	_____	Q	_____

UTM 5311785 N ZONE 13N  
UTM 613411 E NAD 1927 \_\_\_\_\_ NAD 1983

Subsection:
1 = N $\frac{1}{2}$
2 = E $\frac{1}{2}$
3 = S $\frac{1}{2}$
4 = W $\frac{1}{2}$
5 = NE $\frac{1}{4}$
6 = SE $\frac{1}{4}$
7 = SW $\frac{1}{4}$
8 = NW $\frac{1}{4}$

City: Alexander  
Street Number: \_\_\_\_\_  
Street Name: County Road 29  
Urban Legal Description: \_\_\_\_\_

**SITE DATA**

Total # **Architectural** Features: 1

Fieldwork Date: 7/13/2014

Reconnaissance Survey \_\_\_\_\_ Intensive Survey

Project Title & Supervisor:  
ND3214018 Arnegard Rural Exchange T3.0 BER  
Andrea F. Behan

Report Title & Author(s):  
Class II and III Cultural Resources Inventory of the Reservation Telephone Cooperative Arnegard Rural Exchange T3.0 BER Buried Cables Project by Andrea F. Behan

Additional Information: one room schoolhouse

<b>SHSND USE</b>	Area of Significance <u>2</u>	Ecozone <u>22</u>	Verified Site <u>1</u>	CR Type <u>2</u>
	Area of Significance _____	Ecozone _____	Non-Site _____	
	Area of Significance _____			

Recorded By Lisa M. Jennings Date Recorded 7/13/2014  
(First Name & Last Name) (mm/dd/year)

*Instructions to complete a digital version of this form: (1) Download a copy to your hard drive; (2) Open the saved blank copy; (3) Fill out the form; (4) Use the Save As command to rename the form appropriately and save; (5) Print and submit to SHSND.*

**NDCRS ARCHITECTURAL SITE FORM**  
**PAGE 2—Feature Data**

Field Code QCRS-LJ071314-ASHSITS# 32 MZ

**Complete one Page 2 for *each* architectural feature at the site.**

Architectural Feature # 1

Construction Date \_\_\_\_\_

Feature Type 9Condition 5Feature Date 4Context 7Plan Shape 5Structural System 25Primary Exterior 26Style Gabled Front: Gabled L/T

Original Owner's Ethnicity \_\_\_\_\_

Secondary Exterior \_\_\_\_\_

Architect/Builder \_\_\_\_\_

Other Information:

Foundation concrete Stories 1Roof/Cornice front gabled with wood shakes/shinglesWindow two windows on the north side/ front of the building and two on east side, no frames extantDating Method(s): professional estimate

**Feature Preservation Recommendation(s) (Check all that apply):**

 Individual nomination Contributes to a potential district No nomination potential Will not contribute to a district Potential district—feature would be a contributing element if other properties constitute a district Thematic nomination potential Component of a historic site or landscape

Moved (specify all applicable choices)—a) relocation occurred within a historic period; b) recreates original site, orientation, landscape, & spatial relationships; c) compatible in context with neighboring structures; d) relocation has damaged eligibility

 Historical associations require further investigation

Recorded By Lisa M. Jennings Date Recorded 7/13/2014  
 (First Name & Last Name) (mm/dd/year)

*Instructions to complete a digital version of this form:* (1) Download a copy to your hard drive; (2) Open the saved blank copy; (3) Fill out the form; (4) Use the Save As command to rename the form appropriately and save; (5) Print and submit to SHSND.

**NDCRS ARCHITECTURAL SITE FORM**  
**PAGE 3—Feature Data**Field Code QCRS-LJ071314-ASHSITS# 32 MZ**Complete a Page 3 for each feature.****1. Feature Description, Integrity, Eligibility:**

The feature is a one room school house or single family home with horizontal wood siding, front gabled roof, wood shakes, and brick chimney. This structure is typical of of ones made in the 1920s and 1930s. It is not an outstanding example of its kind. Due to the prevalence of this type of building and the deterioration due to neglect, it is recommended as not eligible for the NRHP.

Recorded By Lisa M. Jennings Date Recorded 7/13/2014  
(First Name & Last Name) (mm/dd/year)

*Instructions to complete a digital version of this form:* (1) Download a copy to your hard drive; (2) Open the saved blank copy; (3) Fill out the form; (4) Use the Save As command to rename the form appropriately and save; (5) *Print* and submit to SHSND.

**NDCRS ARCHITECTURAL SITE FORM  
PAGE 4—SITE DESCRIPTION**Field Code QCRS-LJ071314-ASHSITS# 32 MZ**Complete one Page 4 for the entire site.**

## 2. Owner's Contact Information:

unknown

## 3. Access (to rural areas):

From Watford City head west for 4.6 miles on ND-200/US-85 and then north on County Road 29 for 3 miles and then turn left to stay on county road 29 for another 9.3 miles. The site is 50 feet off the road edge on the south side of the road.

4. Site Area (ft<sup>2</sup>): 1,0005. Description of **SETTING**:

The site is in rolling plain that, for the most part, is being used as cropland and pasture. There are no other structures for about a mile in all directions. The majority of the nearby fields supported wheat crops at the time this site was recorded. There are many intermittent streams in this area, which is within the Missouri River drainage system.

Recorded By Lisa M. Jennings Date Recorded 7/13/2014  
(First Name & Last Name) (mm/dd/year)

*Instructions to complete a digital version of this form:* (1) Download a copy to your hard drive; (2) Open the saved blank copy; (3) Fill out the form; (4) Use the Save As command to rename the form appropriately and save; (5) Print and submit to SHSND.

**NDCRS ARCHITECTURAL SITE FORM  
PAGE 5—SITE DESCRIPTION**Field Code QCRS-LJ071314-ASHSITS# 32 MZ**6. Summary of ALL Site Features & Evaluation of Significance:**

The feature is a one room school house or single family home with horizontal wood siding, front gabled roof, wood shakes, and brick chimney. This structure is typical of ones made in the 1920s and 1930s. It is not an outstanding example of its kind. Due to the prevalence of this type of building and the deterioration due to neglect, it is recommended as not eligible for the NRHP.

**7. References/Comments:**

n/a

Recorded By Lisa M. Jennings Date Recorded 7/13/2014  
(First Name & Last Name) (mm/dd/year)

*Instructions to complete a digital version of this form:* (1) Download a copy to your hard drive; (2) Open the saved blank copy; (3) Fill out the form; (4) Use the Save As command to rename the form appropriately and save; (5) *Print* and submit to SHSND.

**Photos**



Site facing south.



Site facing southwest.



# NDCRS ARCHITECTURAL SITE FORM PAGE 1

SITS# 32 MZ 2745

### SITE IDENTIFICATION

Field Code MAC-MNB-2002 Site Name \_\_\_\_\_  
Site Name \_\_\_\_\_

Map Quad Watford City NW  
Map Quad \_\_\_\_\_

LTL	TWP	<u>152</u>	R	<u>100</u>	SEC	<u>33</u>	QQQ	<u>8</u>	QQ	<u>5</u>	Q	<u>5</u>
LTL	TWP	_____	R	_____	SEC	_____	QQQ	_____	QQ	_____	Q	_____
LTL	TWP	_____	R	_____	SEC	_____	QQQ	_____	QQ	_____	Q	_____
LTL	TWP	_____	R	_____	SEC	_____	QQQ	_____	QQ	_____	Q	_____

UTM 5311790 N ZONE 13N  
UTM 613419 E NAD 1927 \_\_\_\_\_ NAD 1983

Subsection:
1 = N½
2 = E½
3 = S½
4 = W½
5 = NE¼
6 = SE¼
7 = SW¼
8 = NW¼

City: \_\_\_\_\_  
Street Number: \_\_\_\_\_  
Street Name: \_\_\_\_\_  
Urban Legal Description: \_\_\_\_\_

### SITE DATA

Total # **Architectural** Features: 1

Fieldwork Date: 6/15/2014

Reconnaissance Survey  Intensive Survey \_\_\_\_\_

Project Title & Supervisor:

Project Title: HDR Engineering Inc.'s McKenzie Northern Bypass  
Supervisor: Diana M. Barg

Report Title & Author(s):

Report Title: Results of a Cultural Resource Inventory for HDR Engineering, Inc's Proposed McKenzie Northern Bypass Roadway Project in McKenzie County, North Dakota. Author: Diana M. Barg

Additional Information: Site: 1 one-room schoolhouse

### SHSND USE

Area of Significance <u>2</u>	Ecozone <u>22</u>	Verified Site <u>1</u>	CR Type <u>2</u>
Area of Significance _____	Ecozone _____	Non-Site _____	
Area of Significance _____			

Recorded By D. Barg and P. Bauschard Date Recorded 6/15/2014  
(First Name & Last Name) (mm/dd/year)

Instructions to complete a digital version of this form: (1) Download a copy to your hard drive; (2) Open the saved blank copy; (3) Fill out the form; (4) Use the Save As command to rename the form appropriately and save; (5) Print and submit to SHSND.

## NDCRS ARCHITECTURAL SITE FORM PAGE 2—Feature Data

Field Code MAC-MNB-2002SITS# 32 MZ

**Complete one Page 2 for each architectural feature at the site.**

Architectural Feature # 1

Construction Date \_\_\_\_\_

Feature Type 9Condition 5Feature Date 4Context 7Plan Shape 5Structural System 25Primary Exterior 26Style Gabled Front: Gabled L/T

Original Owner's Ethnicity \_\_\_\_\_

Secondary Exterior \_\_\_\_\_

Architect/Builder \_\_\_\_\_

Other Information:

Foundation Field stone and concrete Stories 1Roof/Cornice Front-gabled; wood shake shinglesWindow Original openings intact; no glass remainsDating Method(s): Plat maps

**Feature Preservation Recommendation(s) (Check all that apply):**

 Individual nomination Contributes to a potential district No nomination potential Will not contribute to a district Potential district—feature would be a contributing element if other properties constitute a district Thematic nomination potential Component of a historic site or landscape

Moved (specify all applicable choices)—a) relocation occurred within a historic period; b) recreates original site, orientation, landscape, & spatial relationships; c) compatible in context with neighboring structures; d) relocation has damaged eligibility

 Historical associations require further investigationRecorded By D. Barg and P. Bauschard  
(First Name & Last Name)Date Recorded 6/15/2014  
(mm/dd/year)

Instructions to complete a digital version of this form: (1) Download a copy to your hard drive; (2) Open the saved blank copy; (3) Fill out the form; (4) Use the Save As command to rename the form appropriately and save; (5) Print and submit to SHSND.

**NDCRS ARCHITECTURAL SITE FORM**  
**PAGE 3—Feature Data**Field Code MAC-MNB-2002SITS# 32 MZ**Complete a Page 3 for each feature.****1. Feature Description, Integrity, Eligibility:**

DESCRIPTION: Feature 1 is a wood-framed one-room schoolhouse. The structure has horizontal shiplap siding and corner boards, all of which is painted white. The schoolhouse has a front-gabled roof with gable returns. It is clad in wood shingles, many of which are missing. A brick chimney is located on the north side of the roof, with a metal flue protruding from the top. Just north of the chimney, there is a flagpole protruding from the roof, which still has two pulleys intact. There are also remnants of jacks (wooden 2 x 4 boards, used as steps) leading to the flagpole. The main door is located on the north facade, but it has been partially boarded up, while the bottom portion is open to the elements. It appears that there may have once been a front stoop or small deck in front of this door. There are two windows on either side of the front door, one single-hung, wood-framed window to the west of the door, and one opening on the east side that has been boarded up. A transom window, just above the front door, has been boarded up as well. In addition, there is a bank of five windows on the east wall, as is typical of most one-room schoolhouses. However, three of the five windows have been boarded up, while the two remaining windows are single-hung with wooden frames. No glass remains. The front area of the schoolhouse, just inside the front door, is a small mudroom/entryway (2 feet by 2 feet), with four storm windows, some of which have glass missing. There are two wooden doors from the entryway into the schoolhouse itself, both of which are a dark yellow/orange color, and have original metal knobs. Inside the school, on the west wall, there is a small opening that has been covered by metal sheeting. There are small metal gable vents located beneath the roof apexes on the north and south walls, and a light fixture is found above the door on the north facade. Debris is strewn about the interior of the schoolhouse, including pieces of wood and lumber, as well as old educational material. For example, a "Young Citizens League Manual" from 1955 was present, as was a copy of "This Year in Agriculture" from 1932. It is clear that a stove was once located inside the school, as an iron ring is still present on the floor, while an iron vent/attachment is located on top of the north wall.

INTEGRITY: This feature retains several essential aspects of integrity, including integrity of setting, design, location, materials, and workmanship. Integrity of feeling has been reduced by the deterioration of the structure over the years, as well as by the boarding up of most openings.

ELIGIBILITY: The schoolhouse has not been evaluated for eligibility to the National Register of Historic Places. Current survey data are not sufficient to determine significance. Until a deed search can be performed, avoidance is recommended.

Recorded By D. Barg and P. Bauschard Date Recorded 6/15/2014  
(First Name & Last Name) (mm/dd/year)

*Instructions to complete a digital version of this form: (1) Download a copy to your hard drive; (2) Open the saved blank copy; (3) Fill out the form; (4) Use the Save As command to rename the form appropriately and save; (5) Print and submit to SHSND.*

**NDCRS ARCHITECTURAL SITE FORM  
PAGE 4—SITE DESCRIPTION**Field Code MAC-MNB-2002SITS# 32 MZ**Complete one Page 4 for the entire site.**

## 2. Owner's Contact Information:

Private

## 3. Access (to rural areas):

From the intersection of US Highway 85/ Theodore Roosevelt Expy and County Road 29, travel east on County Road 29 for approximately 8.7 miles. The site is located approximately 20 meters south of the road.

4. Site Area (ft<sup>2</sup>): 5085. Description of **SETTING**:

This site is located in gently rolling lowland plains, and is surrounded by cropland. County Road 29 is located directly to the north, while a farmstead is situated just southwest of the schoolhouse.

Recorded By D. Barg and P. Bauschard Date Recorded 6/15/2014  
(First Name & Last Name) (mm/dd/year)

*Instructions to complete a digital version of this form:* (1) Download a copy to your hard drive; (2) Open the saved blank copy; (3) Fill out the form; (4) Use the Save As command to rename the form appropriately and save; (5) *Print* and submit to SHSND.

**NDCRS ARCHITECTURAL SITE FORM  
PAGE 5—SITE DESCRIPTION**Field Code MAC-MNB-2002SITS# 32 MZ**6. Summary of ALL Site Features & Evaluation of Significance:**

This site consists of a one-room schoolhouse in fair condition. The structure has a front-gabled roof with wood shake shingles, and horizontal wood shiplap siding. Most of the white paint has chipped and faded away, while most of the windows, as well as the main door on the north facade, have been boarded up. The interior of the school is littered with debris.

This site retains several essential aspects of integrity, including integrity of setting, location, design, materials, and workmanship. Integrity of feeling has been reduced by the deterioration of the structure over the years, as well as by the boarding up of most openings.

The site has not been evaluated for eligibility to the National Register of Historic Places. Current survey data are not sufficient to determine significance. Until a deed search can be performed, avoidance is recommended.

**7. References/Comments:**

Recorded By D. Barg and P. Bauschard Date Recorded 6/15/2014  
(First Name & Last Name) (mm/dd/year)

*Instructions to complete a digital version of this form:* (1) Download a copy to your hard drive; (2) Open the saved blank copy; (3) Fill out the form; (4) Use the Save As command to rename the form appropriately and save; (5) *Print* and submit to SHSND.

**NDCRS SITE FORM  
ATTACHMENTS SECTION**

**Field Code** MAC-MNB-2002

**SITS#** 32MZ



**Figure 2:** View of MAC-MNB-2002, to the south (Image 2630).



**Figure 3:** View of MAC-MNB-2002, to the southwest (Image 2621).

**Recorded By** D. Barg and P. Bauschard

**Date Recorded** 6/15/2014

**NDCRS SITE FORM  
ATTACHMENTS SECTION**

**Field Code** MAC-MNB-2002

**SITS#** 32MZ



**Figure 4:** View of MAC-MNB-2002, to the northeast (Image 2624).



**Figure 5:** Doors from entryway into school (Image 2638).