

**NDCRS ARCHITECTURAL FORM
PAGE 1**

Field Code Randolph School #1 & #2

SITS# 32MZ 3000

Map Quad Alexander

Site Name Randolph School #1 & #2

Map Quad _____

Site Name _____

LTL T. 150 N., R. 102 W., Sec. 23 QQQ 7 of the QQ 8 of the Q 8

LTL T. N., R. W., Sec. QQQ of the QQ of the Q

LTL T. N., R. W., Sec. QQQ of the QQ of the Q

LTL T. N., R. W., Sec. QQQ of the QQ of the Q

NAD 1983 UTM 5295029 Zone 13N

NAD 1983 UTM 596496

Subsection
1 = N½
2 = E½
3 = S½
4 = W½
5 = NE¼
6 = SE¼
7 = SW¼
8 = NW¼

City: _____

Street Number: _____

Street Name: 146th Ave NW

Urban Legal Description: _____

Total Number of **Architectural** Features: 1

Fieldwork Date: 8/18/2021

Reconnaissance Survey

Intensive Survey

Project & Principal Investigator:

Country School House Project
Kathy Wilner
366 43rd Ave SE
Bowdon ND 58418

Contracting Firm or Agency Completing the Form:

Additional Information:

SHSND USE

Component _____ Study Unit _____ Verified Site _____ CR Type _____

Component _____

Component _____

Recorded By: Kathy Wilner **Date Recorded:** 10/30/2021

NDCRS ARCHITECTURAL FORM
PAGE 2 – Feature Data

Field Code Randolph Schools #1 & #2

SITS# 32 MZ 3000

Complete one Page 2 for each architectural feature at the site.

Architectural Feature # 1

Construction Date _____

Feature Date 1900-1915

Structural System Wood Frame

Original Owner's Ethnicity _____

Feature Type 9 - School; Church school

Context Education

Primary Exterior Wood, Horizontal Siding

Secondary Exterior _____

Condition Fair

Plan Shape Rectangular

Style Other Style

Architect/Builder _____

Foundation Concrete Stories 1

Roof/Cornice Gable

Window Double hung openings, some framing

Dating Method(s) Previous documentation

Miscellaneous Information _____

Feature Preservation Recommendation(s) (Check all that apply):

- Individual nomination
- Contributes to a potential district
- No nomination potential
- Will not contribute to a district
- Potential district—feature would be a contributing element if other properties constitute a district
- Thematic nomination potential
- Component of a historic site or landscape
- Moved (specify all applicable choices)—a) relocation occurred within a historic period; b) recreates original site, orientation, landscape, and spatial relationships; c) compatible in context with neighboring structures; d) relocation has damaged eligibility
- Historical associations require further investigation

Recorded By: Kathy Wilner Date Recorded: 10/30/2021

NDCRS ARCHITECTURAL FORM
PAGE 3 – Feature Data**Field Code** Randolph School #1 & #2**SITS#** 32 MZ 3000**Complete one Page 3 for each architectural feature at the site.****1. Feature Description, Integrity, Eligibility:**

The feature is a one room prairie school on a poured concrete basement. It was previously documented as part of the Randolph School site. The story of the building is complete so I won't rewrite it. The buildings are all pretty tired.

2. Owner's Contact Information:

Susan Link
14651 27th St NW
Alexander ND 58831

Recorded By: Kathy Wilner **Date Recorded:** 10/30/2021

NDCRS ARCHITECTURAL FORM
PAGE 4 – Site Description**Field Code** Randolph School #1 & #2**SITS# 32** MZ 30003. Site Area (ft²):

4. Description of Access and Site Setting:

The Randolph School site is west of Watford City. From Hwy 85, where it curves to the north south of Alexander drive west on 27th St NW 3 miles to 146th Ave NW. Turn left and go south to see the schools on the right. There is an oil well pad to the northeast, a farm east and farm fields all directions.

5. Summary of ALL Site Features and Evaluation of Significance:

6. References/Comments:

Kathy Wilner
366 43rd Ave SE
Bowdon ND 58418

Recorded By: Kathy Wilner **Date Recorded:** 10/30/2021

Form instructions: (1) Download; (2) Save A Copy; (3) Submit a paper copy of the form to the SHSND and upload the PDF version of the form and corresponding GIS shapefiles to the ND SHPO-run FTP site.

NDCRS ARCHITECTURAL FORM
PAGE 2 – Feature Data

Field Code Randolph Scools #1 & #2 SITS# 32 MZ 3000

Complete one Page 2 for each architectural feature at the site.

Architectural Feature # 2

Construction Date _____

Feature Date 1915-1930

Structural System Wood Frame

Original Owner's Ethnicity _____

Feature Type 9 - School; Church school

Context Education

Primary Exterior Wood, Horizontal Siding

Secondary Exterior _____

Condition Fair

Plan Shape Rectangular

Style Other Style

Architect/Builder _____

Foundation Concrete Stories 1

Roof/Cornice Gable

Window Double hung openings, some framing

Dating Method(s) Previous documentiion

Miscellaneous Information _____

Feature Preservation Recommendation(s) (Check all that apply):

- Individual nomination
- Contributes to a potential district
- No nomination potential
- Will not contribute to a district
- Potential district—feature would be a contributing element if other properties constitute a district
- Thematic nomination potential
- Component of a historic site or landscape
- Moved (specify all applicable choices)—a) relocation occurred within a historic period; b) recreates original site, orientation, landscape, and spatial relationships; c) compatible in context with neighboring structures; d) relocation has damaged eligibility
- Historical associations require further investigation

Recorded By: Kathy Wilner Date Recorded: 10/30/2021

**NDCRS ARCHITECTURAL FORM
PAGE 3 – Feature Data**

Field Code Randolph Sools #1 & #2

SITS# 32 MZ 3000

Complete one Page 3 for each architectural feature at the site.

1. Feature Description, Integrity, Eligibility:

The feature is also a one room prairie school on a poured concrete basement. It was previously documented as part of the Randolph School site. The story of the building is complete and I won't repeat it here. The difference here is that the previous person documenting the building suggested that it was likely a house. I think it was likely used as a house but all indications point toward a previous life as a school. It could have been moved next to the school to serve as a teacherage.

2. Owner's Contact Information:

Recorded By: Kathy Wilner **Date Recorded:** 10/30/2021



North
Side

Randolph School #1

8/18/2021

Kathy Wilner

MZ

West Side





South Side

Randolph School #1

8/18/2021

Kathy Wilner

MZ

East Side





West Side

Randolph School #2

8/18/2021

Kathy Wilner

MZ



South Side



East Side

Randolph School #2

8/18/2021

Kathy Wilner

MZ



North Side



Imagery ©2021 Maxar Technologies, USDA Farm Service Agency, Map data ©2021 500 ft

Feature

NDCRS ATTACHMENT SECTION

Field Code _____

SITS# 32 MZ 3000



Photo taken summer 2010 by SHSND intern Alicia Liebel



Photo taken summer 2010 by SHSND intern Alicia Liebel

Recorded By: Lorna Meidinger **Date Recorded:** 11/17/2020

NDCRS ATTACHMENT SECTION

Field Code _____

SITS# 32 MZ 3000



Photo taken summer 2010 by SHSND intern Alicia Liebel

Recorded By: Lorna Meidinger **Date Recorded:** 11/17/2020

NDCRS ATTACHMENT SECTION

Field Code _____

SITS# 32 MZ 3000



Photo taken summer 2010 by SHSND intern Alicia Liebel

Recorded By: Lorna Meidinger **Date Recorded:** 11/17/2020

NDCRS ATTACHMENT SECTION

Field Code _____

SITS# 32 MZ 3000



Photos taken summer 2010 by SHSND intern Alicia Liebel

Recorded By: Lorna Meidinger **Date Recorded:** 11/17/2020

NDCRS ATTACHMENT SECTION

Field Code _____

SITS# 32 MZ 3000



Photo taken summer 2010 by SHSND intern Alicia Liebel

Recorded By: Lorna Meidinger **Date Recorded:** 11/17/2020

NDCRS ATTACHMENT SECTION

Field Code _____

SITS# 32 MZ 3000



Photo taken summer 2010 by SHSND intern Alicia Liebel

Recorded By: Lorna Meidinger **Date Recorded:** 11/17/2020

NDCRS ATTACHMENT SECTION

Field Code _____

SITS# 32 MZ 3000



Photo taken summer 2010 by SHSND intern Alicia Liebel

Recorded By: Lorna Meidinger **Date Recorded:** 11/17/2020

Form instructions: (1) Download; (2) Save A Copy; (3) Submit a paper copy of the form to the SHSND and upload the PDF version of the form and corresponding GIS shapefiles to the ND SHPO-run FTP site.

NDCRS ATTACHMENT SECTION

Field Code

SITS# 32

MZ

3000



Photo taken summer 2010 by SHSND intern Alicia Liebel

Recorded By: Lorna Meidinger

Date Recorded: 11/17/2020

NDCRS ATTACHMENT SECTION

Field Code _____ **SITS# 32** **MZ** **3000**



Photo taken summer 2010 by SHSND intern Alicia Liebel

Recorded By: Lorna Meidinger **Date Recorded:** 11/17/2020

NDCRS ATTACHMENT SECTION

Field Code _____

SITS# 32

MZ _____

3000



Photo taken summer 2010 by SHSND intern Alicia Liebel

Recorded By: Lorna Meidinger

Date Recorded: 11/17/2020

NDCRS ATTACHMENT SECTION

Field Code _____

SITS# 32 **MZ** **3000**



Photo taken summer 2010 by SHSND intern Alicia Liebel

Recorded By: Lorna Meidinger

Date Recorded: 11/17/2020

NDCRS ATTACHMENT SECTION

Field Code

SITS# 32 MZ 3000



Photo taken summer 2010 by SHSND intern Alicia Liebel

Recorded By: Lorna Meidinger **Date Recorded:** 11/17/2020

NDCRS ATTACHMENT SECTION

Field Code _____

SITS# 32 **MZ** **3000**



Photo taken summer 2010 by SHSND intern Alicia Liebel

Recorded By: Lorna Meidinger

Date Recorded: 11/17/2020

NDCRS ATTACHMENT SECTION

Field Code _____

SITS# 32 MZ 3000



Photo taken summer 2010 by SHSND intern Alicia Liebel

Recorded By: Lorna Meidinger **Date Recorded:** 11/17/2020

NDCRS ATTACHMENT SECTION

Field Code _____

SITS# 32 MZ 3000



Photo taken summer 2010 by SHSND intern Alicia Liebel

Recorded By: Lorna Meidinger **Date Recorded:** 11/17/2020

NDCRS ATTACHMENT SECTION

Field Code _____

SITS# 32 MZ 3000



Photo taken summer 2010 by SHSND intern Alicia Liebel

Recorded By: Lorna Meidinger **Date Recorded:** 11/17/2020

NDCRS ATTACHMENT SECTION

Field Code _____

SITS# 32 MZ 3000



Photo taken summer 2010 by SHSND intern Alicia Liebel

Recorded By: Lorna Meidinger

Date Recorded: 11/17/2020

NDCRS ATTACHMENT SECTION

Field Code _____

SITS# 32 MZ 3000



Photo taken summer 2010 by SHSND intern Alicia Liebel

Recorded By: Lorna Meidinger **Date Recorded:** 11/17/2020

NDCRS ATTACHMENT SECTION

Field Code _____

SITS# 32 MZ 3000



Photo taken summer 2010 by SHSND intern Alicia Liebel

Recorded By: Lorna Meidinger

Date Recorded: 11/17/2020

NDCRS ARCHITECTURAL SITE FORM

PAGE 1

Field Code JUP-MKRWD14-201

SITS# 32 MZ 3000

SITE IDENTIFICATION

Map Quad Alexander Site Name Randolph School
Map Quad _____ Site Name _____

LTL	___	TWP	<u>150</u>	R	<u>102</u>	SEC	<u>23</u>	QQQ	<u>7</u>	QQ	<u>8</u>	Q	<u>8</u>
LTL	___	TWP	_____	R	_____	SEC	_____	QQQ	_____	QQ	_____	Q	_____
LTL	___	TWP	_____	R	_____	SEC	_____	QQQ	_____	QQ	_____	Q	_____
LTL	___	TWP	_____	R	_____	SEC	_____	QQQ	_____	QQ	_____	Q	_____

NAD 1983, UTM 5295029 N ZONE 13N
NAD 1983, UTM 596496 E

Subsection:
1 = N $\frac{1}{2}$
2 = E $\frac{1}{2}$
3 = S $\frac{1}{2}$
4 = W $\frac{1}{2}$
5 = NE $\frac{1}{4}$
6 = SE $\frac{1}{4}$
7 = SW $\frac{1}{4}$
8 = NW $\frac{1}{4}$

City: Alexander

Street Number: _____

Street Name: Unnamed

Urban Legal Description: _____

SITE DATA

Total # **Architectural** Features: 4

Fieldwork Date: 05/13/2014

Reconnaissance Survey Intensive Survey

Project & Principal Investigator:

McKenzie County Rural Water District, System IV John G. Morrison

Report Title & Author(s):

McKenzie County Rural Water District, System IV: Class III Cultural Resource Inventory, McKenzie County, North Dakota. B. Joby Hunt

Contracting firm or Agency completing the form:

Juniper, LLC

Additional Information:

Randolph School site

SHSND USE

Area of Significance <u>2</u>	Ecozone <u>22</u>	Verified Site <u>1</u>	CR Type <u>2</u>
Area of Significance <u>3</u>	Ecozone <u>22</u>		
Area of Significance _____	Ecozone _____		

Recorded By Kaelyn M. Olson Date Recorded 01/20/2016
(First Name & Last Name) (mm/dd/year)

Instructions to complete a digital version of this form: (1) Download a copy; (2) Open the saved blank copy; (3) Fill out the form; (4) Use the Save As command to rename the form appropriately, and save; (5) **Print** and submit to SHSND.

**NDCRS ARCHITECTURAL SITE FORM
PAGE 2—Feature Data**

Field Code JUP-MKRWD14-201

SITS# 32 MZ

Complete one Page 2 for each architectural feature at the site.

Architectural Feature # 1

Construction Date _____	Feature Type <u>9</u>	Condition <u>5</u>
Feature Date <u>4</u>	Context <u>7</u>	Plan Shape <u>5</u>
Structural System <u>25</u>	Primary Exterior <u>26</u>	Style <u>Utilitarian</u>
Original Owner's Ethnicity _____	Secondary Exterior <u>N/A</u>	Architect/Builder _____

Other Information: _____

Foundation Historic concrete Stories 1.0

Roof/Cornice Gable

Window Original windows replaced or missing, openings intact

Dating Method(s): Professional estimate, topo maps

Feature Preservation Recommendation(s) (Check all that apply):

- Individual nomination
 - Contributes to a potential district
 - No nomination potential
 - Will not contribute to a district
 - Potential district—feature would be a contributing element if other properties constitute a district
 - Thematic nomination potential
 - Component of a historic site or landscape
- Moved (specify all applicable choices)—a) relocation occurred within a historic period; b) recreates original site, orientation, landscape, & spatial relationships; c) compatible in context with neighboring structures; d) relocation has damaged eligibility
- Historical associations require further investigation

Recorded By Kaelyn M. Olson Date Recorded 01/20/2016
(First Name & Last Name) (mm/dd/year)

*Instructions to complete a digital version of this form: (1) Download a copy; (2) Open the saved blank copy; (3) Fill out the form; (4) Use the Save As command to rename the form appropriately, and save; (5) **Print** and submit to SHSND.*

**NDCRS ARCHITECTURAL SITE FORM
PAGE 3—Feature Data**Field Code JUP-MKRWD14-201SITS# 32 MZ**Complete a Page 3 for each feature.****1. Feature Description, Integrity, Eligibility:**

Feature 1 consists of a one room school house as part of the Randolph School site. The structure is utilitarian and composed of a historic concrete foundation, a wooden frame, horizontal wooden slat exterior, and a wood shingle roof. A single window is located on the western elevation of the structure, in the entryway and overlooking the road; a row of six windows are located on the northern wall of the main room, facing towards the highway, and two boarded up windows are set into concrete at cellar height. The front (west) side of the building has three wooden steps inset between the main room and the entry room, leading into an entry space that is approximately half the width of the main room. A metal tank approximately 4' in diameter is located on the eastern side of the structure, in close proximity to electrical wiring; the generator or other power sources are no longer present. Cellar steps and the remains of the door to the stairs are located on the eastern side of the structure, immediately north of the tank. The exterior was formerly painted white, but the paint has faded in all places except immediately under the eaves. The gable roof consists of horizontal wooden slats surfaced with wooden shingles. A square brick chimney extends from the eastern end of the roof, and has damage on the eastern side. A metal ridge cap and metal roof caps are present and in good condition. The interior of the structure consists of an entry way to a single large room, which is painted white. The lower walls are inlaid with vertical wooden slats, and the upper walls and the inner portion of the chimney are drywall. The flooring consists of inlaid linoleum tiles laid over wooden slats; the edges of the individual tiles are peeling up, and the floor is generally in poor condition. A blackboard is located in the southeast corner of the room, on the walls facing the windows and entry. The portions that remain are in fair to good condition, and there is a stain on the wall where the central panel has fallen away to reveal the white-painted drywall. The chalk tray remains in place. Portions of the ceiling have fallen away to reveal the attic space. An empty wooden shelving unit remains on the east wall, along with a fuse box and two outlets. An early 20th century furnace is located on the eastern wall, and has a unusual glass and metal feed door. The use of the room was most likely as the school house of the Randolph School. This structure lacks aspects of structural integrity, but spatial integrity remains. Feature 1 does not qualify for the National Register of Historic Places independently under Criteria C or D, but a deeds search is needed to more fully understand nomination potential under Criteria A and B.

Recorded By Kaelyn M. Olson Date Recorded 01/20/2016
(First Name & Last Name) (mm/dd/year)

*Instructions to complete a digital version of this form: (1) Download a copy; (2) Open the saved blank copy; (3) Fill out the form; (4) Use the Save As command to rename the form appropriately, and save; (5) **Print** and submit to SHSND.*

**NDCRS ARCHITECTURAL SITE FORM
PAGE 2—Feature Data**

Field Code JUP-MKRWD14-201

SITS# 32 MZ

Complete one Page 2 for each architectural feature at the site.

Architectural Feature # 2

Construction Date _____

Feature Type 9

Condition 5

Feature Date 4

Context 7

Plan Shape 5

Structural System 25

Primary Exterior 26

Style Utilitarian

Original Owner's Ethnicity _____

Secondary Exterior _____

Architect/Builder _____

Other Information: _____

Foundation Historic concrete Stories 1.0

Roof/Cornice Gable

Window Windows missing or broken, openings intact

Dating Method(s): Professional estimate, topo maps

Feature Preservation Recommendation(s) (Check all that apply):

Individual nomination

Contributes to a potential district

No nomination potential

Will not contribute to a district

Potential district—feature would be a contributing element if other properties constitute a district

Thematic nomination potential

Component of a historic site or landscape

Moved (specify all applicable choices)—a) relocation occurred within a historic period; b) recreates original site, orientation, landscape, & spatial relationships; c) compatible in context with neighboring structures; d) relocation has damaged eligibility

Historical associations require further investigation

Recorded By Kaelyn M. Olson
(First Name & Last Name)

Date Recorded 01/20/2016
(mm/dd/year)

NDCRS ARCHITECTURAL SITE FORM
PAGE 3—Feature Data

Field Code JUP-MKRWD14-201SITS# 32 MZ**Complete a Page 3 for each feature.****1. Feature Description, Integrity, Eligibility:**

Feature 2 consists of a one-room structure that is part of the Randolph School site. Feature 2 lies 75' south of Feature 1, across the two track that bisects the site while running west/east. The structure has a large central room with a ground-level entry room, and is a wooden frame structure with horizontal wooden slat sides and a historic concrete foundation. The exterior was formerly painted white, but the paint has faded from the walls with the exception of the protected areas under the eaves. There are two windows facing west and a row of five windows facing north from the main room, and a single west-facing window from the entryway. Four of the five northern windows are boarded shut. There is no evidence of electrical wiring on the outside of the structure. The roof is in better condition than that of Feature 1 and also consists of horizontal slats covered with wooden shingles. There is a square brick chimney in good condition, and there are a metal ridge cap and metal roof caps. The interior of the structure has wooden slat walls and ceiling, with a wooden plank floor. The walls are painted pale yellow, and the ceiling is dark green; the floor is stained wood. A single wire runs along the windows on the northern wall of the central room, but there are no outlets or additional indications of potential electric wiring. There is a square opening to the attic space near the eastern end of the ceiling. The chimney is on the eastern wall and attaches to an iron stove. A metal bed frame suggests that at some point this building was used as a residence, though there are no other clear indicators of purpose for the structure and it may have been used for multiple purposes over time. Because of the similarity in structure to Feature 1 and its place in the school site, it has been coded as a school. Cut plywood, a door, a table, a wooden frame, and a metal box are also on the floor of the room. Five feet east of Feature 2 is Feature 5, a collapsed shed discussed in the attached historical archaeology form. This structure lacks aspects of structural integrity, but spatial integrity remains. Feature 2 does not qualify for the National Register of Historic Places independently under Criteria C or D, but a deeds search is needed to more fully understand nomination potential under Criteria A and B.

Recorded By Kaelyn M. Olson Date Recorded 01/20/2016
 (First Name & Last Name) (mm/dd/year)

*Instructions to complete a digital version of this form: (1) Download a copy; (2) Open the saved blank copy; (3) Fill out the form; (4) Use the Save As command to rename the form appropriately and save; (5) **Print** and submit to SHSND.*

**NDCRS ARCHITECTURAL SITE FORM
PAGE 4—SITE DESCRIPTION**

Field Code JUP-MKRWD14-201

SITS# 32 MZ

Complete one Page 4 for the entire site.

2. Owner's Contact Information:

Private

3. Access (to rural areas):

From Watford City, Take 2nd Ave SW 3.7 miles west from town and merge onto the Theodore Roosevelt Expressway/Highway 85. Follow the expressway west for 13.7 miles, then continue west on 27th St NW/County Highway 15. Continue for 3.2 miles, then turn left (south) on the unnamed road just past Antelope creek. Drive for 0.2 miles, and the site is on the left (east).

4. Site Area (ft²): 35,415

5. Description of **SETTING**:

The site is located in an area being used for agriculture east of the Little Missouri Grassland and southwest of Alexander, North Dakota. A modern farm house and complex lie 1,710' east of the site. Antelope Creek lies 1,470' east of the school site. The view from and access to the school has been altered by the addition of well pad access roads and wells. A fenceline follows the agricultural field to the east and south of the site, avoiding the site, and a two track leading into the field runs through the center of the site. No additional previously recorded cultural resources sites are related to the Randolph school or are in the adjoining sections.

Recorded By Kaelyn M. Olson Date Recorded 01/20/2016
(First Name & Last Name) (mm/dd/year)

**NDCRS ARCHITECTURAL SITE FORM
PAGE 5—SITE DESCRIPTION**Field Code JUP-MKRWD14-201SITS# 32 MZ**6. Summary of ALL Site Features & Evaluation of Significance:**

Feature 1 is a one-room school house. Feature 2 is a one-room structure that may have been used as a residence at one point, and has possibly been used for other activities as well. Feature 3 is a fallen storage shed. Features 3 and 4 are privies on the eastern end of the school site. Based on professional judgement, the school site construction dates to the 1915-1930, and the site was likely used over multiple decades. Features 1 and 2 are in fair condition; Features 3 and 4 are in poor condition; Feature 3, a fallen shed, is almost destroyed. Feature 5 is discussed in the attached historical archaeological form. The cultural material scatter outside of the features is sparse and consists solely of the wooden beams and bricks.

The site lacks aspects of structural integrity. Spatial integrity is maintained, as there is no evidence the structures have ever been moved. The workmanship, materials, and design of the structures are not significant. The setting is very similar to what it would have been during active use of the site.

Site JUP-MKRWD14-201 is recommended unevaluated for the National Register of Historic Places. The site does not qualify for the NRHP under Criteria C or D, but a deeds search should be conducted to better understand the potential for the site to qualify for Criteria A or B, a significant event or person.

7. References/Comments:

Recorded By Kaelyn M. Olson Date Recorded 01/20/2016
(First Name & Last Name) (mm/dd/year)

NDCRS SITE FORM
ATTACHMENTS SECTION

Field Code: JUP-MKRWD14-201

SITS#: 32MZ



Figure 4: Overview of Feature 1, the schoolhouse, facing the western elevation and the entryway.



Figure 5: Overview of Feature 1 facing the southern elevation.

Recorded By Kaelyn M. Olson
(First Name & Last Name)

Date Recorded 01/20/2016
(mm/dd/year)

NDCRS SITE FORM
ATTACHMENTS SECTION

Field Code: JUP-MKRWD14-201

SITS#: 32MZ



Figure 6: Overview of Feature 1 facing the eastern elevation, including the metal tank, the cellar entrance, and the electrical wiring.



Figure 7: Overview of Feature 1 facing the northern elevation.

Recorded By Kaelyn M. Olson
(First Name & Last Name)

Date Recorded 01/20/2016
(mm/dd/year)

NDCRS SITE FORM
ATTACHMENTS SECTION

Field Code: JUP-MKRWD14-201

SITS#: 32MZ



Figure 8: Close up of the cellar entrance of Feature 1.



Figure 9: Overview of the interior of Feature 1, facing east.

Recorded By Kaelyn M. Olson
(First Name & Last Name)

Date Recorded 01/20/2016
(mm/dd/year)

NDCRS SITE FORM
ATTACHMENTS SECTION

Field Code: JUP-MKRWD14-201

SITS#: 32MZ



Figure 10: Overview of Feature 2, the residence, facing the western elevation.



Figure 11: Overview of Feature 2 facing the southern elevation. Feature 5, the collapsed shed, is visible on the right.

Recorded By Kaelyn M. Olson
(First Name & Last Name)

Date Recorded 01/20/2016
(mm/dd/year)

NDCRS SITE FORM
ATTACHMENTS SECTION

Field Code: JUP-MKRWD14-201

SITS#: 32MZ



Figure 12: Overview of Feature 2, facing the eastern elevation.




Figure 13: Overview of Feature 2, facing the northern elevation.

Recorded By Kaelyn M. Olson
(First Name & Last Name)

Date Recorded 01/20/2016
(mm/dd/year)

NDCRS SITE FORM
ATTACHMENTS SECTION

Field Code: JUP-MKRWD14-201

SITS#: 32MZ



Figure 14: Overview of the interior of Feature 2. Of note are the stove and the metal bed frame.



Figure 15: Close up view of the historic concrete foundation of Feature 2. The poorly sorted gravel of the concrete is consistent with Features 1, 2, and 5.

Recorded By Kaelyn M. Olson
(First Name & Last Name)

Date Recorded 01/20/2016
(mm/dd/year)