

NDCRS ARCHITECTURAL FORM

PAGE 1

UPDATE

Field Code Historic Elkhorn School

SITS# 32MZ 3004

Map Quad Lone Butte NW

Site Name Historic Elkhorn School

Map Quad \_\_\_\_\_

Site Name \_\_\_\_\_

LTL    T. 149 N., R. 98 W., Sec. 13 QQQ 6 of the QQ 6 of the Q 6

LTL    T.    N., R.    W., Sec.    QQQ    of the QQ    of the Q   

LTL    T.    N., R.    W., Sec.    QQQ    of the QQ    of the Q   

LTL    T.    N., R.    W., Sec.    QQQ    of the QQ    of the Q   

NAD 1983 UTM 5286647 Zone 13N

NAD 1983 UTM 638354

City: \_\_\_\_\_

Street Number: \_\_\_\_\_

Street Name: 120th Ave NW and 21st St NW

Urban Legal Description: \_\_\_\_\_

Total Number of Architectural Features: 1

Fieldwork Date: 8/18/2021

Reconnaissance Survey

Intensive Survey

Project & Principal Investigator:

Country School House Project  
Kathy Wilner  
366 43rd Ave SE  
Bowdon ND 58418

Contracting Firm or Agency Completing the Form:

Additional Information:

SHSND USE

Component \_\_\_\_\_ Study Unit \_\_\_\_\_ Verified Site \_\_\_\_\_ CR Type \_\_\_\_\_

Component \_\_\_\_\_

Component \_\_\_\_\_

Recorded By: Kathy Wilner Date Recorded: 10/30/2021

Form instructions: (1) Download; (2) Save A Copy; (3) Submit a paper copy of the form to the SHSND and upload the PDF version of the form and corresponding GIS shapefiles to the ND SHPO-run FTP site.

Subsection
1 = N½
2 = E½
3 = S½
4 = W½
5 = NE¼
6 = SE¼
7 = SW¼
8 = NW¼

NDCRS ARCHITECTURAL FORM  
PAGE 2 – Feature Data

Field Code Historic Elkhorn School SITS# 32 MZ 3004

Complete one Page 2 for each architectural feature at the site.

Architectural Feature # 1

Construction Date \_\_\_\_\_

Feature Date 1915-1930

Structural System Wood Frame

Original Owner's Ethnicity \_\_\_\_\_

Feature Type 9 - School; Church school

Context Education

Primary Exterior Wood, Horizontal Siding

Secondary Exterior \_\_\_\_\_

Condition Good

Plan Shape \_\_\_\_\_

Style Ethnic / Vernacular

Architect/Builder \_\_\_\_\_

Foundation Rocks and Bricks Stories 1

Roof/Cornice Gable

Window Covred

Dating Method(s) Previous documentation

Miscellaneous Information \_\_\_\_\_

**Feature Preservation Recommendation(s) (Check all that apply):**

- Individual nomination
- Contributes to a potential district
- No nomination potential
- Will not contribute to a district
- Potential district—feature would be a contributing element if other properties constitute a district
- Thematic nomination potential
- Component of a historic site or landscape
- Moved (specify all applicable choices)—a) relocation occurred within a historic period; b) recreates original site, orientation, landscape, and spatial relationships; c) compatible in context with neighboring structures; d) relocation has damaged eligibility
- Historical associations require further investigation

Recorded By: Kathy Wilner Date Recorded: 10/30/2021

**NDCRS ARCHITECTURAL FORM**  
**PAGE 3 – Feature Data**

**Field Code** Historic Elkhorn School

**SITS# 32** MZ 3004

**Complete one Page 3 for each architectural feature at the site.**

**1. Feature Description, Integrity, Eligibility:**

The feature has been documented and updated several times. The only change I see is in the deterioration of the paint.

**2. Owner's Contact Information:**

Kurt and Laura Johnsrud  
2003 120th Ave NW  
Watford City, ND 58854

**Recorded By:** Kathy Wilner **Date Recorded:** 10/30/2021

**NDCRS ARCHITECTURAL FORM**  
**PAGE 4 – Site Description****Field Code** Historic Elkhorn School**SITS# 32** MZ 30043. Site Area (ft<sup>2</sup>):

4. Description of Access and Site Setting:

From Highway 85 south of Watford City look for Co Rd 37 on the left (east). Take Co Rd 37 east about 7 3/4 miles to the junctions with 120th Ave NW. You will see the school on the left. The land around this school is tillable farm land and pasture. There is a farm to the east.

5. Summary of ALL Site Features and Evaluation of Significance:

6. References/Comments:

Kathy Wilner  
366 43rd Ave SE  
Bowdon ND 58418

**Recorded By:** Kathy Wilner **Date Recorded:** 10/30/2021

Form instructions: (1) Download; (2) Save A Copy; (3) Submit a paper copy of the form to the SHSND and upload the PDF version of the form and corresponding GIS shapefiles to the ND SHPO-run FTP site.



East Side

Historic Elkhorn School

8/18/2021

Kathy Wilner

MZ



North Side



West Side

Historic Elkhorn School

8/18/2021

Kathy Wilner

MZ

South Side





Imagery ©2021 Maxar Technologies, USDA Farm Service Agency, Map data ©2021 500 ft

Feature

**NDCRS ATTACHMENT SECTION**

**Field Code** \_\_\_\_\_

**SITS# 32**   MZ     3004  



Photo taken summer 2010 by SHSND intern Alicia Liebel

**Recorded By:**   Lorna Meidinger   **Date Recorded:**   11/17/2020



**NDCRS ATTACHMENT SECTION**

**Field Code** \_\_\_\_\_

**SITS# 32**   MZ     3004  



Photo taken summer 2010 by SHSND intern Alicia Liebel

**Recorded By:**   Lorna Meidinger   **Date Recorded:**   11/17/2020

**NDCRS ATTACHMENT SECTION**

**Field Code** \_\_\_\_\_

**SITS# 32**   MZ     3004  



Photo taken summer 2010 by SHSND intern Alicia Liebel

**Recorded By:**   Lorna Meidinger   **Date Recorded:**   11/17/2020

**NDCRS ATTACHMENT SECTION**

**Field Code** \_\_\_\_\_

**SITS# 32**   MZ     3004  



Photo taken summer 2010 by SHSND intern Alicia Liebel

**Recorded By:**   Lorna Meidinger   **Date Recorded:**   11/17/2020

**NDCRS ATTACHMENT SECTION**

**Field Code** \_\_\_\_\_

**SITS# 32**   MZ     3004  



Photo taken summer 2010 by SHSND intern Alicia Liebel

**Recorded By:**   Lorna Meidinger   **Date Recorded:**   11/17/2020

**NDCRS ATTACHMENT SECTION**

**Field Code** \_\_\_\_\_

**SITS# 32**   MZ     3004  



Photo taken summer 2010 by SHSND intern Alicia Liebel

**Recorded By:**   Lorna Meidinger   **Date Recorded:**   11/17/2020

**NDCRS ATTACHMENT SECTION**

**Field Code** \_\_\_\_\_

**SITS# 32**   MZ     3004  



Photo taken summer 2010 by SHSND intern Alicia Liebel

**Recorded By:**   Lorna Meidinger   **Date Recorded:**   11/17/2020

**NDCRS ATTACHMENT SECTION**

**Field Code** \_\_\_\_\_

**SITS# 32**   MZ   3004



Photo taken summer 2010 by SHSND intern Alicia Liebel

**Recorded By:** Lorna Meidinger      **Date Recorded:** 11/17/2020

# NDCRS ARCHITECTURAL SITE FORM

## PAGE 1

**UPDATE**

Field Code \_\_\_\_\_

SITS# 32 MZ 3004

### SITE IDENTIFICATION

Map Quad Lone Butte NW Site Name Historic Elkhorn

Map Quad \_\_\_\_\_ Site Name \_\_\_\_\_

LTL \_\_\_TWP 149 R 98 SEC 13 QQQ 6 QQ 6 Q 6

LTL \_\_\_TWP \_\_\_\_\_ R \_\_\_\_\_ SEC \_\_\_\_\_ QQQ \_\_\_\_\_ QQ \_\_\_\_\_ Q \_\_\_\_\_

LTL \_\_\_TWP \_\_\_\_\_ R \_\_\_\_\_ SEC \_\_\_\_\_ QQQ \_\_\_\_\_ QQ \_\_\_\_\_ Q \_\_\_\_\_

LTL \_\_\_TWP \_\_\_\_\_ R \_\_\_\_\_ SEC \_\_\_\_\_ QQQ \_\_\_\_\_ QQ \_\_\_\_\_ Q \_\_\_\_\_

NAD 1983, UTM \_\_\_\_\_ N ZONE 13N

NAD 1983, UTM \_\_\_\_\_ E

City: Watford City

Street Number: \_\_\_\_\_

Street Name: 120th Ave NW & 21st St NW

Urban Legal Description: \_\_\_\_\_

Subsection:
1 = N $\frac{1}{2}$
2 = E $\frac{1}{2}$
3 = S $\frac{1}{2}$
4 = W $\frac{1}{2}$
5 = NE $\frac{1}{4}$
6 = SE $\frac{1}{4}$
7 = SW $\frac{1}{4}$
8 = NW $\frac{1}{4}$

### SITE DATA

Total # **Architectural** Features: 1

Fieldwork Date: 05/07/2018

Reconnaissance Survey  Intensive Survey

Project & Principal Investigator:

McKenzie County Route 37, Wade Burns (PI)

Report Title & Author(s):

A Class I and Class III Intensive Cultural Resource Inventory for the McKenzie County Route 37 Road Improvements Project in McKenzie County, North Dakota  
by Brittany Brooks

Contracting firm or Agency completing the form:

Beaver Creek Archaeology, Inc.

Additional Information:

The historic Elkhorn School is located within the current survey area; however, it will not be impacted by the proposed project.

### SHSND USE

Area of Significance \_\_\_\_\_ Ecozone \_\_\_\_\_ Verified Site \_\_\_\_\_ CR Type \_\_\_\_\_

Area of Significance \_\_\_\_\_ Ecozone \_\_\_\_\_

Area of Significance \_\_\_\_\_ Ecozone \_\_\_\_\_

Recorded By Brittany Brooks Date Recorded 05/14/2018  
(First Name & Last Name) (mm/dd/year)



NDCRS ARCHITECTURAL SITE FORM
PAGE 2—Feature Data

UPDATE

Field Code \_\_\_\_\_

SITS# 32 MZ 3004

Complete one Page 2 for each architectural feature at the site.

Architectural Feature # 1

Construction Date \_\_\_\_\_ Feature Type 9 Condition 6
Feature Date 4 Context 7 Plan Shape 5
Structural System 25 Primary Exterior 26 Style Ethnic/Vernacular
Original Owner's Ethnicity \_\_\_\_\_ Secondary Exterior N/A Architect/Builder \_\_\_\_\_

Other Information: No Change

Foundation \_\_\_\_\_ Stories \_\_\_\_\_

Roof/Cornice \_\_\_\_\_

Window \_\_\_\_\_

Dating Method(s): \_\_\_\_\_

Feature Preservation Recommendation(s) (Check all that apply):

- Individual nomination
Contributes to a potential district
No nomination potential
Will not contribute to a district
Potential district—feature would be a contributing element if other properties constitute a district
Thematic nomination potential
Component of a historic site or landscape
Moved (specify all applicable choices)—a) relocation occurred within a historic period; b) recreates original site, orientation, landscape, & spatial relationships; c) compatible in context with neighboring structures; d) relocation has damaged eligibility
Historical associations require further investigation

Recorded By Brittany Brooks Date Recorded 05/14/2018
(First Name & Last Name) (mm/dd/year)

**NDCRS ARCHITECTURAL SITE FORM  
PAGE 3—Feature Data****UPDATE**

Field Code \_\_\_\_\_

SITS# 32 MZ 3004**Complete a Page 3 for each feature.****1. Feature Description, Integrity, Eligibility:**

Site 32MZ3004 was recorded in 2016 by C. Rohe and updated in 2017 by BCA. The site consisted of the historic Elkhorn School located in the corner of a hay field. The Elkhorn schoolhouse measured approximately 22' by 35' and had a concrete and stone foundation, wood framing, horizontal wood siding, and a gable roof covered with asphalt shingles. All the windows were covered. The site was in good condition and retained some aspects of integrity of location, design, setting, materials, feeling, and association. Site 32MZ3004 was recommended unevaluated for the NRHP, as further work is needed.

During the current inventory, no significant change was noted. Site 32MZ3004 is still recommended as unevaluated for the NRHP, as further work is necessary to understand the site's potential eligibility. The proposed road improvements would move McKenzie County Route 37 to the northwest side of the site. As the site consists of the historic Elkhorn School, an architectural structure, it will be avoided by the proposed project.

Recorded By Brittany Brooks Date Recorded 05/14/2018  
(First Name & Last Name) (mm/dd/year)



**Figure 1.** Site 32MZ3004, facing northeast.



**Figure 2.** Site 32MZ3004, facing northwest.



**Figure 3.** Site 32MZ3004, facing southeast.



**Figure 4.** Site 32MZ3004, facing southwest.

NDCRS ARCHITECTURAL SITE FORM

PAGE 1

UPDATE

Field Code \_\_\_\_\_

SITS# 32 MZ 3004

SITE IDENTIFICATION

Map Quad Lone Butte NE Site Name Historic Elkhorn School

Map Quad \_\_\_\_\_ Site Name \_\_\_\_\_

LTL \_\_\_TWP 149 R 98 SEC 13 QQQ 6 QQ 6 Q 6

LTL \_\_\_TWP \_\_\_\_\_ R \_\_\_\_\_ SEC \_\_\_\_\_ QQQ \_\_\_\_\_ QQ \_\_\_\_\_ Q \_\_\_\_\_

LTL \_\_\_TWP \_\_\_\_\_ R \_\_\_\_\_ SEC \_\_\_\_\_ QQQ \_\_\_\_\_ QQ \_\_\_\_\_ Q \_\_\_\_\_

LTL \_\_\_TWP \_\_\_\_\_ R \_\_\_\_\_ SEC \_\_\_\_\_ QQQ \_\_\_\_\_ QQ \_\_\_\_\_ Q \_\_\_\_\_

NAD 1983, UTM \_\_\_\_\_ N ZONE 13N

NAD 1983, UTM \_\_\_\_\_ E

City: Watford City

Street Number: \_\_\_\_\_

Street Name: 120th Ave NW & 21st St NW

Urban Legal Description: \_\_\_\_\_

Subsection:
1 = N1/2
2 = E1/2
3 = S1/2
4 = W1/2
5 = NE1/4
6 = SE1/4
7 = SW1/4
8 = NW1/4

SITE DATA

Total # Architectural Features: 1

Fieldwork Date: 11/14/2017

Reconnaissance Survey \_\_\_ Intensive Survey [checked]

Project & Principal Investigator:

AE2S Spring Creek Water Line; Principal Investigator: Wade Burns

Report Title & Author(s):

A Class I and Class III Intensive Cultural Resource Inventory of the Spring Creek Rural Water Line Project in Dunn and McKenzie Counties, North Dakota by Brittany Brooks

Contracting firm or Agency completing the form:

Beaver Creek Archaeology, Inc.

Additional Information:

The historic Elkhorn School is located within the current survey area; however, it will not be impacted by the proposed project.

SHSND USE

Area of Significance \_\_\_\_\_ Ecozone \_\_\_\_\_ Verified Site \_\_\_\_\_ CR Type \_\_\_\_\_

Area of Significance \_\_\_\_\_ Ecozone \_\_\_\_\_

Area of Significance \_\_\_\_\_ Ecozone \_\_\_\_\_

Recorded By Brittany Brooks Date Recorded 01/26/2018
(First Name & Last Name) (mm/dd/year)

NDCRS ARCHITECTURAL SITE FORM
PAGE 2—Feature Data

UPDATE

Field Code \_\_\_\_\_

SITS# 32 MZ 3004

Complete one Page 2 for each architectural feature at the site.

Architectural Feature # 1

Construction Date \_\_\_\_\_ Feature Type 9 Condition 6
Feature Date 4 Context 7 Plan Shape 5
Structural System 25 Primary Exterior 26 Style Ethnic/Vernacular
Original Owner's Ethnicity \_\_\_\_\_ Secondary Exterior N/A Architect/Builder \_\_\_\_\_

Other Information: No Change

Foundation \_\_\_\_\_ Stories \_\_\_\_\_

Roof/Cornice \_\_\_\_\_

Window \_\_\_\_\_

Dating Method(s): \_\_\_\_\_

Feature Preservation Recommendation(s) (Check all that apply):

- Individual nomination
Contributes to a potential district
No nomination potential
Will not contribute to a district
Potential district—feature would be a contributing element if other properties constitute a district
Thematic nomination potential
Component of a historic site or landscape
Moved (specify all applicable choices)—a) relocation occurred within a historic period; b) recreates original site, orientation, landscape, & spatial relationships; c) compatible in context with neighboring structures; d) relocation has damaged eligibility
Historical associations require further investigation

Recorded By Brittany Brooks Date Recorded 01/26/2018
(First Name & Last Name) (mm/dd/year)

## 32MZ3004

**Site 32MZ3004** was recorded in 2016 by C. Rohe and consisted of the historic Elkhorn School located in the corner of a hay field. The Elkhorn schoolhouse measured approximately 22 ft by 35 ft and had a concrete and stone foundation, wood framing, horizontal wood siding, and a gable roof covered with asphalt shingles. All the windows were covered. The site was in good condition and retains some aspects of integrity of location, design, setting, materials, feeling, and association. Site 32MZ3004 was recommended unevaluated for the NRHP, as further work is needed.

During the current inventory, no significant change was noted. Site 32MZ3004 is still recommended as unevaluated for the NRHP, as further work is necessary to understand the site's potential eligibility.



**Figure 1:** Site 32MZ3004 overview, looking to the northwest.



**Figure 2:** Site 32MZ3004 overview, looking to the west.



NDCRS ARCHITECTURAL SITE FORM
PAGE 1

Field Code JUP-WAWSP-104

SITS# 32 MZ 3004

SITE IDENTIFICATION

Map Quad Lone Butte NW Site Name Historic Elkhorn School
Map Quad Site Name

LTL TWP 149 R 98 SEC 13 QQQ 6 QQ 6 Q 6
LTL TWP R SEC QQQ QQ Q
LTL TWP R SEC QQQ QQ Q
LTL TWP R SEC QQQ QQ Q

NAD 1983, UTM 5286647 N ZONE 13N
NAD 1983, UTM 638354 E

Subsection:
1 = N 1/2
2 = E 1/2
3 = S 1/2
4 = W 1/2
5 = NE 1/4
6 = SE 1/4
7 = SW 1/4
8 = NW 1/4

City: Watford

Street Number:

Street Name: 120th Ave NW and 21st St NW

Urban Legal Description:

SITE DATA

Total # Architectural Features: 1

Fieldwork Date: 07/26/2014

Reconnaissance Survey Intensive Survey [checked]

Project & Principal Investigator:

WAWSP 2014, John G. Morrison

Report Title & Author(s):

System I Expansion Tobacco Garden Area Water Supply Project: Class III Cultural Resource Inventory, McKenzie County, North Dakota. --Chris M. Rohe

Contracting firm or Agency completing the form:

Juniper, LLC

Additional Information:

Elkhorn School

SHSND USE

Area of Significance 2 Ecozone 22 Verified Site 1 CR Type 2
Area of Significance Ecozone
Area of Significance Ecozone

Recorded By Chris Rohe Date Recorded 02/02/2016
(First Name & Last Name) (mm/dd/year)

Instructions to complete a digital version of this form: (1) Download a copy; (2) Open the saved blank copy; (3) Fill out the form; (4) Use the Save As command to rename the form appropriately, and save; (5) Print and submit to SHSND.

### NDCRS ARCHITECTURAL SITE FORM PAGE 2—Feature Data

Field Code JUP-WAWSP-104

SITS# 32 MZ

Complete one Page 2 for each architectural feature at the site.

Architectural Feature # 1

Construction Date \_\_\_\_\_

Feature Type 9

Condition 6

Feature Date 4

Context 7

Plan Shape 5

Structural System 25

Primary Exterior 26

Style Ethnic/Vernacular

Original Owner's Ethnicity \_\_\_\_\_

Secondary Exterior N/A

Architect/Builder \_\_\_\_\_

Other Information: \_\_\_\_\_

Foundation Concrete and stone Stories 1.0

Roof/Cornice Gable roof with a hip on the eastern edge

Window All boarded, 2 on eastern wall, 5 on the southern wall, a boarded transom

Dating Method(s): Professional estimate

**Feature Preservation Recommendation(s) (Check all that apply):**

- Individual nomination
  - Contributes to a potential district
  - No nomination potential
  - Will not contribute to a district
  - Potential district—feature would be a contributing element if other properties constitute a district
  - Thematic nomination potential
  - Component of a historic site or landscape
- Moved (specify all applicable choices)—a) relocation occurred within a historic period; b) recreates original site, orientation, landscape, & spatial relationships; c) compatible in context with neighboring structures; d) relocation has damaged eligibility
- Historical associations require further investigation

Recorded By Chris Rohe Date Recorded 02/02/2016  
(First Name & Last Name) (mm/dd/year)

Instructions to complete a digital version of this form: (1) Download a copy; (2) Open the saved blank copy; (3) Fill out the form; (4) Use the Save As command to rename the form appropriately, and save; (5) **Print** and submit to SHSND.

**NDCRS ARCHITECTURAL SITE FORM  
PAGE 3—Feature Data**

Field Code JUP-WAWSP-104

SITS# 32 MZ

**Complete a Page 3 for each feature.**

**1. Feature Description, Integrity, Eligibility:**

This sites is the Elkhorn School Building. The building has a gable roof with a hip on the eastern end that is shaped like a shelf. An initial review of this form by <sup>Lorna Meisinger</sup> Amy Bleier of the SHSND in 2016 noted that the vent decoration and accommodating roof structure are unique (Figures 4 and 7). The structure measures approximately 22 feet (N-S) and 35 feet (E-W). A concrete stoop extends off the eastern edge from the door and is approximately 5 feet (N-S) and 6 feet (E-W). There are two steps leading up to the door. The stoop is poured concrete while the school itself is sitting on rock and concrete footings. The structure itself is of wood clapboard construction. There is one boarded window on each side of the doorway, and there is a boarded transom and wiring for a transom light above the door. The door for the entrance is not original; it has been replaced with a modern six-panel door replaced that is painted a fresh, glossy white. The whole school is a flat white color, and the paint is deteriorating on each side of the structure. The north and west walls have no windows or openings while the south wall has a large 5 section window that measures approximately 6 feet in height by 15 feet (E-W). There is a light fixture near the door way and cut conduit noticed in the walls showing that the structure once had electricity.

The condition of the building is good and it retains some aspects of integrity of location, design, setting, materials, feeling, and association. Although its physical integrity has been impacted by weathering, alteration, animal burrowing and nesting. The overall structure appears to still be structurally sound.

Site JUP-WAWSP-104 has limited integrity, and it is unlikely that the site could meet the criteria for the National Register of Historic Places under Criterion D; however the unique hip vent construction above the east entrance is unique for one room schools of this period and location, and therefore may qualify under Criterion C. Further work is necessary to better understand the eligibility of the site under Criteria A and B. Site JUP-WAWSP-104 is currently unevaluated for the NRHP pending further work.

Recorded By Chris Rohe Date Recorded 02/02/2016  
(First Name & Last Name) (mm/dd/year)

*Instructions to complete a digital version of this form: (1) Download a copy; (2) Open the saved blank copy; (3) Fill out the form; (4) Use the Save As command to rename the form appropriately, and save; (5) **Print** and submit to SHSND.*

**NDCRS ARCHITECTURAL SITE FORM  
PAGE 4—SITE DESCRIPTION**Field Code JUP-WAWSP-104SITS# 32 MZ**Complete one Page 4 for the entire site.**

## 2. Owner's Contact Information:

Private

## 3. Access (to rural areas):

From Watford City take Main St. South for 2.4 miles and turn right onto ND-23 for 0.5 miles. Turn left onto US-85 for 3.3 miles to Co Rd 37. Turn left onto Co. Rd. 37 for 7.8 miles and turn left at the 4 way intersection of Co. Rd. 37, 21 St. NW, and 120 Ave. NW and the school will be on the left.

4. Site Area (ft<sup>2</sup>): 4,2105. Description of **SETTING**:

The school is located in the corner of a utilized hay field that is generally flat with some sloping buttes in the distance. There is a dirt 4-way intersection (120th Ave NW and 21st St NW) just 200 feet to the southeast.

Recorded By Chris Rohe Date Recorded 02/02/2016  
(First Name & Last Name) (mm/dd/year)

*Instructions to complete a digital version of this form:* (1) Download a copy; (2) Open the saved blank copy; (3) Fill out the form; (4) Use the Save As command to rename the form appropriately, and save; (5) **Print** and submit to SHSND.

**NDCRS ARCHITECTURAL SITE FORM  
PAGE 5—SITE DESCRIPTION**Field Code JUP-WAWSP-104SITS# 32 MZ**6. Summary of ALL Site Features & Evaluation of Significance:**

Site JUP-WAWSP-104 consists of the Elkhorn Schoolhouse. The school matches the style of many other contemporary, rural one-room school houses in North Dakota. The hip and decorated vent on the eastern face of the building may be a relatively unique feature. The school has likely been altered over time, such as with electricity, but it is unclear if the style and roof have any significance under Criterion C.

Site JUP-WAWSP-104 has limited integrity, and it is unlikely that the site could meet the criteria for the National Register of Historic Places under Criterion D. Further work is necessary to better understand the eligibility of the site under Criteria A, B, and C. Site JUP-WAWSP-104 is currently unevaluated for the NRHP pending further work.

**7. References/Comments:**

Recorded By Chris Rohe Date Recorded 02/02/2016  
(First Name & Last Name) (mm/dd/year)

*Instructions to complete a digital version of this form:* (1) Download a copy; (2) Open the saved blank copy; (3) Fill out the form; (4) Use the Save As command to rename the form appropriately, and save; (5) **Print** and submit to SHSND.

NDCRS SITE FORM  
ATTACHMENTS SECTION

Field Code: JUP-WAWSP-104

SITS#: 32MZ



Figure 4: Overview of structure facing northwest. The decorated vent and the hip of the roof noted by Amy Bleier in 2016 are in the foreground.



Figure 5: Overview of the schoolhouse, facing northeast.

Recorded By Chris Rohe  
(First Name & Last Name)

Date Recorded 02/02/2016  
(mm/dd/year)

NDCRS SITE FORM  
ATTACHMENTS SECTION

Field Code: JUP-WAWSP-104

SITS#: 32MZ



Figure 6: Overview of schoolhouse facing southeast.



Figure 7: Close up the ventilation window below the hip and above the entrance to the schoolhouse. Review by Bleier in 2016 indicated that this type of vent is relatively unique.

Recorded By Chris Rohe  
(First Name & Last Name)

Date Recorded 02/02/2016  
(mm/dd/year)

NDCRS SITE FORM  
ATTACHMENTS SECTION

Field Code: JUP-WAWSP-104

SITS#: 32MZ



Figure 8: Close up of the south wall and the five windows, now containing sheet metal, that form one continuous portal.



Figure 9: Close up of conduit showing that the schoolhouse had electricity at one point.

Recorded By Chris Rohe  
(First Name & Last Name)

Date Recorded 02/02/2016  
(mm/dd/year)



NDCRS SITE FORM  
ATTACHMENTS SECTION

Field Code: JUP-WAWSP-104

SITS#: 32MZ



Figure 10: Close up of the stone and concrete footings for the structure.



Figure 11: Close up of the main entrance (east side) showing that the door appears to have been painted or replaced recently, and two replaced windows.

Recorded By Chris Rohe  
(First Name & Last Name)

Date Recorded 02/02/2016  
(mm/dd/year)