### NDCRS ARCHITECTURAL FORM

PAGE 1 UPDATE ♥

Field Code Charbonn	neau School		S	SITS# 32MZ	X106	
Map Quad Charbonneau		Site	Name Charb	onneau School		
Map Quad Charbonneau Map Quad		Site				
LTL T151_ N., R.  LTL T N., R.  LTL T N., R.  LTL T N., R.  NAD1983 UTM  NAD1983 UTM  City:  Street Number:	102 W., Sec. 32 W., Sec. W., Sec. 5300730 592545	QQQ or QQQ or QQQ or QQQ or Zone13N	f the QQ 8 f the QQ f the QQ f the QQ	_ of the <b>Q</b> <u>6</u> _ of the <b>Q</b> _ of the <b>Q</b>	Subsection 1 = N½	¥
Street Name:148th A	ve NW					
Urban Legal Description	1:					
Total Number of <b>Archite</b>		1				
Fieldwork Date:8	3/18/2021					
Reconnaissance Survey	, <u> </u>	Intensive Su	ırvey			
Project & Principal Investigation Country School House F Kathy Wilner 366 43rd Ave SE Bowdon ND 58418	_					
Contracting Firm or Age	ency Completing the F	orm:				
Additional Information:						
SHSND USE Component Component Component	_ Study Unit	Verified	Site	_ CR Type		
Recorded By:	Kathy Wilne	er	Date P	ecorded- 10/	31/2021	

Form instructions: (1) Download; (2) Save A Copy; (3) Submit a paper copy of the form to the SHSND and upload the PDF version of the form and corresponding GIS shapefiles to the ND SHPO-run FTP site.

#### NDCRS ARCHITECTURAL FORM PAGE 2 – Feature Data

Field Code Charbon	neau School	SITS# 32	<u>IVIZ</u> X 100
Complete one Page 2 f	or each architectural featu	re at the site.	
Architectural Feature # _	14		
Construction Date	<del></del>		
Feature Date <u>1900-1</u>	915		
Structural System Wo	ood Frame		
Original Owner's Ethnici	ty		
Feature Type 9 - Schoo	l; Church school		
Context <u>Education</u>			
Primary Exterior Woo	od, Horizontal Siding		
Condition Fair			
Plan Shape Rectand			
- 0			
	crete		
Roof/Cornice Hip			
	penings, no glass and little framir		
Dating Method(s) Estin			
			=
	Recommendation(s) (Checletion	k all that apply):	
Individual nomina Contributes to a			
No nomination p			
Will not contribut			
<del></del>		uting element if other proper	ties constitute a district
Thematic nomina			
Component of a	historic site or landscape		
site, orientation,	• • • • • • • • • • • • • • • • • • • •		storic period; b) recreates original ntext with neighboring structures; d)
	ations require further investi	gation	
Recorded By:	Kathy Wilner	Date Recorded	l: 10/31/2021

## NDCRS ARCHITECTURAL FORM PAGE 3 – Feature Data

Field Code Charbonneau School	SITS# 32 MZ X106

Complete one Page 3 for each architectural feature at the site.

1. Feature Description, Integrity, Eligibility:

The feature is a large, two room prairie school on a poured concrete basement. The school served the small village of Charbonneau. The hip roof of the school has remnants of both asphalt shingles and wood shakes with horizontal slats visible. Metal capping with finials can be seen at the peak of the roof with remnants on the ribs of the roof. There are holes in the roof. The soffits were closed at construction but today much of that is failing. There is a red brick chimney at the south end of the west slope. The building measures 36 feet east to west and 45 feet north to south.

The siding begins with a rake board under the eaves on all four sides of the school. The remainder of the siding is 6 inch wood lap with 6 inch corner trim finished with waterboard. A large concrete porch is seen on the west side of the school with concrete steps leading up to it. The west wall has two door openings with small window openings to either side of each door. The door's lead into separate coatrooms. Each has shelving along the center wall with remnants of doors made from beadboard. There is a stairway leading down into the basement from one of the entries. There are door openings (one has a 5 panel wood door) leading from the coatrooms into each half of the school. A bank of 7 double hung window openings is located on both the north and south sides. There is no glass an little framing. The walls and ceiling were finished with lathe and plaster and much of the plaster is laying on the floor. The wall in one of the coat rooms has wainscot. Blackboards are gone. The floor is hardwood. There is a large opening between the two rooms with partial walls to the north and south and folding doors. One of the 5 panel doors is left. The basement is dirt with concrete shoring up the walls. Light fixtures would indicate the presence of electricity once upon a time.

 Owner's Contact Information: Safely Family Trust; First National Bank and Trust - Trustee PO Box 1827 Williston ND 58802

Recorded By: _	Kathy Wilner	Date Recorded: 10/31/2021
_		

## NDCRS ARCHITECTURAL FORM PAGE 4 – Site Description

Field Code Charbonnea	au School	SITS#	32 MZ X106	
3. Site Area (ft²):				
4. Description of Access a This building sits to the oil well pad to the so farm fields all direction	he south of the town site utheast and the abondor	of Charbonneau on anded buildings of the	a slight rise. There is and village to the north with	n
5. Summary of ALL Site F	eatures and Evaluation of S	ignificance:		
6. References/Comments: Kathy Wilner 366 43rd Ave SE Bowdon ND 58418				
Recorded By:	Kathy Wilner	Date Record	led: 10/31/2021	





North Side

Charbonneau School 8/18/2021 Kathy Wilner

ΜZ

#### West Side





South Side

Charbonneau School

8/18/2021

Kathy Wilner

MZ

East Side

Photo courtesy of Peter Herman





Imagery ©2021 Maxar Technologies, USDA Farm Service Agency, Map data ©2021 200 ft

**Feature** 



# NDCRS ARCHITECTURAL SITE FORM PAGE 1

**UPDATE** 

SITS# 32 MZ X106

SITE IDENTIFICATION				
Field Code			of Charbonneau	
Map Quad Charbonneau Map Quad		iame		
LTL TWP R SEC LTL TWP R SEC	C C C C	QQQ	QQ 8 OO QQ QQ	Q <u>6</u> Q Q
UTM 5300730 N UTM 592545 E			NAD 1983 <u>✓</u>	Subsection: 1 = N½ 2 = E½ 3 = S½
Street Number:  Street Name:  Lirban Legal Description:				4 = W½ 5 = NE¼ 6 = SE¼ 7 = SW¼ 8 = NW¼
Urban Legal Description:				
SITE DATA				
Total # Architectural Features:				
Fieldwork Date: 7/14/2014				
Reconnaissance Survey Inte	ensive Sun	vey <u></u>		
Project Title & Supervisor:  ND3214016 Alexander Rural Buried Cables Andrea F. Behan  Report Title & Author(s):	s Exchange	•		
Class II and III Cultural Resources Inventor	-	•	one Cooperative	Alexander Rural
Exchange T3.0 BER Buried Cables Project,	, by Andrea	a F. Behan		
Additional Information:				
SHSND USE Area of Significance		erified Site on-Site	_ СК Туре	
Recorded By Andrea F. Behan 8	Steve I	Hunt Date	Recorded	7/14/2014
(First Name & Last Name)				(mm/dd/year)

Instructions to complete a digital version of this form: (1) Download a copy to your hard drive; (2) Open the saved blank copy; (3) Fill out the form; (4) Use the Save As command to rename the form appropriately and save; (5) *Print* and submit to SHSND.

## NDCRS ARCHITECTURAL SITE FORM PAGE 2—Feature Data

UPDATE

(mm/dd/year)

Field Code N/A		SITS# 32_MZ X106
Complete one Page 2 <u>for ea</u>	ach architectural feature	at the site.
Architectural Feature #14		
Construction Date	Feature Type9	Condition 5
Feature Date <u>3</u>	Context 7	Plan Shape 5
Structural System 25	Primary Exterior 26	Style Hipped Roof Box
Original Owner's Ethnicity	Secondary Exterior	Architect/Builder
Other Information: <del>paint is almost c</del>	completely weathered away, rem	nains suggest it was white
Foundation concrete		Stories 1
Roof/Cornice hipped roof		
-	dows on the north side of the bu	iilding
	oon after the town was establish	ned
Dating Method(s): it is likely built so	,	
Dating Method(s): it is likely built so	,	
Dating Method(s): it is likely built so  Feature Preservation Recomn  Individual nomination	nendation(s) (Check all that	
Pating Method(s): it is likely built so  Feature Preservation Recomm  Individual nomination  Contributes to a potential description	nendation(s) (Check all that	
Pating Method(s): it is likely built so reature Preservation Recommunication Individual nomination Contributes to a potential decomposition No nomination potential	nendation(s) (Check all that	
Pating Method(s): it is likely built so pating Method(s): it is likely built so pating Method(s): it is likely built so permitted in the pating Method(s): it is likely built so permitted. It is likely built so pating Method(s): it is likely built so pating Method(s): it is likely built so permitted. It is likely built so pating Method(s): it is likely built so pa	nendation(s) (Check all that	t apply):
Pating Method(s): it is likely built so pating Method(s): it is likely built so pating Method(s): it is likely built so permitted in the pating Method(s): it is likely built so permitted. It is likely built so pating Method(s): it is likely built so permitted. It is likely built so permitted in the pating Method(s): it is likely built so permitted. It is likely built so permitted in the pating Method(s): it is likely built so permitted in the pating Method(s): it is likely built so permitted in the pating Method(s): it is likely built so permitted in the pating Method(s): it is likely built so permitted in the pating Method(s): it is likely built so permitted in the pating Method(s): it is likely built so permitted in the pating Method(s): it is likely built so permitted in the pating Method(s): it is likely built so permitted in the pating Method in the pa	nendation(s) (Check all that	
Pating Method(s): it is likely built so pating Method(s): it is likely built so pating Method(s): it is likely built so permitted in the pating Method(s): it is likely built so permitted. It is likely built so pating Method(s): it is likely built so pating Method(s): it is likely built so permitted. It is likely built so pating Method(s): it is likely built so pa	nendation(s) (Check all that district rict vould be a contributing element	t apply):
Potential district—feature will set on the potential district—feature will set on the potential district—feature will not contribute to a district — feature will not	nendation(s) (Check all that district rict vould be a contributing element	t apply):
Contributes to a potential d  ✓ No nomination potential  ✓ Will not contribute to a distr  Potential district—feature w  Thematic nomination poten  ✓ Component of a historic site  Moved (specify all applicable recreates original site, orier	nendation(s) (Check all that district vould be a contributing element ntial de or landscape ole choices)—a) relocation occur	t apply):  if other properties constitute a districular and the context of the context apply in the context apply

Instructions to complete a digital version of this form: (1) Download a copy to your hard drive; (2) Open the saved blank copy; (3) Fill out the form; (4) Use the Save As command to rename the form appropriately and save; (5) Print and submit to SHSND.

(First Name & Last Name)

**UPDATE** 

## NDCRS ARCHITECTURAL SITE FORM PAGE 3—Feature Data

Field Code N/A SITS# 32 MZ X106

#### 1. Feature Description, Integrity, Eligibility:

Feature 14 is located at the southern boundary of the town of Charbonneau. It is 40' x 50' with a hipped roof and vertical wood siding. It is highly weathered but paint remnants suggest it was white. It has a row of seven windows on the northeast wall and a chimney on the northwest side. Its location and layout suggest it was not residential and may have been a schoolhouse, town-hall or some other type of public meeting place. Due to the deteriorated condition which is a result of neglect, this structure has lost most of its historic integrity and should be considered non-contributing to the town site of Charbonneau and not eligible for the National Register of Historic Places.


Recorded By Andrea F. Behan & Steve Hunt
(First Name & Last Name)

Date Recorded

7/14/2014

(Name)


(mm/dd/year)



View of feature 14 facing southwest. A. Behan 07/14/2014.



Overview of the site from feature 14. A. Behan 07/14/2014.



View facing west of feature 15. A. Behan 07/14/2014.



View facing southwest of feature 15. A. Behan 07/14/2014.

### NDCRS SITE FORM HISTORICAL ARCHEOLOGICAL SITES

SITS# 32 MZ X0106 State County Site Number **CHARBONNEAU** Field Code Site Name Site Name Field Code Map Quad Map Quad 1. N 1/2 QQQ 0 Section 32 QQ 8 Q LTL 0 Range 102 Twp 151 2. E 1/2 3. S 1/2 4. W 1/2 5. NE 1/4 6. SE 1/4 7. SW 1/4 8. NW 1/4 9. C **CULTURAL MATERIAL FEATURE TYPE** SiteType 0 Bone 1 **CM Scatter** 0 Ceramics Chimney Context Depression 0 Charcoal 1 0 Cloth 0 SiteArea Dump 0 0 **Faunal Remains** Earthworks 0 m. x m. Fire Cracked Rock Fortification 0 Cultural Depth cm. Floral Remains 1 Foundation 0 Graves 0 Glass Depth Indicator 0 0 Hide, Hair, Fur Hearth 0 Occupation Date **Human Remains** 0 Machinery Begin End Masonry 0 Quarry/Mine 0 0 0 Rock Art 0 Metal Trail 0 **Plastic** Basis for Dating 0 Rubber Wreck 0 0 0 Shell Other **CM** Density 0 Wood 0 Other Isolated Find Slope/Exposure **Ecosystem** Landform 1 Landform 2 Slope/Exposure **Ecosystem** Landform 1 Landform 2 View, View, Elevation: **Drainage System** Degree Distance YELLOWSTONE RIVER 0 m. Dist Perm Water **Dist Seas Water** Seas Water Type Perm Water Type 0 m. 0 m. Ownership Ownership Fieldwork Date Fieldwork Date Collection Test/Probe Excavation Site Condition Management Recommendation Additional Information TWETON REAP

3 Area Signif

0 Non-Site

National Register

Area Signif

3 ECF

3 TF

E BENSON Coder

2/14/1980 DateCoded

Update

0 Soils

0 Soils

22 Ecozone

1 CR Type 0 Verified Site

State Registry

Ecozone