

NDCRS ATTACHMENT SECTION

Field Code _____

SITS# 32 MZ x1473



Photo taken summer 2010 by SHSND intern Alicia Liebel

Recorded By: Lorna Meidinger **Date Recorded:** 11/17/2020

NDCRS ATTACHMENT SECTION

Field Code _____

SITS# 32 MZ x1473



Photo taken summer 2010 by SHSND intern Alicia Liebel

Recorded By: Lorna Meidinger **Date Recorded:** 11/17/2020

NDCRS ATTACHMENT SECTION

Field Code _____

SITS# 32 MZ x1473



Photo taken summer 2010 by SHSND intern Alicia Liebel

Recorded By: Lorna Meidinger **Date Recorded:** 11/17/2020

Form instructions: (1) Download; (2) Save A Copy; (3) Submit a paper copy of the form to the SHSND *and* upload the PDF version of the form and corresponding GIS shapefiles to the ND SHPO-run FTP site.

NDCRS ATTACHMENT SECTION

Field Code _____

SITS# 32 MZ x1473



Photo taken summer 2010 by SHSND intern Alicia Liebel

Recorded By: Lorna Meidinger **Date Recorded:** 11/17/2020

NDCRS ARCHITECTURAL SITE FORM PAGE 1

SITS# 32 MZ X 1473

SITE IDENTIFICATION

Field Code MAC-NKL-60x Site Name _____
Site Name _____

Map Quad Figure 4 Ranch
Map Quad _____

LTL ___ TWP 149 R 95 SEC 20 QQQ 7 QQ 7 Q 6
LTL ___ TWP _____ R _____ SEC _____ QQQ _____ QQ _____ Q _____
LTL ___ TWP _____ R _____ SEC _____ QQQ _____ QQ _____ Q _____
LTL ___ TWP _____ R _____ SEC _____ QQQ _____ QQ _____ Q _____

UTM 5285584 N ZONE 13N
UTM 660104 E NAD 1927 ___ NAD 1983

Subsection:
1 = N½
2 = E½
3 = S½
4 = W½
5 = NE¼
6 = SE¼
7 = SW¼
8 = NW¼

City: _____
Street Number: _____
Street Name: _____
Urban Legal Description: _____

SITE DATA

Total # *Architectural* Features: 3

Fieldwork Date: 10/20/2014

Reconnaissance Survey Intensive Survey _____

Project Title & Supervisor:
Project Title: Basin Electric- North Killdeer Loop
Supervisor: Emily Sakariassen

Report Title & Author(s):
Report Title: Visual and Historic Sensitivity Analysis for Proposed North Killdeer Loop (NKL) Transmission Project
Author: Emily Sakariassen

Additional Information: Site lead: One schoolhouse, one trailer, and one historic house.

SHSND USE
Area of Significance 2 Ecozone 22 Verified Site 1 CR Type 1
Area of Significance _____ Ecozone _____ Non-Site _____
Area of Significance _____

Recorded By C. Carlson and E. Sakariassen Date Recorded 10/20/2014
(First Name & Last Name) (mm/dd/year)

Instructions to complete a digital version of this form: (1) Download a copy to your hard drive; (2) Open the saved blank copy; (3) Fill out the form; (4) Use the Save As command to rename the form appropriately and save; (5) Print and submit to SHSND.

NDCRS ARCHITECTURAL SITE FORM
PAGE 2—Feature Data

Field Code MAC-NKL-60xSITS# 32 MZ

Complete one Page 2 for each architectural feature at the site.

Architectural Feature # 1

Construction Date _____

Feature Type 9Condition 5Feature Date 5Context 30Plan Shape 5Structural System 25Primary Exterior 26Style Other Style

Original Owner's Ethnicity _____

Secondary Exterior _____

Architect/Builder _____

Other Information:

Foundation Cinder blocks Stories 1Roof/Cornice Front-gabled; interlocking asphalt shinglesWindow Original openings intact; some glass missingDating Method(s): Professional estimate

Feature Preservation Recommendation(s) (Check all that apply):

 Individual nomination Contributes to a potential district No nomination potential Will not contribute to a district Potential district—feature would be a contributing element if other properties constitute a district Thematic nomination potential Component of a historic site or landscape

Moved (specify all applicable choices)—a) relocation occurred within a historic period; b) recreates original site, orientation, landscape, & spatial relationships; c) compatible in context with neighboring structures; d) relocation has damaged eligibility

 Historical associations require further investigation

Recorded By C. Carlson and E. Sakariassen Date Recorded 10/20/2014
 (First Name & Last Name) (mm/dd/year)

Instructions to complete a digital version of this form: (1) Download a copy to your hard drive; (2) Open the saved blank copy; (3) Fill out the form; (4) Use the Save As command to rename the form appropriately and save; (5) Print and submit to SHSND.

NDCRS ARCHITECTURAL SITE FORM
PAGE 3—Feature DataField Code MAC-NKL-60xSITS# 32 MZ**Complete a Page 3 for each feature.****1. Feature Description, Integrity, Eligibility:**

DESCRIPTION: Feature 1 is a one-room schoolhouse. It has horizontal wood clapboard siding, originally painted white, though the paint has mostly faded. The structure has a front-gabled roof with cornice returns, and interlocking gray asphalt shingles. There is a brick chimney located at the west end of the roof. Part of the cornice is missing on the south facade. A bank of six double-hung windows is located on the south facade. Glass is missing in most windows, leaving only two extant, while a two-over-two storm window is present over one of the center windows. The primary entrance, located on the east facade, is a wooden door with a two-light transom above. One large single-hung window, missing its top pane, is located south of this door. Another opening, north of the door, has been boarded up. A rusted louvered vent is located beneath the roof apex on this facade. Electrical hook-ups are present on the east facade. No fenestration is present on the north facade. Original wood shingles are still present on the north half of the roof, while the south half has asphalt shingles. No fenestration is present on the west facade. The wood siding is coming off on this facade, and the paint is almost completely faded. Wood shingles are still present on the eave returns on the west facade. The lathe is exposed on the interior of the structure, and tongue-and-groove wainscotting is visible.

INTEGRITY: Feature 1 is in fair condition, and retains integrity of design, workmanship, and feeling. Integrity of location and setting are lost due to the fact that the structure was moved here from its original location. Integrity of materials is reduced by the loss of and boarding up of windows, loss of shingles, and the structure's general deterioration.

ELIGIBILITY: Feature 1 has not been evaluated for eligibility to the National Register of Historic Places. Current survey data are not sufficient to determine significance. Until a deed search can be performed, avoidance is recommended.

Recorded By C. Carlson and E. Sakariassen Date Recorded 10/20/2014
(First Name & Last Name) (mm/dd/year)

Instructions to complete a digital version of this form: (1) Download a copy to your hard drive; (2) Open the saved blank copy; (3) Fill out the form; (4) Use the Save As command to rename the form appropriately and save; (5) Print and submit to SHSND.

**NDCRS ARCHITECTURAL SITE FORM
PAGE 4—SITE DESCRIPTION**Field Code MAC-NKL-60xSITS# 32 MZ**Complete one Page 4 for the entire site.**

2. Owner's Contact Information:

Private

3. Access (to rural areas):

From the center of Watford City, travel north on Main St. N for .2 miles. Turn right onto ND-23 E/4th Ave NE, and travel east for 3.2 miles. Turn left to stay on ND-23 E, and follow for 12.8 miles. Continue straight onto ND-73 E, and travel east for 3.9 miles. Turn right. The site lead is located south of the road.

4. Site Area (ft²): 17,9095. Description of **SETTING**:

This site lead is located on flat terrain, though a steep ravine runs roughly east-west along the north edge of the property, beyond a barbed-wire fence. Hills rise to the north and south. A corral and associated grazing grounds lie to the east.

Recorded By C. Carlson and E. Sakariassen Date Recorded 10/20/2014
(First Name & Last Name) (mm/dd/year)

Instructions to complete a digital version of this form: (1) Download a copy to your hard drive; (2) Open the saved blank copy; (3) Fill out the form; (4) Use the Save As command to rename the form appropriately and save; (5) *Print* and submit to SHSND.

**NDCRS ARCHITECTURAL SITE FORM
PAGE 5—SITE DESCRIPTION**Field Code MAC-NKL-60xSITS# 32 MZ**6. Summary of ALL Site Features & Evaluation of Significance:**

Site MAC-NKL-60x consists of three features. Feature 1 is a schoolhouse in fair condition, moved here from its original location and set upon a cinder block foundation. Feature 2 is a modern trailer house which exhibits several modifications, including a wood porch and changes to several windows. Feature 3 is a historic house, likely moved to the property. Overall, the site has experienced loss of integrity of design, feeling, location, and to some extent, materials. Currently, a foundation has been poured for a new building to the east of Feature 1.

This site lead has not been evaluated for eligibility to the National Register of Historic Places. Current survey data are not sufficient to determine significance. Until a deed search can be performed, avoidance is recommended.

7. References/Comments:

Recorded By C. Carlson and E. Sakariassen Date Recorded 10/20/2014
(First Name & Last Name) (mm/dd/year)

Instructions to complete a digital version of this form: (1) Download a copy to your hard drive; (2) Open the saved blank copy; (3) Fill out the form; (4) Use the Save As command to rename the form appropriately and save; (5) *Print* and submit to SHSND.

**NDCRS SITE FORM
ATTACHMENTS SECTION**

Field Code MAC-NKL-60x

SITS# 32MZ



Figure 1: Site MAC-NKL-60x, Feature 1, view northeast (Image 5719).



Figure 2: Site MAC-NKL-60x, Feature 1, view southwest (Image 5728).

Recorded By C. Carlson and E. Sakariassen

Date Recorded 10/20/2014