Field Code ______ SITS# 32 ___ MZ __ x1774



Photo taken summer 2010 by SHSND intern Alicia Liebel

Field Code ______ SITS# 32 <u>MZ</u> <u>x1774</u>



Photo taken summer 2010 by SHSND intern Alicia Liebel

Field Code ______ SITS# 32 <u>MZ</u> <u>x1774</u>



Photo taken summer 2010 by SHSND intern Alicia Liebel

Field Code ______ SITS# 32 <u>MZ</u> <u>x1774</u>



Photo taken summer 2010 by SHSND intern Alicia Liebel

Field Code ______ SITS# 32 ___MZ __x1774



Photo taken summer 2010 by SHSND intern Alicia Liebel

Field Code ______ SITS# 32 ___MZ __x1774



Photo taken summer 2010 by SHSND intern Alicia Liebel

Recorded By: _____ Date Recorded: _____11/17/2020

Field Code ______ SITS# 32 ___MZ __x1774



Photo taken summer 2010 by SHSND intern Alicia Liebel

Field Code ______ SITS# 32 <u>MZ</u> <u>x1774</u>



Photo taken summer 2010 by SHSND intern Alicia Liebel

Field Code ______ SITS# 32 ___MZ __x1774



Photo taken summer 2010 by SHSND intern Alicia Liebel

Field Code ______ SITS# 32 <u>MZ</u> <u>x1774</u>



Photo taken summer 2010 by SHSND intern Alicia Liebel

NDCRS ARCHITECTURAL FORM PAGE 1

Field Code Twin Valley Township Hall	_	SITS# 32 MZ	X 1774
Map Quad Timber Prong Creek Map Quad	Site Name		
LTL T152 N., R98 W., Sec14 LTL TN., RW., Sec LTL TN., RW., Sec LTL TN., RW., Sec	QQQ of the QQ _ QQQ of the QQ _ QQQ of the QQ _	of the Q of the Q	1 = N½ 2 = E½ 3 = S½
NAD1983 UTM 5316620 NAD1983 UTM 634513 City: Street Number:			4 = W½ 5 = NE¼ 6 = SE¼ 7 = SW¼ 8 = NW¾
Street Name: Highway 1806			
Urban Legal Description: Total Number of Architectural Features:			
Fieldwork Date:7/26/2020			
Reconnaissance Survey	Intensive Survey	_	
Project & Principal Investigator: Kathy Wilner 366 43rd Ave SE Bowdon ND 58418			
Contracting Firm or Agency Completing the F	orm:		
Additional Information:			
SHSND USE Component Study Unit Component Component	Verified Site	CR Type	2
Recorded By: Kathy Wilner and Hu	nter Andes Date	Recorded: 8/23	3/2020

NDCRS ARCHITECTURAL FORM PAGE 2 – Feature Data

Field Code Twin	Valley Township Hall	;	SITS#	32 MZ		
Complete one Page	e 2 for each architectural feature at t	he site.				
Architectural Feature	e#					
Construction Date						
Feature Date191	5-1930					
Structural System	Wood Frame					
Original Owner's Eth	nicity					
Feature Type 9 - Sc	thool; Church school					
	on					
Primary Exterior	Metal, Horizontal Siding					
Secondary Exterior						
Condition <u>Excell</u>						
Plan Shape Rect	angular					
Style Other Style	3					
	Concrete	Stories	_			
Roof/CorniceGab	le					
	ed pane					
	Estimate					
	nation					
	on Recommendation(s) (Check all the					
Individual no		• • • • • •				
Contributes t	o a potential district					
No nomination	on potential					
Will not conti	ribute to a district					
Potential dist	trict—feature would be a contributing e	lement if ot	her prop	erties con	stitute a district	
Thematic no	mination potential					
Component	of a historic site or landscape					
site, orientati	cify all applicable choices)—a) relocation ion, landscape, and spatial relationship is damaged eligibility					
Historical as:	sociations require further investigation					
Recorded By:	Kathy Wilner and Hunter Andes	Date F	Record	led:	8/23/2020	

NDCRS ARCHITECTURAL FORM PAGE 3 – Feature Data

Field Code	Twin Valley Township Hall	SITS# 32 MZ
Fleia Coae	Twill valley township trail	SII S# 32

Complete one Page 3 for each architectural feature at the site.

1. Feature Description, Integrity, Eligibility:

This feature is either a large one room school or a township hall sitting on a poured concrete foundation. I was unable to learn if it was used as a school. The roof is finished with new asphalt shingles. The soffits are closed. There is no evidence of a chimney.


The siding on the building is horizontal, metal sheeting. There are three, side by side, fixed pane windows on the east and west sides, one more on the north side. The entry has a side by side, sliding window on the east wall of the entry. Ther are two doors into the building, one at the entry on the south side and another at the north east corner of the building. There is a concrete platform leading to the south door and a ramp leading to the northeast door. The interior of the school has clear coated plywood walls. The sloped ceiling is finished with wallboard along the width as well as at the peak ends. Indicators of electricity are ceiling light fixtures as well as baseboard heat. The floor is tongue and groove hardwood. One small blackboard is located on the north wall.

 Owner's Contact Information: Kimberly and Daniel Neprash 3972 ND 1806 Watford City 58854

Recorded By:	Kathy Wilner and Hunter Andes	Date Recorded: 8/23/2020
Recorded by:	Tradity Willion and Hallton Mides	Date Recorded: 0/20/2020

NDCRS ARCHITECTURAL FORM PAGE 4 – Site Description

Field Code Twin Va	lley Township Hall		SITS# 32 <u></u>	MZ	_
3. Site Area (ft²):					
	ss and Site Setting: amidst hay fields and chool is on ND Highway				
5. Summary of ALL Si	ite Features and Evaluatio	on of Significan	ce:		
6. References/Comme	ents:				
Recorded By:	Kathy Wilner and Hunte	er Andes	Date Recorded:	8/23/2020	



Twin Valley Township Hall


7/26/2020

Kathy Wilner

ΜZ

West Side





North Side


Twin Valley Township Hall

7/26/2020

Kathy Wilner

ΜZ

East Side





Imagery ©2020 CNES / Airbus, Maxar Technologies, USDA Farm Service Agency, Map data 200 ft ©2020

