NDCRS ARCHITECTURAL FORM PAGE 1

Field Code Forde #3	_	SITS# 32 ^{NE}	437
Map Quad Binford NW Map Quad	Site Name Fo	orde #3	
LTL TN., R61W., Sec20	QQQ of the QQ QQQ of the QQ	of the Q of the Q	1 = N½ 2 = E½
NAD <u>20221983</u> UTM 5284193 NAD <u>20221983</u> UTM 537935 City: Street Number:	_Zone <u>14N</u>	oi trie u	3 = 5½ 4 = W½ 5 = NE¼ 6 = SE¼ 7 = SW¼ 8 = NW¼
Street Name: 98th Ave NE	-		
Urban Legal Description;			
Total Number of Architectural Features:	1		
Fieldwork Date:10/30/2022			
Reconnaissance Survey	Intensive Survey		
Project & Principal Investigator: Country School House Project Kathy Wilner 366 43rd Ave SE Bowdon ND 58418			
Contracting Firm or Agency Completing the Fo	orm:		
Additional Information:			
SHSND USE Component Study Unit17 Component Component	Verified Site	CR Type	2
Recorded By: Kathy Wilner	Date	Recorded: 11/	05/2022

NDCRS ARCHITECTURAL FORM PAGE 3 – Feature Data

Field Code Forde #3	SITS# 32 NE 437
	\$0

Complete one Page 3 for each architectural feature at the site.

1. Feature Description, Integrity, Eligibility:

This feature is a one room school moved to the farm for storage. It is sitting on the ground, no foundation. The gable roof is covered with metal sheeting. The chimney is gone. The soffits are closed. The school measures 34 feet north to south and 20 feet east to west.

The siding begins with a rake board under the peak roofed ends. The remainder of the siding is 6 inch wood lap with 6 inch corner trim. There is a 5 panel wood door on the north wall giving entry to the school. Inside the door is an entry with 5 panel wood doors leading into the school proper located at both the east and west ends. Coat hooks are seen on the entry wall. A double hung window is located on each side of the entry door. A bank of 6 double hung windows, with glass intact, are located on the east wall. 4 of the six windows have storm windows. A plywood door was added on the south end of the school. Wallboard covers all walls and the ceiling with wainscot at the lower third of the walls. The floor is hardwood. Light fixtures indicate electricity was present at some point. There are blackboards on the west wall and the south wall either side of that south door.

 Owner's Contact Information: Monroe Tweed PO Box 59 Tolna ND 58380


Recorded By:	Kathy Wilner	Date Recorded: 11/05/2022	
I IQQQI WQW D I		mato i todoi addi	

NDCRS ARCHITECTURAL FORM PAGE 4 – Site Description

Date Recorded: 11/05/2022

Kathy Wilner

Recorded By: _



East Side


Forde #3

10/30/2022

Kathy Wilner

NE

South Side






North Side

10/30/2022 Forde #3







Imagery ©2022 CNES / Airbus Maxar Technologies, USDA/FPAC/GEO, Map data 500 ft ©2022

Feature