# NDCRS ARCHITECTURAL SITE FORM PAGE 1

SITS# 32 PB 242

SITE IDENTIFICATION		3113# 32	2 1/2
Field Code Hensal Fire Hall	Site Name Hensel	Fire Hall	
Map Quad Hersel Map Quad	Site Name		illy distribution of the control of
LTL TWP R SEC _ LTL TWP R SEC _		QQ QQ	Q5 Q Q
UTM 5393625 N UTM 598138 E	ZONE 14N NAD 1927	NAD 1983 <u>✓</u>	Subsection: 1 = N½
City: Hensal			2 = E½ 3 = S½
Street Number:			$4 = W\frac{1}{2}$ $5 = NE\frac{1}{4}$
Street Name: 88th St NE			6 = SE¼ 7 = SW¼
Urban Legal Description:			8 = NW1/4
SITE DATA			
Total # Architectural Features: 1	Operation		
Fieldwork Date: 9/19/2016			
Reconnaissance Survey   Intens	ive Survey		
Project Title & Supervisor: Country Schoolhouse Project			
Report Title & Author(s):			
Additional Information:			
SHSND USE Area of Significance Area of Significance Ecozone Area of Significance Ecozone	Verified Site	. CR Type	_2_
Recorded By Kathy Wilne	Pr Date I	Recorded	2/18/2016 (mm/dd/year)

# NDCRS ARCHITECTURAL SITE FORM PAGE 2—Feature Data

Field Code Hensal Fir	SITS# 32_PB		
Complete one Page 2 for each architectural feature at the site.			
Architectural Feature	#1		
Construction Date	Feature Type	Condition 5	
Feature Date 2	Context 7	Plan Shape 5	
Structural System 25	Primary Exterior 2	26 Style Hipped Roof B	ox
Original Owner's Ethnici	ty Secondary Exterio	or Architect/Builder	
Other Information:			
Foundation Concrete		Stories1	
Roof/Cornice_Hip			Potential Autoritorium delegane
Window Double hung, g	lass		of proceedings of the second
Dating Method(s): Estim	ate		MANAGEMENT STREET
Feature Preservation Recommendation(s) (Check all that apply):  —Individual nomination  —Contributes to a potential district  —No nomination potential  —Will not contribute to a district  —Potential district—feature would be a contributing element if other properties constitute a district  —Thematic nomination potential  —Component of a historic site or landscape  Moved (specify all applicable choices)—a) relocation occurred within a historic period; b) recreates original site, orientation, landscape, & spatial relationships; c) compatible in context  —with neighboring structures; d) relocation has damaged eligibility  —Historical associations require further investigation			
Recorded By	Kathy Wilner	Date Recorded 2/18/2016	

### NDCRS ARCHITECTURAL SITE FORM PAGE 3—Feature Data

Field Code Hensal Fire Hall		SITS# 32	PB

#### Complete a Page 3 for each feature.

#### 1. Feature Description, Integrity, Eligibility:

The feature is a one room prairie school on a councrete foundation. This school was moved into Hensel to serve as a firehall. The roof of the building is covered with ribbed metal sheeting. There is a concrete chimney on the west slope of the roof. The soffits are open. The building measures 34 feet north to south and 30 feet east to west.

There is a wide trim board under the soffits on all four side of the school. The remainder of the siding is 4 inch wood lap with metal corner capping. On the south side there is one small double hung window, the east side has a bank of 5 large, three over two, windows with glass intact, also on the east side closer to the north end are two more similar windows. The north side has an overhead door on most of the east 1/3 of the building with another small double hung window. On the west side there are two more of the smaller windows, three over two and with glass intact, either side of an entry door. The door is inset with a porch roof supported by brackets giving some protection from weather. There is a 3 panel wood door that opens into a small entry. At either side of the entry are two small rooms which may have been used for coatrooms. The main body of the building has a concrete floor and beadboard ceiling. The walls have wallboard. There are no blackboards remaining. Light fixtures and exterior wiring suggest electricity.

Recorded By	Kathy Wilner	Date Recorded	2/18/2016
(First Name & Last Name)			(mm/dd/year)

### NDCRS ARCHITECTURAL SITE FORM PAGE 4—SITE DESCRIPTION

Field Code Herisal Fire Hall		SIIS# 32_F	Ъ
Complete one Page 4 for the entire s	s <u>ite</u> .		
Owner's Contact Information:     Hensel Fire Department     Hensel ND			
Access (to rural areas):     Located at the intersection of 88th St NE and	138th Ave NE		
4. Site Area (ft²):	an and a second		
5. Description of <b>SETTING</b> : There is a large hall to the west, houses south	n and southeast, busines	ses to the north.	
Recorded By Kathy Wilne (First Name & Last Name)	er Date	Recorded	2/18/2016 (mm/dd/year)

### NDCRS ARCHITECTURAL SITE FORM PAGE 5—SITE DESCRIPTION

Field Code Hensal Fire H	Hall	SITS# 32_	PB
6. Summary of ALL Site Features & Evaluation of Significance:			
7. References/Comments:			
Kathy Wilner 366 43rd Ave SE			
Bowdon ND 58418	*		
Recorded By(First Name	Kathy Wilner	Date Recorded	2/18/2016
(First Name	& Last Name)		(mm/dd/year)



North Side


Hensal Fire Hall

9/19/2016

Kathy Wilner

PB

### West Side





East Side


Hensal Fire Hall

9/19/2016

Kathy Wilner

PB


South Side



PB

bing maps

Notes
Hensal Fire Hall
9/19/2016
Kathy Wilner





Feature