NDCRS 2009

State Historical Society of North Dakota

NDCRS ARCHITECTURAL SITE FORM PAGE 1

	PAGE	SITS# 32	<u>рв 248</u>
SITE IDENTIFICATION		0110# 02	
Field Code St. Joseph Township School			
Map Quad <u>Cavalier</u> NW Map Quad	Site Name		
LTL TWP R SEC LTL TWP R SEC	2 QQQ 8 QQQ QQQ QQQ QQQ	QQ	Q 7 Q Q Q
UTM5424787N UTM592993E	ZONE <u>14N</u> NAD 1927 _	NAD 1983 🗸	Subsection: - $1 = N\frac{1}{2}$
City:			$2 = E\frac{1}{2}$ $3 = S\frac{1}{2}$
Street Number:			4 = W½ 5 = NE¼
Street Name: 136th Ave NE			6 = SE¼ 7 = SW¼ 8 = NW¼
Urban Legal Description:		2	0 - 1907/4
SITE DATA			
Total # Architectural Features:1			
Fieldwork Date: 9/19/2016			
Reconnaissance Survey 🖌 Intens	sive Survey		
Project Title & Supervisor:			
Country Schoolhouse Project			
Report Title & Author(s):			
Additional Information:			
SHSND USE Z Ecozone 16 Area of Significance Ecozone Ecozone 16 Area of Significance Ecozone Ecozone Ecozone	Verified Site Non-Site	CR Typ	• _2
Recorded ByKathy Wilne	er Dat	e Recorded	2/18/2017
(First Name & Last Name)			(mm/dd/year)

State Historical Society of North Dakota

NDCRS 2009

NDCRS ARCHITECTURAL SITE FORM PAGE 2—Feature Data				
Field Code St. Joseph Township Scho	lool	SITS# 32_PB		
Complete one Page 2 for each architectural feature at the site.				
Architectural Feature #1				
Construction Date	Feature Type <u>9</u>	Condition <u>6</u>		
Feature Date 2	Context_7	Plan Shape <u>5</u>		
Structural System 25	Primary Exterior 26	StyleOther Style		
Original Owner's Ethnicity	Secondary Exterior	Architect/Builder		
Other Information:				
Foundation Concrete		Stories		
Roof/Cornice_Gable				
Window Double hung, a lot of glass				
Dating Method(s): Estimate				
Feature Preservation Recommendation(s) (Check all that apply):				
Individual nomination				
Contributes to a potential district				
No nomination potential				
Will not contribute to a district				
Potential district—feature would be a contributing element if other properties constitute a district				
Thematic nomination potential				
Component of a historic site or landscape				
Moved (specify all applicable choices)—a) relocation occurred within a historic period; b) recreates original site, orientation, landscape, & spatial relationships; c) compatible in contextwith neighboring structures; d) relocation has damaged eligibility				
Historical associations require further investigation				
Recorded By Kathy	Wilner Date I	Recorded 2/18/2017		

Recorded By (First Name & Last Name)

Date Recorded

2/18/2017 (mm/dd/year)

NDCRS 2009

NDCRS ARCHITECTURAL SITE FORM PAGE 3—Feature Data

Field Code St. Joseph Township School

SITS# 32 PB

Complete a Page 3 for each feature.

1. Feature Description, Integrity, Eligibility:

The feature is a one room prairie school on a concrete foundation. The gable roof of the main body and the entry are covered with asphalt chingles. There is a concrete chimney on the north slope of the roof near the west end. A flag pole rises above the door at the west end. The soffits are closed.

There is a wide trim board located under the soffits at the peak ends of the school and entry. The remaining siding is 6 inch wood lap with 6 inch wood corner trim. The entry has two 5 panel wood doors on the west side. A two pane window is above the middle door which gives entry to the school from a two step concrete porch. A small fixed pane window is to the south side of the door with one more small window on the north side of the entry. There are two more 5 panel wood doors inside the school, one a door from the coatroom and the other entry to the school room. Above the school room door is a transom. The interior walls of the coatroom are covered with wallpaper. The school room walls have fiberboard panels with wainscot on the bottom 1/3. The ceiling is covered with 12 inch ceiling tiles. The floor is tongue and groove hardwood. There is a stage at the east end of the building. There is one covered window on the south wall. There are two sets of three large double hung, multipane windows on the north side with exterior decorative cornices. Much of the glass is missing. There are blackboards on the entire east wall and most of the south wall. There are desks in the school but birds have been making a mess of the building. Light fixtures suggest electricity.

Recorded By Kathy Wilner (First Name & Last Name)

Date Recorded_

2/18/2017 (mm/dd/year)

State Historical Society of North Dakota

NDCRS 2009

NDCRS ARCHITECTURAL SITE FORM PAGE 4—SITE DESCRIPTION

Field Code St. Joseph Township School

SITS# 32 PB

Complete one Page 4 for the entire site.

2. Owner's Contact Information:

3. Access (to rural areas):

This building can be reached from Highway 55 9 miles west of the junction of Highway 32 and Highway 55 north of Walhalla 2 miles. The school is 1/2 mile north of Highway 55 on 136th Ave NE and it is on a farm site on the east side of the road.

4. Site Area (ft²): ____

5. Description of SETTING:

The location is called Patron Isles of memories and there are museum buildings located here. There are open fields to the west, south and east and a large museum building just north with more buildings beyond that to the north.

Recorded By______ (First Name & Last Name) **Kathy Wilner**

Date Recorded

2/18/2017 (mm/dd/vear)

State Historical Society of North Dakota

NDCRS 2009

NDCRS ARCHITECTURAL SITE FORM PAGE 5—SITE DESCRIPTION

Field Code St. Joseph Township School

SITS# 32_PB_____

6. *Summary of ALL* Site Features & Evaluation of Significance:

7. References/Comments: Kathy Wilner 366 43rd Ave SE Bowdon ND 58418

Recorded By Kathy Wilner Date Recorded 2/18/2017
(First Name & Last Name) (mm/dd/year)



West Side

St. Joseph Township School 9/19/2016

Kathy Wilner PB

North Side





South Side

St. Joseph Township School

9/19/2016

Kathy Wilner

PB



East Side

10/10/2016

Bing Maps - Directions, trip planning, traffic cameras & more

bing maps

Notes	
St. Joseph Township School	
9/19/2016	
Kathy Wilner	
РВ	



© 2016 Microsoft Corporation © 2016 HERE

Feature bing

Cromy 27 Drusslet Comp 25 DUP 504