Recorded By

(First Name & Last Name)

NDCRS ARCHITECTURAL SITE FORM PAGE 2—Feature Data

UPDATE

Field Code		SITS# 32_	RI	876
Complete one Page 2 for each	architectural featur	e at the site.		
Architectural Feature #1				
Construction Date	Feature Type	Condition 1		
Feature Date	Context	Plan Shape_		
Structural System	Primary Exterior	Style Not App	olicable	
Original Owner's Ethnicity	Secondary Exterior N/A	Architect/Build	der	_
Other Information: moved to 300 Ash A	ve in Wyndmere			
Foundation	*****	Stories		
Roof/Cornice		,		
Window	· · · · · · · · · · · · · · · · · · ·			
Dating Method(s):				
Feature Preservation Recommen	dation(s) (Check all th	at apply):		
Individual nomination				
Contributes to a potential distric	et			
✓ No nomination potential				
Will not contribute to a district				
Potential district—feature would be a contributing element if other properties constitute a district				
Thematic nomination potential				
Component of a historic site or landscape				
Moved (specify all applicable cl recreates original site, orientati with neighboring structures; d)	on, landscape, & spatial r	elationships; c) compa		
Historical associations require f	urther investigation			
Pagardad By Lorna N	leidinger	Data Dagardad	04/08/2	2016

Date Recorded

(mm/dd/year)

NDCRS ARCHITECTURAL SITE FORM PAGE 1

Field Code SITE IDENTIFICATION Map Quad Wyndmere SE Map Quad		Site Name Danton School #1		
LTL TWP132	SEC	_ QQQ _ QQQ	QQ 5 QQ QQ	Q 6 Q Q
UTM5124935 UTM651680 City: Street Number: Street Name: 161 Ave SE and Hwy 13	_E		NAD 1983 <u>√</u>	2 = E½ 3 = S½ 4 = W½ 5 = NE¼ 6 = SE¼ 7 = SW¼
Urban Legal Description:				8 = NW1/4
SITE DATA Total # <u>Architectural</u> Features:	1			
Fieldwork Date: 8/28/2013	_			
Reconnaissance Survey	Intensive Sur	vey		
Project Title & Supervisor:				
Report Title & Author(s):				
Additional Information:				
SHSND USE Area of Significance Area of Significance Ecozone Area of Significance Ecozone		Verified Site	CR Ty	pe <u>2</u>
J	leidinger	Date F	Recorded	10/15/2013
(First Name & Las	(Name)			(mm/dd/vear)

Instructions to complete a digital version of this form: (1) Download a copy to your hard drive; (2) Open the saved blank copy; (3) Fill out the form; (4) Use the Save As command to rename the form appropriately and save; (5) *Print* and submit to SHSND.

NDCRS ARCHITECTURAL SITE FORM PAGE 2—Feature Data

Field Code Complete one Pa	ge 2 <u>for each</u>	architectural feat	SITS# 32 ure at the site.	RI
Architectural Featu	ure #1			
Construction Date1	889	Feature Type9	Condit	ion <u>6</u>
Feature Date 2	_	Context 7	Plan S	hape 5
Structural System 25	<u> </u>	Primary Exterior 26	Style C	Other Style
Original Owner's Ethn	icity	Secondary Exterior _	Archite	ect/Builder
Other Information:				
Foundation concrete		as likely replaced	Stories	;1
Window openings app	pear original, glas	ss likely replaced		
Roof/Cornice hip				
Dating Method(s): loc	al lady on comm	ittee of the school	<u> </u>	
<i>Feature</i> Preservati	on Recommen	dation(s) (Check al	that apply):	
✓ Individual non	nination			
Contributes to	a potential distri	ct		
No nomination	n potential			
Will not contri	bute to a district			
Potential distr	ict—feature woul	d be a contributing eler	ment if other prope	erties constitute a district
Thematic non	nination potential			
Component o	f a historic site or	landscape		
a recreates orig	jinal site, orientati	choices)—a) relocation ion, landscape, & spati relocation has damage	al relationships; c)	
Historical ass	ociations require	further investigation		
Recorded By	Lorna l	Meidinger	Date Recor	ded 10/15/2013 (mm/dd/year)

Instructions to complete a digital version of this form: (1) Download a copy to your hard drive; (2) Open the saved blank copy; (3) Fill out the form; (4) Use the Save As command to rename the form appropriately and save; (5) *Print* and submit to SHSND.

NDCRS ARCHITECTURAL SITE FORM PAGE 3—Feature Data

Field Code	SITS# 32 RI	
1. Feature Description, Integrity, Eligibility:		

The school has a full basement that houses metal vents and has wood support poles under a beam on a cracked correte floor. A three-lite window to the basement is visible on the west side of the school and the interior photo shows two six-lite windows that have been covered, one on the north wall at the west end and one on the west end near the center. On the east end, front, there is a five-panel wood door at ground level that opens to a half flight of stairs to the basement. Stairs also lead up into the classroom. A second door is a modern flush steel door and has concrete steps (with a metal pipe rail) outside the entrance so the door opens directly onto the main floor. Above this door is a single pane transom and a 1:1 window is on each side. A hipped dormer has vertical siding covering it and there is no longer an opening. The north side has a band of six 1:1 windows that begins at the west end and runs the length of the interior classroom. The west end has two shed-roofed additions that housed the toilets. The south side has one 1:1 window near the east end. All of the roofs have the same asphalt shingles covering them.

The Danton School #1 was moved a couple miles west of its original location to where it sits now around 1900. The building operated as a school until 1960 and then housed meetings until around 2000. While the building is eligible for the National Register of Historic Places now, a committe has formed and there are plans to move the school in the next year or so to Gateway Park in Wyndmere. The setting would be completely changed and remove eligibility.

Recorded By Lorna Meidinger Date Recorded 10/15/2013 (mm/dd/year)

NDCRS ARCHITECTURAL SITE FORM PAGE 4—SITE DESCRIPTION

Field Code Complete one Page 4 <u>for the</u>		SITS# 32RI	
2. Owner's Contact Information:			
3. Access (to rural areas):			
From Wyndmere, go east along Hwy southwest corner of this intersection.	13 approximately five mile	s to 161 Ave SE. The scl	nool is on the
	000		
4. Site Area (ft²):			
5. Site Description:			
The school is surrounded mostly by our tree rows visible in the background of just south of the school.			•
Recorded By Lorna (First Name & L	Meidinger	Date Recorded	10/15/2013 (mm/dd/year)

NDCRS ARCHITECTURAL SITE FORM PAGE 5—SITE DESCRIPTION

Field Code	Site Features & Evaluation	SITS# 32 RI of Site Significance:	
6. Summary of All Site Features & Evaluation of Site Significance: While the school is in good shape and currently eligible, the current owner wants it removed. A local group has formed and plans to move the school into a city park in Wyndmere. The setting and orientation of the building will be changed and integrity lost with this move so that it will no longer be eligible for the National Register of Historic Places.			
7. References/Commer	nts:		
Recorded By	Lorna Meidinger (First Name & Last Name)	Date Recorded_	10/15/2013

·- 1040 --R 50 W 0 -1040-1 1053 11 BM 1014 R 51 W R 50 W 13! 13004 0 3

NDCRS SITE FORM ATTACHMENTS SECTION

Field Code SITS# 32 RI



Danton School front, east




Danton School, south



Danton School, west

Recorded By Lorna Meidinger (First Name & Last Name)




Danton School, N



Danton School, NE

Recorded By Lorna Meidinger
(First Name & Last Name)

Date Recorded




Danton School, interior NW




Danton School, interior 5 √
Recorded By Lorna Meidinger
(First Name & Last Name)

Date Recorded

10/15/2013 (mm/dd/year)







Danton School, interior basement, west wall Recorded By Lorna Meidinger (First Name & Last Name)

Date Recorded