
NDCRS ARCHITECTURAL SITE FORM PAGE 1

Field Code	_ SITS#	# 32 RI 8	81
SITE IDENTIFICATION Map Quad Wyndmere	Site Name Danton Sch	ool #1	
Map Quad	Site Name		
LTLTWP R SEC LTLTWP R SEC	7 000 8 — QQQ QQQ	QQ <u>5</u> QQ QQ	Q 8 Q Q
NAD 1983, UTM 5125405 N NAD 1983, UTM 644128 E	ZONE 14N		Subsection: 1 = N½
City: Wyndmere			$2 = E\frac{1}{2}$ $3 = S\frac{1}{2}$
Street Number:300			$4 = W\frac{1}{2}$ $5 = NE\frac{1}{4}$
Street Name: Ash Ave	-		6 = SE½ 7 = SW¼
Urban Legal Description:			8 = NW1/4
SITE DATA			
Total # Architectural Features: 1			
Fieldwork Date: 4/8/2014			
Reconnaissance Survey — Inter	sive Survey		
Project & Principal Investigator:			
Report Title & Author(s):			
Contracting firm or Agency completing the for SHSND	m:		
Additional Information: moved to 300 Ash Ave in Wyndmere either la Brad Abel and aerial photographs dated 8/20		nerly 32RI876. v	erified by
SHSND USE Area of Significance Ecozone Ecozone Area of Significance Ecozone		☐ CR Typ	pe
Recorded By Lorna Meidin (First Name & Last Name)	ger Date F	Recorded	04/08/2016
(First lagine or mast maine)			(mm/dd/year)

NDCRS SITE FORM ATTACHMENTS SECTION

Field Code LM-RI876-16

SITS# 32 RI



Recorded By Lorna Meidinger (First Name & Last Name)

Date Recorded

4/8/2016 (mm/dd/year)

Instructions to complete a digital version of this form: (1) Download a copy; (2) Open the saved blank copy; (3) Fill out the form; (4) Use the Save As command to rename the form appropriately, and save; (5) *Print* and submit to SHSND.

NDCRS ARCHITECTURAL SITE FORM PAGE 1

Field Code SITE IDENTIFICATION Map Quad Wyndmere SE Map Quad	Site Name Danton School #1 Site Name
LTLTWP R SEC LTLTWP R SEC	11 QQQ 5 QQ 5 Q 6 QQQ QQ QQ Q Q Q Q Q Q Q Q Q Q Q Q Q
UTM 5124935 N UTM 651680 E City:	$4 = W\frac{1}{2}$ $5 = NE\frac{1}{4}$
Street Name: 161 Ave SE and Hwy 13	$8 = NW^{1/4}$
Urban Legal Description:	
SITE DATA Total # <u>Architectural</u> Features: 1	
Fieldwork Date: 8/28/2013	
Reconnaissance Survey ✓ Intens	sive Survey
Project Title & Supervisor:	
Report Title & Author(s):	
Additional Information:	
SHSND USE Area of Significance	Verified Site CR Type
Recorded By Lorna Meidin (First Name & Last Name)	

Instructions to complete a digital version of this form: (1) Download a copy to your hard drive; (2) Open the saved blank copy; (3) Fill out the form; (4) Use the Save As command to rename the form appropriately and save; (5) *Print* and submit to SHSND.

NDCRS ARCHITECTURAL SITE FORM PAGE 2—Feature Data

Field Code SITS# 32 <u>RI</u> Complete one Page 2 <u>for each architectural feature</u> at the site.				
Architectural Feat	ure #1			
Construction Date1	889	Feature Type9	Condition 6	
Feature Date 2		Context 7	Plan Shape	5
Structural System 25		Primary Exterior 26	Style Other St	tyle
Original Owner's Ethn	nicity	Secondary Exterior	Architect/Buil	der
Other Information:				
Foundation concrete			Stories1	_
Window openings ap	pear original, glass	likely replaced		
Roof/Cornice hip				
Dating Method(s): loc	al lady on committ	ee of the school		
Feature Preservati	on Recommend	ation(s) (Check all th	nat apply):	
✓ Individual non	nination			
Contributes to	a potential district			
No nomination	n potential			
Will not contri	bute to a district			
Potential district—feature would be a contributing element if other properties constitute a district				
Thematic nom	nination potential			
Component or	f a historic site or la	andscape		
a recreates orig	inal site, orientatio	oices)—a) relocation oc n, landscape, & spatial r elocation has damaged (elationships; c) compa	
Historical ass	ociations require fu	irther investigation		
Recorded By	Lorna M	eidinger	Date Recorded	10/15/2013 (mm/dd/year)

Instructions to complete a digital version of this form: (1) Download a copy to your hard drive; (2) Open the saved blank copy; (3) Fill out the form; (4) Use the Save As command to rename the form appropriately and save; (5) *Print* and submit to SHSND.

Field Code

them.

NDCRS ARCHITECTURAL SITE FORM PAGE 3—Feature Data

SITS# 32 RI

1. Feature Description, Integrity, Eligibility:
The school has a full basement that houses metal vents and has wood support poles under a beam on a cracked conrete floor. A three-lite window to the basement is visible on the west side of the school and
the interior photo shows two six-lite windows that have been covered, one on the north wall at the west
end and one on the west end near the center. On the east end, front, there is a five-panel wood door at
ground level that opens to a half flight of stairs to the basement. Stairs also lead up into the classroom. A
second door is a modern flush steel door and has concrete steps (with a metal pipe rail) outside the
entrance so the door opens directly onto the main floor. Above this door is a single pane transom and a
1:1 window is on each side. A hipped dormer has vertical siding covering it and there is no longer an

opening. The north side has a band of six 1:1 windows that begins at the west end and runs the length of the interior classroom. The west end has two shed-roofed additions that housed the toilets. The south side has one 1:1 window near the east end. All of the roofs have the same asphalt shingles covering

The Danton School #1 was moved a couple miles west of its original location to where it sits now around 1900. The building operated as a school until 1960 and then housed meetings until around 2000. While the building is eligible for the National Register of Historic Places now, a committe has formed and there are plans to move the school in the next year or so to Gateway Park in Wyndmere. The setting would be completely changed and remove eligibility.

Lorna Meidinger 10/15/2013 Recorded By____ ____ Date Recorded_

NDCRS ARCHITECTURAL SITE FORM PAGE 4—SITE DESCRIPTION

Field Code Complete one Page 4 <u>for the entire <i>sit</i>e</u> .	SITS# 32 <u>RI</u>
2. Owner's Contact Information:	
3. Access (to rural areas):	
From Wyndmere, go east along Hwy 13 approximate southwest corner of this intersection.	ly five miles to 161 Ave SE. The school is on the
4. Site Area (ft²):	
5. Site Description:	
The school is surrounded mostly by cultivated fields to tree rows visible in the background of the school to the just south of the school.	•

Recorded By Lorna Meidinger Date Recorded 10/15/2013

(First Name & Last Name) (mm/dd/year)

(mm/dd/year)

NDCRS ARCHITECTURAL SITE FORM **PAGE 5—SITE DESCRIPTION**


Field Code	E Features & Evaluation of S	SITS# 32 <u>RI</u> _ Site Significance:		
While the school is in good shape and currently eligible, the current owner wants it removed. A local group has formed and plans to move the school into a city park in Wyndmere. The setting and orientation of the building will be changed and integrity lost with this move so that it will no longer be eligible for the National Register of Historic Places.				
7. References/Comments:				
Recorded By	Lorna Meidinger t Name & Last Name)	_ Date Recorded	10/15/2013 (mm/dd/year)	

NDCRS SITE FORM ATTACHMENTS SECTION

Field Code SITS# 32 RI



Danton School front, east



Danton School, south



Danton School, west




Danton School, N



Danton School, NE

Recorded By Lorna Meidinger
(First Name & Last Name)

Date Recorded



Danton School, interior NW



Danton School, interior 5 √
Recorded By Lorna Meidinger
(First Name & Last Name)

Date Recorded



Danton School, interior east wall



Danton School, interior basement, ~est~all Recorded By Lorna Meidinger (First Name & Last Name)

Date Recorded