NDCRS 2009

192

NDCRS	ARCHITECTURAL	SITE	FORM
	PAGE 1		

Field Code Bale Township School Site Name Map Quad Eliph SE Map Quad Site Name LTL TWP R SEC QQQ QQ QQ QQ UTM S134240 UTM S134240 UTM S134240 UTM S95208 E QQQ QQ QQ City: Liston Street Number: Street Number: Street Name: 127th Ave SE Urban Legal Description: Street Number: SITE DATA Street Attract Features: Fieldwork Date: 5/5/2016 Reconnaissance Survey Intensive Survey Project Title & Supervisor: Country Schoolhouse Project Report Title & Author(s): Additional Information: Area of Significance Ecozone Area of Significance Ecozone Yerified Site CR Type Z CR Type			SITS# 32_R	м 192
Map Quad Site Name LTL TWP LTL TWP R SEC QQQ QQ QQQ QQ UTM S134240 UTM 5134240 UTM 595208 E NAD 1927 NAD 1983 Subsection: 1 N/2 2 E/X 3 Site Name UTM 5134240 VTM 595208 E NAD 1927 NAD 1983 Subsection: 1 N/2 2 E/X 3 SY Street Number: Subsection: Street Name: 127th Ave SE Street Name: 127th Ave SE Street Name: 1 Fieldwork Date: 51/2016 Reconnaissance Survey Intensive Survey Project Title & Supervisor: Country Schoolhouse Project Report Title & Author(s): Additional Information: Area of Significance Ecozone Survet CR Type	SITE IDENTIFICATION Field Code Bale Township School	Site Name		
LTL	Map Quad Elliot SE	011 11		
UTM 595208 E NAD 1927 NAD 1983 1 = N½ City: Lisbon	LTL TWP R SI LTL TWP R SI	EC QQQ EC QQQ	QQ QQ	Q
City: Lisbon 3 = S½ Street Number: 3 = N½ Street Name: 127th Ave SE Urban Legal Description: 5 SITE DATA SITE DATA Total # Architectural Features: 1 Fieldwork Date: 5/5/2016 Reconnaissance Survey ✓ Project Title & Supervisor: Country Schoolhouse Project Report Title & Author(s): Additional Information: Additional Information:	UTM <u>5134240</u> N UTM <u>595208</u> E	ZONE <u>14N</u> NAD 1927	NAD 1983	
Street Number:	City: Lisbon			
Street Name: 12/th Ave SE Urban Legal Description: SITE DATA Total # Architectural Features: 1 Fieldwork Date: 5/5/2016 Reconnaissance Survey ✓ Intensive Survey Project Title & Supervisor: Country Schoolhouse Project Report Title & Author(s): Additional Information: SHSND USE Area of Significance Area of Significance Leczone Leczone Verified Site CR Type Leczone	Street Number:			5 = NE ¹ ⁄ ₄
Urban Legal Description: SITE DATA Total # Architectural Features: 1 Fieldwork Date: 5/5/2016 Reconnaissance Survey ✓ Intensive Survey Project Title & Supervisor: Country Schoolhouse Project Report Title & Author(s): Additional Information:	Street Name: 127th Ave SE			7 = SW1⁄4
Total # Architectural Features: 1 Fieldwork Date: 5/5/2016 Reconnaissance Survey ✓ Intensive Survey Project Title & Supervisor: Country Schoolhouse Project Report Title & Author(s): Additional Information: SHSND USE Area of Significance Ecozone Verified Site Non-Site	Urban Legal Description:			8 = NW ¹ ⁄ ₄
Fieldwork Date: 5/5/2016 Reconnaissance Survey ✓ Intensive Survey Project Title & Supervisor: Country Schoolhouse Project Report Title & Author(s): Additional Information: SHSND USE Area of Significance Area of Significance Area of Significance Ecozone Verified Site CR Type	SITE DATA			
Reconnaissance Survey ✓ Intensive Survey Project Title & Supervisor: Country Schoolhouse Project Report Title & Author(s): Additional Information: SHSND USE Area of Significance Area of Significance Ecozone L Verified Site Non-Site CR Type	Total # <i>Architectural</i> Features:1			
Project Title & Supervisor: Country Schoolhouse Project Report Title & Author(s): Additional Information: SHSND USE Area of Significance Area of Significance Image: Significance <td< td=""><td>Fieldwork Date:5/5/2016</td><td></td><td></td><td></td></td<>	Fieldwork Date:5/5/2016			
Country Schoolhouse Project Report Title & Author(s): Additional Information: SHSND USE Area of Significance Area of Significance Area of Significance Area of Significance	Reconnaissance Survey 🖌 In	tensive Survey		
Additional Information: SHSND USE Area of Significance Area of Significance Area of Significance Area of Significance Verified Site CR Type				
SHSND USE Area of Significance Area of Significance Area of Significance Area of Significance Ecozone Verified Site Non-Site	Report Title & Author(s):			
Area of Significance Ecozone Verified Site CR Type Area of Significance Ecozone Non-Site Area of Significance If the units	Additional Information:			
	Area of Significance Ecozone		. CR Type	_2
Recorded By Kathy Wilner Date Recorded 1/11/2017 (First Name & Last Name) (mm/dd/year)	Recorded By Kathy W	ilner Date I	Recorded	1/11/2017

NDCRS 2009

NDCRS ARCHITECTURAL SITE FORM PAGE 2—Feature Data						
Field Code Bale Township School		SITS# 32_ <u>RM</u> _				
Complete one Page 2 for each architectural feature at the site.						
Architectural Feature #1						
Construction Date	Feature Type <u>9</u>	Condition <u>5</u>				
Feature Date 2	Context 7	Plan Shape <u>5</u>				
Structural System 25	Primary Exterior <u>26</u>	Style <u>Other Style</u>				
Original Owner's Ethnicity	Secondary Exterior	Architect/Builder				
Other Information: Foundation <u>Poured Concrete</u>						
Window Double hung, some glass, some shuttered Dating Method(s): estimate						
Feature Preservation Recommen	dation(s) (Check all that app	oly):				
Individual nomination						
Contributes to a potential distric	ct					
No nomination potential						
Will not contribute to a district						
Potential district—feature would be a contributing element if other properties constitute a district						
Thematic nomination potential						
Component of a historic site or landscape						
Moved (specify all applicable choices)—a) relocation occurred within a historic period; b) recreates original site, orientation, landscape, & spatial relationships; c) compatible in context with neighboring structures; d) relocation has damaged eligibility						
Historical associations require further investigation						
Recorded By Kathy (First Name & Last Name)	Wilner Date		/ 2017 /dd/year)			
Instructions to complete a digital version of	this form: (1) Download a copy to yo	ur hard drive: (2) Open t	he saved			

NDCRS 2009

NDCRS ARCHITECTURAL SITE FORM PAGE 3—Feature Data

Field Code Bale Township School

SITS# 32_RM

Complete a Page 3 for each feature.

1. Feature Description, Integrity, Eligibility:

The feature is a one room prairie school on a concrete foundation. The school has a hip roof covered with a mix of wood shaked and asphalt shingles. Some metal capping remains on the hip seams. At the front of the school there is a gable roofed open porch. At the outside end of the entry roof there is a decorative slant of roofing with wood shakes that sits back under the gable end. There is a bell tower on top of the entry with a box bottom that has wood lap siding with metal corner caps and 4 posts to hold up the pyramid cap which is finished with metal. No bell remains. There is a yellow brick chimney on the north slope of the roof. Soffits are closed with white painted 4 inches boards. The school was painted red. It measures 32 feet east to west and 28 1/2 feet north to south with an entry porch measuring 8 1/2 feet wide by 4 feet deep.

The siding is 3 inch wood lap with 4 inch corner trim on two corners and wide metal cap trim on the other two. There is a wide trim board at the bottom of the siding under a waterboard trim piece.

The porch has siding on the north and sides in the same manner as the remainder of the school. That siding comes around to the front of the porch in a piece that is about a foot wide on either side. There is a wood step leading to the entry door opening, the entry door is missing. Boards cover what were sidelights and a transom window above. Inside the entry there three more door openings, two have 5 panel wood doors and the other nothing, all have transoms above them and some are broken. The doors to either side lead to coatrooms and again another door leads into the bathroom off each cloat room. There doors leading from the coat rooms into the main room of the school. Most inner doors are still in place with wide, decorative cornices. The floor is tongue and groove hardwood. There are a variety of window sizes, all double hung with little or no glass and many of them are shuttered. There are blackboards on both the north and south walls below high placed windows. The school has been used for storage. The walls and ceiling of the school are lathe and plaster and much of that has fallen away. There is wainscot on the walls. Electricity was present.

Recorded By Kathy Wilner Date Recorded 1/11/2017
(First Name & Last Name) (mm/dd/year)

NDCRS 2009

NDCRS ARCHITECTURAL SITE FORM PAGE 4—SITE DESCRIPTION

Field Code Bale Township School

SITS# 32_RM_____

Complete one Page 4 for the entire site.

2. Owner's Contact Information:

Allan Hankel 12604 74th St SE Lisbon ND 58504

3. Access (to rural areas):

From Highway 32, going south of Lisbon, look for 73rd St SE and turn west (right) to drive 5 miles. You will have reached 127th Ave SE and the school will be on the southeast corner of the intersection.

4. Site Area (ft²):_____

5. Description of **SETTING**:

There is a farm site to the south and farm fields all other directions.

Recorded By Kathy Wilner Date Recorded 1/11/2017
(First Name & Last Name) (mm/dd/year)

NDCRS 2009

NDCRS ARCHITECTURAL SITE FORM PAGE 5—SITE DESCRIPTION

Field Code Bale Township School

SITS# 32_<u>RM</u>_____

6. *Summary of ALL* Site Features & Evaluation of Significance:

7. References/Comments: Kathy Wilner 366 43rd Ave SE Bowdon ND 58418

Recorded By Kathy Wilner Date Recorded 1/11/2017
(First Name & Last Name) (mm/dd/year)



West Side

Bale Township School

5/5/2016

Kathy Wilner

LM

North Side





South Side

Bale Township School

5/15/2016

bing maps

Notes

Bale Township School 5/5/2016 Kathy Wilner RM





Feature