State Historical Society of North Dakota

NDCRS 2020

NDCRS ARCHITECTURAL FORM PAGE 1

Field Code Birklid Scho		- Site Name Birk	SITS# 32 RM	
Map Quad Ft. Ransom Map Quad	57 W., Sec. 29 W., Sec. W., Sec. W., Sec. S157250 52.8 585940		of the Q of the Q of the Q	Subsection 1 = N ¹ / ₂ 2 = E ¹ / ₂
Street Name:122nd Av				
Urban Legal Description: Total Number of Architec Fieldwork Date:7/20	tural Features:			
Reconnaissance Survey _	4	Intensive Survey	-	
Project & Principal Investig Country School House Pro Kathy Wilner 366 43rd Ave SE Bowdon ND 58418				
Contracting Firm or Agend	cy Completing the Fo	orm:		
Additional Information:				
SHSND USE Component Component Component	Study Unit	Verified Site	CR Type	2
Recorded By:	Kathy Wilne	r Date	Recorded: <u>8/8</u>	/2020

Form instructions: (1) Download; (2) Save A Copy; (3) Submit a paper copy of the form to the SHSND and upload the PDF version of the form and corresponding GIS shapefiles to the ND SHPO-run FTP site.

NDCRS ARCHITECTURAL FORM PAGE 2 – Feature Data

Field Code Birklid School	SITS# 32	2 <u>RM</u>	
Complete one Page 2 for each architectural feature at the site.			
Architectural Feature #1			
Construction Date			
Feature Date <u>1900-1915</u>			
Structural System <u>Wood Frame</u>			
Original Owner's Ethnicity			
Feature Type 9 - School; Church school			
Context <u>Education</u>			
Primary Exterior Wood, Horizontal Siding			
Secondary Exterior			
Condition Good			
Plan Shape <u>Rectangular</u>			
Style <u>Other Style</u>			
Architect/Builder			
	s1		
Roof/CorniceGable			
Window Large, multipane, double hung with glass			
Dating Method(s)Estimate			
Miscellaneous Information			
Feature Preservation Recommendation(s) (Check all that apply)			
Individual nomination	-		
Contributes to a potential district			
No nomination potential			
Will not contribute to a district			
Potential district—feature would be a contributing element if	other prope	rties constitute a distr	ict
Thematic nomination potential			
Component of a historic site or landscape			
Moved (specify all applicable choices)—a) relocation occurrents site, orientation, landscape, and spatial relationships; c) compression has damaged eligibility			
Historical associations require further investigation			

8/8/2020

Date Recorded:

Kathy Wilner

Recorded By: _

NDCRS ARCHITECTURAL FORM PAGE 3 – Feature Data

Field Code Birklid School

SITS# 32 RM

Complete one Page 3 for each architectural feature at the site.

1. Feature Description, Integrity, Eligibility:

The feature is a large, one room prairie school on a foundation of rocks in cement. The gable roof is covered with wood shakes, metal capping and finials. The north addition shed roof is also covered with wood shakes. There is a red brick chimney on the north slope of the wall close to the east end. The soffits are open. The school measures 36 feet east to west and 20 feet north to south while the addition measures 6 feet by 20 feet. A gabled roof covers a portico at the entrance. A flag pole can be seen at the southeast corner of the school.

A rake board begins the siding at the peak ends of the school. The rest of the siding is 6 inch wood lap with 4 inch wood corner trim. Two wood steps take you to the portico at the entrance to the school. Wood columns at the outside corners help to support the roof. A solid core door gives entry to the school. You step into the coatroom and all the walls in here are covered with pressed tin. There is one double hung window on the east wall of the entry. Coat hooks run along the east wall at two different heights. There are two doors leading from the entry, one (two panel wood) goes to the left into the school room and another (5 panel wood) goes to the north into a large alcove off the school room, it looks like this area was used for the wash room. Another double hung window is in the alcove on the east wall. The school room has 6 large multipane double hung windows along the south wall with intact glass. All have screen windows and most have remnants of window shades. The floor throughout is tongue and groove hardwood. The walls in the school are wallboard with a wide trim board at the floor. The ceiling has acoustical tile. Light fixtures and switches indicate electricity. There are wood framed blackboards on two walls, one on the north wall at the west end and another on most of the west wall. A collection of maps hangs next to the north blackboard. The addition on the north side was used for a small kitchen. A small window located just to the left of the addition door was used as a pass through for children getting their lunch. The wall at the back (east) of the class room has a built in shelf unit for books. This school was closed in 1950.

2. Owner's Contact Information: Robert Birklid 5851 122nd Ave SE Nome ND 58062

Recorded By:

Kathy Wilner

Date Recorded: 8/8/2020

NDCRS ARCHITECTURAL FORM PAGE 4 – Site Description

Field Code Birklid School

SITS# 32 RM

3. Site Area (ft²):

4. Description of Access and Site Setting:

This school is sitting to the east of the owners farm yard. There are buildings to the southwest and open fields all other directions. Access to the school is 4 miles south of Highway 46 on 123rd Ave SE to 58th St SE. Then one mile west to 122nd Ave SE and 1/2 mile south to the drive way, turn right and drive another mile to the east to see the school.

5. Summary of ALL Site Features and Evaluation of Significance:

6. References/Comments:

Kathy Wilner

Date Recorded: 8/8/2020

Form instructions: (1) Download; (2) Save A Copy; (3) Submit a paper copy of the form to the SHSND and upload the PDF version of the form and corresponding GIS shapefiles to the ND SHPO-run FTP site.



South Side

Birklid School 7/20/2020 Kathy Wilner RM

East Side





West Side

Birklid School 7/20/2020 Kathy Wilner RM

North Side





Imagery ©2020 Google, Imagery ©2020 Maxar Technologies, USDA Farm Service 500 ft Agency, Map data ©2020

Feature