State Historical Society of North Dakota

NDCRS ARCHITECTURAL FORM PAGE 1

Component Component		
SHSND USE Component 2 Study Unit 5	Verified Site CR Type	2
Additional Information:		
Contracting Firm or Agency Completing the F	⁼ orm:	
Project & Principal Investigator: Country School House Project Kathy Wilner 366 43rd Ave SE Bowdon ND 58418		
Reconnaissance Survey	Intensive Survey	
Fieldwork Date:7/7/2020		
Total Number of Architectural Features:	1	
Urban Legal Description:		
Street Number:12128 Street Name:59th St SE		
City:		6 = SE ¹ / ₄ 7 = SW ¹ / ₄ 8 = NW ¹ / ₄
NAD <u>1983</u> UTM 5156419 NAD <u>1983</u> UTM 585 361 (,3)	Zone 14N	4 = W½ 5 = NE¼ 6 = SE¼
LTL TN., RW., Sec LTL TN., RW., Sec		3 = S½
LTL T. <u>136</u> N., R. <u>57</u> W., Sec. <u>32</u> LTL TN., RW., Sec	_ QQQ of the QQ of the Q _	1 = N½
Map Quad Ft. Ransom Map Quad		
Field Code Springer School #5		RM 660

Form instructions: (1) Download; (2) Save A Copy; (3) Submit a paper copy of the form to the SHSND and upload the PDF version of the form and corresponding GIS shapefiles to the ND SHPO-run FTP site.

NDCRS ARCHITECTURAL FORM PAGE 2 – Feature Data

Field Code Springer School #5	SITS# 3	2 RA
Complete one Page 2 for each architectural feature at the		
Architectural Feature #1		
Construction Date		
Feature Date <u>1900-1915</u>		
Structural System Wood Frame		
Original Owner's Ethnicity		
Feature Type <u>9 - School; Church school</u>		
Context Education		
Primary Exterior Wood, Horizontal Siding		
Secondary Exterior		
Condition Excellent		
Plan Shape <u>Rectangular</u>		
Style Other Style		
Architect/Builder		
	Stories 1	
Roof/CorniceGable		
Window Double hung, glass		
Dating Method(s)		
Miscellaneous Information		
Feature Preservation Recommendation(s) (Check all that a	apply):	
Individual nomination		
Contributes to a potential district		
No nomination potential		
Will not contribute to a district	5	
Potential district—feature would be a contributing elem	ent if other prope	rties constitute a district
Thematic nomination potential		
Component of a historic site or landscape		
Moved (specify all applicable choices)—a) relocation o site, orientation, landscape, and spatial relationships; o relocation has damaged eligibility		
Historical associations require further investigation		

NDCRS ARCHITECTURAL FORM PAGE 3 – Feature Data

Field Code Springer School #5

SITS# 32 RA

Complete one Page 3 for each architectural feature at the site.

1. Feature Description, Integrity, Eligibility:

The feature is a one room prairie school on a concrete brick foundation. This school was moved to this location on the farm site after Mrs. Birklid, the schools last teacher, decided to take it home with her. The roof is covered with metal sheeting. The soffits are closed. The chimney hole was covered when the new roof went on. The school measures 36 feet north to south and 16 feet east to west.

A rake board at both of the peak ends, under the easves, begins the siding. The remainder of the siding is 6 inch wood lap with 4 inch wood corner trim. On the east side of the school siding was used to fill two window openings in the main part of the school. One more double hung window with glass, located in the coatroom, is covered with a sheet of plywood. The windows on the west side are two over two double hung windows with much of the glass intact. There is one window closer to the south end that is located in the storage room to the left of the entry door. There are four 4 over 4 windows on the west side of the class room, two are covered with plywood and two have storm windows. Three steps lead up to a wooden porch with metal railings to either side. The entry door is a 5 panel wood door with a large patch near the bottom and a decorative cornice above. Stepping into the building there is a 4 panel wood door immediately to the left that leads into a large area that may have been used for storage. The walls in this area have house siding up about 2/3 of the way on the wall and the remainder if open between the studs. The entry/coatroom itself has beadboard on the walls. The door leading into the school room is 5 panel wood with a transome above it. All the interior doors have decorative cornices above them. The school room walls and ceiling are all finished with beadboard. There is a stage at the north end of the room. The blackboard runs along that north wall. The floor is tongue and groove hardwood. Electricity is present with lights both inside and out.

The school closed in 1957. The building is used today for memorbilia and storage.

2. Owner's Contact Information: Richard Birklid 12128 58th St SE Nome ND 58062

Recorded By:

Kathy Wilner

Date Recorded: 8/8/2020

NDCRS ARCHITECTURAL FORM PAGE 4 – Site Description

Field Code Springer School #5

SITS# 32 RA

3. Site Area (ft²):

4. Description of Access and Site Setting:

Access to the school is 4 miles south of Highway 46 on 123rd Ave SE to 58th St SE. Then one mile west to 122nd Ave SE and 1/2 mile south to the drive way, turn right and drive another 1 south to 59th St SE, 3/4 mile west and follow the road as it cures to the south and takes you into the farm yard where the school is sitting. The school is sitting in the middle of a farm yard with the house to the northeast, open field to the east and buildings and trees all other directions.


5. Summary of ALL Site Features and Evaluation of Significance:

6. References/Comments:

Kathy Wilner

Date Recorded: 8/8/2020

Form instructions: (1) Download; (2) Save A Copy; (3) Submit a paper copy of the form to the SHSND and upload the PDF version of the form and corresponding GIS shapefiles to the ND SHPO-run FTP site.



Spring #5 7/20/2020 Kathy Wilner



East Side



West Side

Spring #5	7/20/2020	Kathy Wilner	RM	
		A.		

North Side





Imagery ©2020 Google, Imagery ©2020 Maxar Technologies, USDA Farm Service Agency, 200 ft ____ Map data ©2020

Feature