NDCRS ARCHITECTURAL SITE FORM PAGE 1

SITS# 32 RO 88

SITE IDENTIFICATION	3110# 32 <u>-110</u>
Field Code Nanson School	Site Name Nanson School Site Name
Map Quad Mylo SE Map Quad	Site Name
LTL TWP R SEC . LTL TWP R SEC .	31 QQQ 8 QQ 5 Q 7 QQQ QQ QQ QQ Q
UTM 5377697 N UTM 454449 E	ZONE 14N Subsection: 1 = N½
City: Wolford	0 0/2
Street Number: 4839	$4 = W\frac{1}{2}$ = 5 = NE\frac{1}{4}
Street Name: 78th St NE	6 = SE½ 7 = SW½
Urban Legal Description:	8 = NW1/4
SITE DATA	
Total # Architectural Features:1	
Fieldwork Date: 7/4/2016	
Reconnaissance Survey <u>✓</u> Intens	sive Survey
Project Title & Supervisor:	
Country Schoolhouse Project	
Report Title & Author(s):	
Additional Information:	
SHSND USE Area of Significance Area of Significance Ecozone Area of Significance	Verified Site CR Type
Recorded By Kathy Wilner	Date Recorded 1/18/2017
(First Name & Last Name)	(mm/dd/year)

Instructions to complete a digital version of this form: (1) Download a copy to your hard drive; (2) Open the saved blank copy; (3) Fill out the form; (4) Use the Save As command to rename the form appropriately and save; (5) Print and submit to SHSND.

NDCRS ARCHITECTURAL SITE FORM PAGE 2—Feature Data

Field Code Nanson School		SITS# 32_	RO
Complete one Page 2 <u>for each architectural feature</u> at the site.			
Architectural Feature #1	_		
Construction Date	Feature Type9	Condition 7	
Feature Date 2	Context 7	Plan Shape	5
Structural System <u>25</u>	Primary Exterior <u>26</u>	Style Other S	Style
Original Owner's Ethnicity	Secondary Exterior	Architect/Bu	ilder
Other Information:			
Foundation Concrete covered by m	etal sheeting	Stories1	_
Roof/Cornice Gable			-
Window Double hung, some fixed p	ane		
Dating Method(s): Estimate			
 Thematic nomination poten Component of a historic site Moved (specify all applicab recreates original site, orier 	strict rould be a contributing element if tial e or landscape le choices)—a) relocation occurritation, landscape, & spatial related by relocation has damaged eligical	other properties of ed within a historic ionships; c) comp	c period; b)
Recorded By Ka		ate Recorded	1/18/2017 (mm/dd/year)

Instructions to complete a digital version of this form: (1) Download a copy to your hard drive; (2) Open the saved blank copy; (3) Fill out the form; (4) Use the Save As command to rename the form appropriately and save; (5) *Print* and submit to SHSND.

NDCRS ARCHITECTURAL SITE FORM PAGE 3—Feature Data

Field Code Nanson School	 SITS# 32_RO	

Complete a Page 3 for each feature.

1. Feature Description, Integrity, Eligibility:

The feature is a one room prairie school sitting on a concrete foundation. The school was moved from Nanson to this museum complex in 1989. This is a wonderful example of a one room school, decorated with items of the time. The desks, books, maps and other items are original to the school.

The gable roof of the school and entry are covered with asphalt shingles. There is a bell tower at the peak of the north end of the roof. The base of the tower is a square structure with 6 inch lap siding with four posts holding up the pyramid roof, also covered in asphalt shingles. There is a flag pole at the peak of the bell tower. There is a red brick chimney at the peak of the roof at the south end of the school. The soffits are closed. The roof on the entry is gable with extension shed roof to the west. The building measures 24 feet north to south and 18 1/2 feet east to west with the shed measuring 8 feet north to south by 14 feet east to west.

There is a wide trim board under the soffits at the peak ends of the school as well as the entry. The siding is 6 inch wood lap with 4 inch wood corner trim. The concrete foundation is skirted with metal sheeting. There is a plywood door on the entry and this is kept locked. Inside the entry there is a plank door giving access to the west 1/2, used for storage today. The floor in the entry was replaced with newer 4 inch wood planks. The floor in the main body of the school has tongue and groove hardwood.

There are windows of various sizes, the entry has a 4 pane fixed window on the west and a small, 3 pane fixed window on the north, two narrow windows are above the blackboard ont he east wall. 5 double hung, 2 over 2, windows are on the west wall. Glass in intact in all windows. Walls and ceiling in the school are wallboard with wainscot on the lower third. There are two more smaller blackboard, one to the left of the entry door and another on the east 1/3 of the south wall. There is a nonfunctioning wood or coal burning stove. Electric lights hang from the ceiling.

Recorded By Kathy Wilner (First Name & Last Name)	Kathy Wilner	Date Recorded	1/18/2017
			(mm/dd/year)

Field Code Nanson School

SITS# 32_RO_____

NDCRS ARCHITECTURAL SITE FORM PAGE 4—SITE DESCRIPTION

Complete o	ne Page 4 <u>for the entire <i>site</i></u> .		
3. Access (to ru	ural areas):		
	s located 6 miles south of Mylo on Highway 30 2 mile to the driveway going north into the mus		left (east) and
4. Site Area (ft ²	·):		
5. Description of	of SETTING :		
	ts in a museum complex, a church to the east, display building to the north.	pioneer home to the we	st, trees south and
Recorded By	Kathy Wilner	Date Recorded	1/18/2017
	(First Name & Last Name)		(mm/dd/year)

NDCRS ARCHITECTURAL SITE FORM PAGE 5—SITE DESCRIPTION

Field Code Nanson School	ol .	SITS# 32_	RO
6. Summary of ALL Si	te Features & Evaluatio	n of Significance:	
7. References/Comments:			
Kathy Wilner			
366 43rd Ave SE Bowdon ND 58418			
Decembed D	Mathew Miles	D. C. D	4/40/2047
Recorded By(First Name &	Kathy Wilner Last Name)	Date Recorded	1/18/2017 (mm/dd/year)

Instructions to complete a digital version of this form: (1) Download a copy to your hard drive; (2) Open the saved blank copy; (3) Fill out the form; (4) Use the Save As command to rename the form appropriately and save; (5) *Print* and submit to SHSND.



North Side

Nanson School

7/4/2016

Kathy Wilner

RO

East Side



bing maps

Notes

Nanson School

7/4/2016

Kathy Wilner

RO



0 2016 HERE

Feature