NDCRS ARCHITECTURAL SITE FORM PAGE 1

SITS# 32 RO 407

SITE IDENTIFICATION					~
Field Code Ackworth Sch	100!	Site Na	me Ackworth Semi	chool	
Map Quad Boundary Lak Map Quad					
	R S R S	EC 8 EC EC EC	QQQ 8 QQQ QQQ	QQ 8 QQ QQ QQ	Q 8 Q Q Q
UTM	N	l :	ZONE NAD 1927	NAD 1983	Subsection: $1 = N\frac{1}{2}$
City:					$2 = E\frac{1}{2}$ $3 = S\frac{1}{2}$
Street Number:					4 = W½ 5 = NE¼
Street Name: 107th St N	IE				$6 = SE\frac{1}{4}$ 7 = SW $\frac{1}{4}$
Urban Legal Description:					8 = NW1⁄4
SITE DATA					
Total # Architectural Fe	atures: 1				
Fieldwork Date:	4/9/2020				
Reconnaissance Survey	<u> </u>	ntensive Surve	У		
Project Title & Superviso Country Schoolhouse Pa					
Report Title & Author(s):					
Additional Information:					
SHSND USE Area of Significance Area of Significance	Ecozone		ified Site	CR Type	2
Recorded By	Kathy W	Vilner	Date	Recorded 5/2	3/2020
(First Nan	ne & Last Name)				(mm/dd/year)

NDCRS ARCHITECTURAL SITE FORM PAGE 2—Feature Data				
Field Code Ackworth School		SITS# 32 RO		
Complete one Page 2 for each	architectural feature at t	he site.		
Architectural Feature # 1				
Construction Date $\frac{1914}{1914}$	Feature Type 9	Condition 7		
Feature Date 3	Context 7	Plan Shape 5		
Structural System 25	Primary Exterior 16	Style Other Style		
Original Owner's Ethnicity	Secondary Exterior	Architect/Builder		
Other Information:				
Foundation Concrete		Stories 1		
Roof/Cornice Gable				
Window Double hung, glass, transoms	above			
Dating Method(s): History				
Feature Preservation Recommen	dation(s) (Check all that ap	ply):		
Individual nomination				
Contributes to a potential district				
No nomination potential				
Will not contribute to a district				
Potential district—feature would	d be a contributing element if oth	ner properties constitute a district		
Thematic nomination potential				
Component of a historic site or landscape				
Moved (specify all applicable choices)—a) relocation occurred within a historic period; b) recreates original site, orientation, landscape, & spatial relationships; c) compatible in context with neighboring structures; d) relocation has damaged eligibility				

____Historical associations require further investigation

Recorded By	Kathy Wilner	Date Recorded	5/23/2020	
	(First Name & Last Name)		(mm/dd/year)	

NDCRS ARCHITECTURAL SITE FORM

PAGE 3—Feature Data

Field Code Ackworth School

SITS# 32 RO

Complete a Page 3 for each feature.

1. Feature Description, Integrity, Eligibility:

The feature is a one room prairie school built in 1914. It was moved to the current location in 1982. The foundation is concrete pillars. The roof of the school is covered with asphalt shingles with a yellow brick chimney located at the south end of the school. The soffits are closed. The school mearues 32 feet north to south and 24 feet east to west.

The siding of the school is metal sheeting. A plywood door is located on the north end of the school with a wood porch giving access. To either side of the door are double hung windows with fixed pane transoms on top of the window. A bank of 6 windows on the west side are also double hung with transom windows at the top. All glass is intact. At the rear (south) of the school there are two more similar windows located closer to the west wall. On the east wall there are two high four pane fixed glass windows. There is a coatroom located directly inside the main door, it is about 2/3 of that end of the building. A 5 panel wood door with a transom windows above it leads into the school at the very west wall. There is another similar door leading into a library and storage room located in the southeast corner of the building. The walls look to be lathe and plaster while the ceiling is pressed tin squares. The floor is tile over hardwood.

There are blackboards on three of the walls, the west wall under the two high windows, 3/4 of the east wall and another located between the two doors on the north wall. The schools is wired for electricity but is not longer connected. There is no wainscoting. Heating was done with both coal and fuel oil. Furniture in the school today are several pews in place of desks so they can use it for gatherings.

Recorded By.

Kathy Wilner

Date Recorded 5/23/2020

(First Name & Last Name)

(mm/dd/year)

NDCRS ARCHITECTURAL SITE FORM PAGE 4—SITE DESCRIPTION

Field Code Ackworth School

SITS# 32 RO

Complete one Page 4 for the entire site.

2. Owner's Contact Information: Ackworth School/Cemetery Association Russell Fauske - President 10817 25th Ave NE Dunseith ND 58329

3. Access (to rural areas):

Drive 9 miles north of Dunseith to 106th St NE, turn left (west) and drive 5 miles west to 25th Ave NE. Turn right (north) and drive one mile north. At the intersection with 107th St. NE turn right and the school is on the south side of the road.

4. Site Area (ft²):

5. Description of SETTING:

The school backs into trees with an open area to the west. There is a cemetery to the northwest and farm fields all other directions.

Recorded By

(First Name & Last Name)

Date Recorded 5/23/2020 (mm/dd/year)

NDCRS ARCHITECTURAL SITE FORM PAGE 5—SITE DESCRIPTION

Field Code Ackworth School

SITS# 32 RO

6. Summary of ALL Site Features & Evaluation of Significance:


7. References/Comments: Kathy Wilner 366 43rd Ave SE Bowdon ND 58418

Photos and information from Glenda and Russell Fauske

Recorded By	Kathy V	Wilner	Date Recorded	5/23/2020
	(First Name & Last Name)		D, D.	(mm/dd/year)

Instructions to complete a digital version of this form: (1) Download a copy to your hard drive; (2) Open the saved blank copy; (3) Fill out the form; (4) Use the Save As command to rename the form appropriately and save; (5) Print and submit to SHSND.

13



North Side

RO

4/9/2020 Ackworth School

West Side




East Side

Ackworth School 4/9/2020 Kathy Wilner RO South Side



Google Maps



Kathy Wilner

Imagery ©2020 CNES / Airbus, Maxar Technologies, USDA Farm Service Agency, Map data ©2020 Feature 200 ft