# NDCRS ARCHITECTURAL FORM PAGE 1

Field Code Plain Township School #2	_ SITS# 32 <sup>F</sup>	1V 446	
Map Quad Grano Map Quad			
LTL T	QQQ of the QQ of the Q QQQ of the QQ of the Q QQQ of the QQ of the Q	1 = N½ 2 = E½ 3 = S½ 4 = W½ 5 = NE¼ 6 = SE¼	
City: Street Number:		7 = SW¼ 8 = NW¼	
Street Name: 40th Ave NW			
Urban Legal Description:			
Total Number of <b>Architectural</b> Features:	1		
Fieldwork Date: 4/10/2022			
Reconnaissance Survey	Intensive Survey		
Project & Principal Investigator: Country School House Project Kathy Wilner 366 43rd Ave SE Bowdon ND 58418			
Contracting Firm or Agency Completing the F	orm:		
Additional Information:			
SHSND USE Component Component Component	Verified Site CR Type	· <u>Z</u>	
Recorded By: Kathy Wilner & Hun	ter Andes Date Recorded	4/12/2022	

#### NDCRS ARCHITECTURAL FORM PAGE 2 – Feature Data

Field Code Plain Township School #2	SITS# 32 RV
Complete one Page 2 for each architectural feature at the site.	
Architectural Feature #1	
Construction Date	
Feature Date1880-1900	
Structural System Wood Frame	
Original Owner's Ethnicity	
Feature Type 9 - School; Church school	
Context <u>Education</u>	
Primary Exterior Wood, Horizontal Siding	
Secondary Exterior	
Condition Fair	
Plan Shape Rectangular	
Style Other Style	
Architect/Builder	
	ies1
Roof/Cornice Gable	
WindowDouble hung, some glass	
Dating Method(s)Estimate	
Miscellaneous Information	
Feature Preservation Recommendation(s) (Check all that appli	y):
Individual nomination	
Contributes to a potential district	
No nomination potential	
Will not contribute to a district	
Potential district—feature would be a contributing element	if other properties constitute a district
Thematic nomination potential	
Component of a historic site or landscape	
Moved (specify all applicable choices)—a) relocation occur site, orientation, landscape, and spatial relationships; c) corelocation has damaged eligibility	
Historical associations require further investigation	
Recorded By:Kathy Wilner & Hunter AndesDa	te Recorded:4/12/2022

## NDCRS ARCHITECTURAL FORM PAGE 3 – Feature Data

Field Code Plain Township School #2	SITS# 32 RV

Complete one Page 3 for each architectural feature at the site.

1. Feature Description, Integrity, Eligibility:

This feature is a one room prairie school sitting on a foundation of slab rocks. It was moved to this location from about a mile south for use as a storage shed. The gable roof has wood shakes with metal capping and finials. The chimney is missing and there is a piece of metal closing the hole. There are two holes on the south slope of the roof along with two holes near the bottom on the south wall that indicate to me that it was likely used as a granary at some point. The soffits are closed.

The siding begins with a rake board under the eaves at the peak ends of the school. The remaining siding is 6 inch wood lap with 6 inch corner trim. The east wall has a side sliding door to give access to the interior of the building. There are several double hung windows in the building, two on the south side, 5 on the north side and two on the west side. Some are covered and there is some glass and framing. Old doors were used to cover several of the windows on the inside of the building. The ceiling is completely gone. The walls have some plaster remaining on the lathe. There is wainscot along the bottom third of the walls. The floor is tongue and groove hardwood. There is no evidence of electricity. No blackboards.

2. Owner's Contact Information: Bruce Bloms 7480 42nd Ave NW Carpio ND 58725

Recorded By:	Kathy Wilner	Date Recorded: 4/12/2022

## NDCRS ARCHITECTURAL FORM PAGE 4 – Site Description

	PAGE 4 – Site Description			
Field Code Plain Township Sc	hool #2	SITS# 32 RV		
3. Site Area (ft²):				
southwest. Farm fields are Carpio on Hwy 28 (46th Av	of an abandoned farm site e all directions. You reach re NW) to 76th St. NW. To	. There are a few trees to the west and this school by driving 5 miles north of urn right and go east 6 miles to 40th Av o see the school on your right.		
5. Summary of ALL Site Feature	s and Evaluation of Significar	nce:		
6. References/Comments: Photos provided by Hunter And Kathy Wilner 366 43rd Ave SE Bowdon ND 58418				
Recorded By:Kathy W	/ilner & Hunter Andes	Date Recorded: 4/12/2022		



North Side


Plain Township School #2

4/10/2022

Kathy Wilner

 $\mathsf{RV}$ 

West Side






South Side

Plain Township School #2 4/10/2022 Kathy Wilner RV

### East Side





Imagery ©2022 CNES / Airbus, Maxar Technologies, USDA/FPAC/GEO, Map data 500 ft ©2022