ĸ

NDCRS 2009

	NDCRS A		TURAL SITE	FORM	
		PAG		SITS# 32_	<u>sh 277</u>
SITE IDENTIFICATION			,		
SITE IDENTIFICATION Field Code Lamont Town Map Quad Denha	nship School	Site	Name <u>LAM</u>	mt Town:	hig school
Map Quad <u>Denher</u> Map Quad	I	Site			
LTL TWP I LTL TWP I LTL TWP I LTL TWP I	۲ ۲	SEC SEC SEC SEC	000 QQQ	QQ	Q <u>5</u> Q Q Q
UTM UTM		_N _E	ZONE NAD 1927	NAD 1983	Subsection: $1 = N\frac{1}{2}$
City: McClusky ND					2 = E½ 3 = S½
Street Number: 391					$4 = W^{1/2}$ 5 = NE ¹ / ₄
Street Name: 12 Ave NE					6 = SE¼ 7 = SW¼
Urban Legal Description:					8 = NW¼
SITE DATA					
Total # Architectural Fea	atures:	1			
Fieldwork Date: 6/	/10/2012	-			
Reconnaissance Survey	<u> </u>	Intensive Sur	vey		
Project Title & Supervisor	r:				
Country Schoolhouse Pr	oject				
Report Title & Author(s):					
Additional Information:					
SHSND USE Area of Significance Area of Significance	Ecozone Ecozone		/erified Site Ion-Site	CR Тур	e _2_
Recorded By		Wilner	Date	Recorded	11/14/2012
(First Nam	e & Last Name)				(mm/dd/year)

NDCRS 2009

NDCRS	ARCHITECTURAL SITE FORM
	PAGE 2— <i>Feature Data</i>

Field Code Lamont Township School	SITS# <u>32_SH</u>				
Complete one Page 2 for each architectural feature at the site.					
Architectural Feature #1					
Construction Date	Feature Type <u>9</u>	Condition 4			
Feature Date	Context 7	Plan Shape <u>5</u>			
Structural System 25	Primary Exterior <u>26</u>	Style <u>Other Style</u>			
Original Owner's Ethnicity	Secondary Exterior	Architect/Builder			
Other Information:					
Foundation Cement blocks		Stories <u>1</u>			
Roof/Cornice Gable, shed roof on the er	ntry				
Window Double Hung		· · · · · · · · · · · · · · · · · · ·			
Dating Method(s): School records					
Feature Preservation Recommendation(s) (Check all that apply):					
Individual nomination					
Contributes to a potential district					
No nomination potential					
——Will not contribute to a district					

____Potential district—feature would be a contributing element if other properties constitute a district

____Thematic nomination potential

-----Component of a historic site or landscape

Moved (specify all applicable choices)—a) relocation occurred within a historic period; b) recreates original site, orientation, landscape, & spatial relationships; c) compatible in context _____with neighboring structures; d) relocation has damaged eligibility

____Historical associations require further investigation

Recorded By	Kathy Wilner	Date Recorded	11/14/2012
(Fir	rst Name & Last Name)		(mm/dd/year)

NDCRS 2009

NDCRS ARCHITECTURAL SITE FORM PAGE 3—Feature Data

Field Code Lamont Township School

SITS# 32 SH

Complete a Page 3 for each feature.

1. Feature Description, Integrity, Eligibility:

The feature is a one room prairie school sitting in a farm yard. The school has a shed entry, measuring 10 by 5 feet, to the east with the door facing south. The shed roof is covered with asphalt shingles and the maid body of the school has shakes on the roof. There is a newer concrete block chimney in the middle of the gable roof. The roof has metal ridge cap running the length. There is an 8 inch wide trim board under the peak of the roof. The siding is 6 inch wide lap with 6 inch corner trim boards. The school measures 22 feet east to west and 18 feet north to south. It looks like the shed may have been added at a later date as the inside of that entry has the same lap siding as the rest of the school. there is one small window in the entry with no glass in it. There is a concrete pad just outside the shed door. The inside entry door is wood with a window in the top 1/3. The main body of the school was broken up with walls and this building was used as a house at one point. The main walls are lath and plaster with wall board used in the dividing walls. The ceiling is missing is some places and in one room there was an attempt made to put in a dropped ceiling. The floor has linoleum with some rooms back to hard wood. There are electric fixtures in the ceiling indicating electricity. The windows of the main body of the school all have the glass intact. Schools in Lamont Township closed in 1960. We are not sure if this school was originally a Lamont Township school or not. The owner did not know where it came from.

Recorded By Kathy Wilner (First Name & Last Name)

Date Recorded _____11/14/2012

(mm/dd/year)

NDCRS 2009

NDCRS ARCHITECTURAL SITE FORM PAGE 4—SITE DESCRIPTION

Field Code Lamont Township School

SITS# 32_SH____

Complete one Page 4 for the entire site.

2. Owner's Contact Information:

Neal Heitzmann 391 12th Ave NE McClusky ND 58463

3. Access (to rural areas):

Highway 200 at 12th Ave NE, turn to the south and drive 1 miles south. Cross the next road, 4th St NE, and the farm yard is just to the right. The school is in the yard.

4. Site Area (ft²):

5. Description of **SETTING**:

The land rolls away from the school the west and south west where there is a slough. The building sits in a farm yard and there is a machine shed directly south. There is a house to the southeast and it is hilly to the north. Cattle are to the northeast with fields straight north.

Recorded By Kathy Wilner Date Recorded 11/14/2012
(First Name & Last Name) (mm/dd/year)

NDCRS 2009

NDCRS ARCHITECTURAL SITE FORM **PAGE 5—SITE DESCRIPTION**

Field Code Lamont Township School

SITS# 32_SH_____

6. Summary of ALL Site Features & Evaluation of Significance:


7. References/Comments: Kathy Wilner 366 43rd Ave SE Bowdon ND 58418


Recorded By (First Name & Last Name)


Kathy Wilner

_ Date Recorded _

11/14/2012 (mm/dd/year)







SHERIDAN COUNTY