÷.

**NDCRS 2009** 

NDCRS ARCHITECTURAL SITE FORM					
	PAGE 1	SITS# 32_S	н <u>280</u>		
SITE IDENTIFICATION	0	1 1	5.1.1.421		
Field Code Boone Township School #4	Site Name		Jehn #4		
Map Quad_ <u>Pony_bulch</u> Map Quad	Site Name				
LTL TWP R S	EC 27 QQQ 5   SEC QQQ QQQ    SEC QQQ  QQQ	00	Q <u>5</u> Q Q		
UTM N UTM E		NAD 1983	Subsection: $1 = N\frac{1}{2}$		
City: Goodrich ND	. <u></u>		$2 = E\frac{1}{2}$ $3 = S\frac{1}{2}$		
Street Number: Approx. 781			4 = W <sup>1</sup> ⁄ <sub>2</sub> 5 = NE <sup>1</sup> ⁄ <sub>4</sub>		
Street Name: 22nd Ave NE			6 = SE <sup>1</sup> / <sub>4</sub> 7 = SW <sup>1</sup> / <sub>4</sub>		
Urban Legal Description:			8 = NW <sup>1</sup> / <sub>4</sub>		
SITE DATA					
Total # Architectural Features:1					
Fieldwork Date: 5/22/2012					
Reconnaissance Survey 🖌 Ir	ntensive Survey				
Project Title & Supervisor:					
Country Schoolhouse Project					
Report Title & Author(s):					
Additional Information:					
SHSND USE Area of Significance Ecozone Area of Significance	Verified Site Non-Site	_ CR Type	2		
Recorded By Kathy M (First Name & Last Name)	/ilner Date	Recorded 1	1/15/2012 (mm/dd/year)		

**NDCRS 2009** 

NDCRS ARCHITECTURAL SITE FORM
PAGE 2—Feature Data

Field Code Boone Township School #4		SITS# 32 <u>SH</u>
Complete one Page 2 for eac	c <u>h architectural feature</u> a	at the site.
Architectural Feature #1	_	
Construction Date	Feature Type <u>9</u>	Condition 5
Feature Date <u>3</u>	Context 7	Plan Shape <u>5</u>
Structural System 25	Primary Exterior 26	Style <u>Other Style</u>
Original Owner's Ethnicity	Secondary Exterior	Architect/Builder
Other Information: Foundation Poured Concrete		Stories1
Roof/Cornice_Hip		
Window All Covered		
Dating Method(s): School records		
Feature Preservation Recomm		
Individual nomination		
Contributes to a potential dis	strict	
No nomination potential		
—Will not contribute to a distric	ct	
Potential district—feature wo	ould be a contributing element i	f other properties constitute a district
Thematic nomination potent	ial	

——Component of a historic site or landscape

Moved (specify all applicable choices)—a) relocation occurred within a historic period; b) recreates original site, orientation, landscape, & spatial relationships; c) compatible in context \_\_\_\_with neighboring structures; d) relocation has damaged eligibility

\_\_\_\_\_Historical associations require further investigation

Recorded By	Kathy Wilner	<b>Date Recorded</b>	11/15/2012
-	(First Name & Last Name)		(mm/dd/year)

**NDCRS 2009** 

# NDCRS ARCHITECTURAL SITE FORM PAGE 3—Feature Data

Field Code Boone Township School #4

SITS# 32 SH

#### Complete a Page 3 for each feature.

#### 1. Feature Description, Integrity, Eligibility:

The feature is a one room prairie school sitting in the corner of a wheat field. The hip roof has shakes with many missing. All the roofing angles are covered with metal ridge cap. The chimney is starting to fall away with some brick missing on the southwest corner. The building has 6 inch lap siding with metal corner trim. There is plywood over all the windows of the main body of the school. The school sits on a basement. The east side has an opening with steps that allow access to the basement, there is also an opening on this side for delivery of fuel. Any basement windows are also covered. There was electricity in the school and the flag pole still stands on the south side of the building. The entry porch is wood and has fallen away from the school. I could see into the entry to note that the walls are lathe and plaster with wainscoting. The floor is tongue and groove hardwood. In visiting with a student of the school I learned that the coat room was located in the basement. At one time they also used a coat room on the main level to the right of the entry door. There were 5 windows that faces to the east and the blackboards were on the west and north walls. There were windows for light in the entry way as well as to either side of the entry as well. Heat was coal first, later an oil burner before having a propane space heater for warmth. This school closed in 1960.

Recorded By Kathy Wilner Date Recorded 11/15/2012 (First Name & Last Name) (mm/dd/year)

NDCRS 2009

### NDCRS ARCHITECTURAL SITE FORM PAGE 4—SITE DESCRIPTION

Field Code Boone Township School #4

SITS# 32\_SH\_\_\_\_

11/15/2012 (mm/dd/year)

#### Complete one Page 4 for the entire site.

2. Owner's Contact Information:

Gerald Peerboom 311 16th Ave SE Goodrich ND 58444

3. Access (to rural areas):

Highway 200 north of Goodrich, drive north on 20th Ave NE 3 miles and turn right to drive east on 8th Ave NE, 2 miles. The school will be on your right.

4. Site Area (ft<sup>2</sup>):\_\_\_\_\_

5. Description of SETTING:

There is a farm 1/4 mile to the north, another farm a mile and 1/2 to the west and open farm land east and south.

Recorded By Kathy Wilner Date Recorded \_\_\_\_\_\_ Date Recorded \_\_\_\_\_\_

**NDCRS 2009** 

## NDCRS ARCHITECTURAL SITE FORM PAGE 5—SITE DESCRIPTION

Field Code Boone Township School #4

SITS# 32\_SH\_\_\_\_\_

6. Summary of ALL Site Features & Evaluation of Significance:

7. References/Comments: Kathy Wilner 366 43rd Ave SE Bowdon ND 58418

Recorded By Kathy Wilner (First Name & Last Name)


\_ Date Recorded \_


11/15/2012 (mm/dd/year)




Boone Twsp. School #4	East Side	05/22/2012 Kathy Wilner	SH
Boone Twsp. School #4	South Side	05/22/2012 Kathy Wilner	SH











SHERIDAN COUNTY C COPYRIGHT 2011 GREAT PLAINS DIRECTORY SERVICE