

NDCRS ARCHITECTURAL SITE FORM PAGE 1

SITS# 32 SI 118

SITE IDENTIFICATION

Field Code Roger Creek School

Site Name Roger Creek School
Site Name Kaispa School

Map Quad Lookout Butte SE
Map Quad _____

LTL	TWP	<u>130</u> R	<u>85</u>	SEC	<u>32</u>	QQQ	<u>5</u>	QQ	<u>5</u>	Q	<u>5</u>
LTL	TWP	_____	R _____	SEC	_____	QQQ	_____	QQ	_____	Q	_____
LTL	TWP	_____	R _____	SEC	_____	QQQ	_____	QQ	_____	Q	_____
LTL	TWP	_____	R _____	SEC	_____	QQQ	_____	QQ	_____	Q	_____

UTM _____ N ZONE _____
UTM _____ E NAD 1927 _____ NAD 1983 _____

- | |
|-------------|
| Subsection: |
| 1 = N½ |
| 2 = E½ |
| 3 = S½ |
| 4 = W½ |
| 5 = NE¼ |
| 6 = SE¼ |
| 7 = SW¼ |
| 8 = NW¼ |

City: perhaps McIntosh SD

Street Number: 7 miles north of the SD border on Highway 31

Street Name: 95th St. SW and Highway 31

Urban Legal Description: _____

SITE DATA

Total # **Architectural** Features: 1

Fieldwork Date: 10/29/2012

Reconnaissance Survey Intensive Survey

Project Title & Supervisor:
Country Schoolhouse Project

Report Title & Author(s): _____

Additional Information: _____

SHSND USE

Area of Significance <u>2</u>	Ecozone <u>23</u>	Verified Site _____	CR Type <u>2</u>
Area of Significance _____	Ecozone _____	Non-Site _____	
Area of Significance _____			

Recorded By Kathy Wilner Date Recorded 11/17/2012
(First Name & Last Name) (mm/dd/year)

Instructions to complete a digital version of this form: (1) Download a copy to your hard drive; (2) Open the saved blank copy; (3) Fill out the form; (4) Use the Save As command to rename the form appropriately and save; (5) Print and submit to SHSND.

NDCRS ARCHITECTURAL SITE FORM PAGE 2—Feature Data

Field Code Roger Creek School

SITS# 32 SI

Complete one Page 2 for each architectural feature at the site.

Architectural Feature # 1

Construction Date _____

Feature Type 9

Condition 4

Feature Date 2

Context 7

Plan Shape 5

Structural System 25

Primary Exterior 26

Style Other Style

Original Owner's Ethnicity _____

Secondary Exterior _____

Architect/Builder _____

Other Information:

Foundation Field stone with some concrete mixed in Stories 1

Roof/Cornice Gable

Window Double hung

Dating Method(s): former student professional estimate Lm

Feature Preservation Recommendation(s) (Check all that apply):

- Individual nomination
- Contributes to a potential district
- No nomination potential
- Will not contribute to a district
- Potential district—feature would be a contributing element if other properties constitute a district
- Thematic nomination potential
- Component of a historic site or landscape
- Moved (specify all applicable choices)—a) relocation occurred within a historic period; b) recreates original site, orientation, landscape, & spatial relationships; c) compatible in context with neighboring structures; d) relocation has damaged eligibility
- Historical associations require further investigation

Recorded By Kathy Wilner Date Recorded 11/17/2012
(First Name & Last Name) (mm/dd/year)

Instructions to complete a digital version of this form: (1) Download a copy to your hard drive; (2) Open the saved blank copy; (3) Fill out the form; (4) Use the Save As command to rename the form appropriately and save; (5) Print and submit to SHSND.

NDCRS ARCHITECTURAL SITE FORM
PAGE 3—Feature Data

Field Code Roger Creek SchoolSITS# 32 SI**Complete a Page 3 for each feature.****1. Feature Description, Integrity, Eligibility:**

The feature is a one room prairie school sitting in a pasture. At one point it was also called Knispel School. The building shows little or no paint. The roof has a few shakes remaining, otherwise it is covered with board lumber. There is a metal ridge cap running the length of the roof. There is a chimney at the north end, beginning to crumble. The building is clad in 6 inch lap siding with 4 inch corner trim boards. The lap siding is missing where they drilled holes to blow insulation into the school walls. On the west end of the school it looks like a window was covered but I don't see where that window was inside the school. There is a wide trim board running just under roof at the peak ends. The soffit is open on the roof overhang on the north and south sides of the school. A broken wood step leads into the school. The entry is the first of two small rooms at the east end of the school. The 2nd room, in the northeast corner, was for fuel storage and there is a hinged opening on the north wall for fuel delivery. Both of these rooms have plain board walls. The entry door was a multi-panel door and most of the panels are gone. Hardware looks very old. The door into the main room of the school is in a little better shape. The school is mostly trashed. The windows on the south wall are replacement windows, they are double hung but shorter than the originals. There is one room at the northwest corner of the school room and another at the northeast corner of that room as well. Blackboards run along the north wall between these two windows and are on most of the west wall. The ceiling tiles have mostly fallen in but I can see that the ceiling has a curved look at the north and south walls where it curved in from the wall to meet the ceiling. There is some wall board on the walls, much of the south side is missing. I saw electric wires outside the school as well as an outlet inside. There is lots of natural light coming through all the uncovered cracks in the roof. The floor is tongue and groove hardwood. According to a student of the school it closed in the mid 1950's.

Recorded By Kathy Wilner Date Recorded 11/17/2012
(First Name & Last Name) (mm/dd/year)

Instructions to complete a digital version of this form: (1) Download a copy to your hard drive; (2) Open the saved blank copy; (3) Fill out the form; (4) Use the Save As command to rename the form appropriately and save; (5) *Print* and submit to SHSND.

**NDCRS ARCHITECTURAL SITE FORM
PAGE 4—SITE DESCRIPTION**

Field Code Roger Creek School

SITS# 32 SI

Complete one Page 4 for the entire site.

2. Owner's Contact Information:

Toss Schaffer
9590 52nd Ave
McIntosh SD

3. Access (to rural areas):

Highway 31, 28 miles south of Highway 21 west of Flasher, 28 miles to 95th St SW. The school is on the right.

4. Site Area (ft²): _____

5. Description of **SETTING**:

There is an abandoned farm site to the NE, it is sitting pasture land that rolls up to the west. The country side is rugged and hilly with buttes in the distance.

Recorded By Kathy Wilner Date Recorded 11/17/2012
(First Name & Last Name) (mm/dd/year)

Instructions to complete a digital version of this form: (1) Download a copy to your hard drive; (2) Open the saved blank copy; (3) Fill out the form; (4) Use the Save As command to rename the form appropriately and save; (5) Print and submit to SHSND.

**NDCRS ARCHITECTURAL SITE FORM
PAGE 5—SITE DESCRIPTION**

Field Code Roger Creek School

SITS# 32 SI

6. Summary of ALL Site Features & Evaluation of Significance:

7. References/Comments:

Kathy Wilner
366 43rd Ave SE
Bowdon ND 58418

Recorded By Kathy Wilner Date Recorded 11/17/2012
(First Name & Last Name) (mm/dd/year)

Instructions to complete a digital version of this form: (1) Download a copy to your hard drive; (2) Open the saved blank copy; (3) Fill out the form; (4) Use the Save As command to rename the form appropriately and save; (5) *Print* and submit to SHSND.



South Side

Roger Creek School

10/29/2012

Kathy Wilner

SI

East Side





North Side

Roger Creek School

10/29/2012

Kathy Wilner

SI

West Side






Address **Sioux**
ND

Highway 31 and 95th Street

Section 32, T. 130 N., R. 85 W.



©2012 Google

Map data ©2012 Google

Roger Creek School 10/29/2012 Kathy Wilner 51