1

## NDCRS ARCHITECTURAL SITE FORM PAGE 1 SITE# 32 SK 1217

SITE IDENTIFICATION			3113# 32_0	1/2/1
Field Code Antelope School	Site N	ame		
Map Quad <u>Antel npe</u> Map Quad	Site N	ame	· · · /· · · · · · · · · · · · · · · ·	
LTL TWP 139 R 91 LTL TWP R R LTL TWP R LTL TWP R	SEC <u>19</u> SEC <u> </u>	000	00	Q 5 Q Q
UTM I		ZONE NAD 1927	NAD 1983	Subsection: $1 = N\frac{1}{2}$
City:				$2 = E^{1/2}$ $3 = S^{1/2}$
Street Number:				4 = W <sup>1</sup> / <sub>2</sub> 5 = NE <sup>1</sup> / <sub>4</sub>
Street Name: 83rd Ave SW				6 = SE¼ 7 = SW¼
Urban Legal Description:				8 = NW¼
SITE DATA				
Total # Architectural Features:1				
Fieldwork Date: 4/13/2016				
Reconnaissance Survey	ntensive Surv	ey		
Project Title & Supervisor:				
Country Schoolhouse Project				
Report Title & Author(s):				
Additional Information:				
SHSND USE Area of Significance Ecozone Area of Significance		erified Site	_ CR Type	2
Recorded By Kathy V	Vilner	Date	Recorded	/23/2017
(First Name & Last Name)				(mm/dd/year)

**NDCRS 2009** 

NDCRS ARCHITECTURAL SITE FORM PAGE 2—Feature Data					
Field Code Antelope School		SITS# 32_SK			
Complete one Page 2 for eac	h architectural feature a	t the site.			
Architectural Feature #1					
Construction Date	Feature Type <u>9</u>	Condition <u>6</u>			
Feature Date 2	Context 7	Plan Shape <u>5</u>			
Structural System 25	Primary Exterior <u>26</u>	Style <u>Other Style</u>			
Original Owner's Ethnicity	Secondary Exterior	Architect/Builder			
Other Information:					
Foundation Poured concrete		Stories			
Roof/Cornice Hip with shed on addition	on, gable on dormer	=			
Window Double hung, glass					
Dating Method(s)= estimat	و				
Feature Preservation Recommendation(s) (Check all that apply):					

\_\_\_\_Contributes to a potential district

\_\_\_\_No nomination potential

\_\_\_\_Will not contribute to a district

\_\_\_\_Potential district—feature would be a contributing element if other properties constitute a district

\_\_\_\_ Thematic nomination potential

----- Component of a historic site or landscape

Historical associations require further investigation

Recorded By	Kathy Wilner	<b>Date Recorded</b>	1/23/2017
(F	First Name & Last Name)		(mm/dd/year)

## NDCRS ARCHITECTURAL SITE FORM PAGE 3—Feature Data

Field Code Antelope School

SITS# 32 SK

#### Complete a Page 3 for each feature.

#### 1. Feature Description, Integrity, Eligibility:

The feature is a one room prairie school on a poured concrete foundation. The hip roof and shed roof are covered with wood shakes, the gable roof of the dormer is covered with asphalt shingles. There is metal capping at the peak of the hip roof with finials at both ends. There is metal capping on all the hips as well. There is a red brick chimney on the east facing slope of the roof just west of the dormer. The dormer most likely was the bell tower, has two openings to the east with rounded tops. At the peak of the dormer roof is a flagpole. The building measures 34 feet west to east and 20 feet north to south with the shed measuring 10 feet by 10 feet.

There is a wide trim board under the soffits on all four side sof the school. The remainder of the siding is 6 inch wood lap with 6 inch wood corner trim. The shed has a small window opening on the north side, glass intact and a door on the south side that opens into a room with no finished walls or ceiling, likely used for fuel storage. There are two double hung, two over two, smaller windows with glass on the east wall to either side of the entry door. The south wall has 6 large double hung, two over two, windows with storms, again glass intact. The entry door is a broken wood door with a transom above it. The transom has two rows of 5 small panes of glass in it. The entry foyer has two 5 panel doors to either side as you enter, the door right goes to a coat room and the door to the left goes into the school proper. There are decorative cornices above the doors and all the windows. The large windows have shades that pull down from the top of the window frame. The walls and ceiling are lathe and plast with wainscot at the bottom third. A blackboard runs along the west wall and corner to more on about 1/4 of the north wall. The floor is tongue and groove hardwood. There is a furnace sitting near the east interior wall. Conduit and light fixtures suggest electricity.

Recorded By Kathy Wilner Date Recorded 1/23/2017
(First Name & Last Name) (mm/dd/year)

**NDCRS 2009** 

# NDCRS ARCHITECTURAL SITE FORM PAGE 4—SITE DESCRIPTION

Field Code Antelope School

SITS# 32\_SK\_\_\_\_\_

### Complete one Page 4 for the entire site.

2. Owner's Contact Information:

Craig Fisher 8330 39th St SW Richardton ND 58652

3. Access (to rural areas):

Access to this school is I 94 at exit 90, go south on 83rd Ave SW about 1/2 mile to see the school at the intersection with 39th St SW

4. Site Area (ft<sup>2</sup>):\_\_\_\_\_

5. Description of SETTING:

There is a large farm to the west, gravel pits to the east and farmland all directions.

Recorded By Kathy Wilner Date Recorded 1/23/2017
(First Name & Last Name) (mm/dd/year)

NDCRS 2009

# NDCRS ARCHITECTURAL SITE FORM PAGE 5—SITE DESCRIPTION

Field Code Antelope School

SITS# 32\_SK\_\_\_\_\_

6. Summary of ALL Site Features & Evaluation of Significance:

7. References/Comments: Kathy Wilner 366 43rd Ave SE Bowdon ND 58418

Recorded By Kathy Wilner Date Recorded 1/23/2017 (First Name & Last Name) (mm/dd/year)



# East Side





South Side

Antelope School 4/13/2016 Kathy Wilner DU West Side

## **b** bing maps

#### Notes

Antelope School 4/13/2016 Kathy Wilner DU



b bing

& 2016 Microsoft Corporation & 2016 HERE

