NDCRS ARCHITECTURAL SITE FORM PAGE 1

	PAGE I	SITS# 32_S	1 3/2
SITE IDENTIFICATION		0110# 32 <u> </u>	<u> </u>
Field Code Rainy School			
Map Quad <u>Daglum SE</u> Map Quad	Site Name		
LTLTWP R SEC LTLTWP R SEC	2 14 QQQ 5 QQQ QQQ QQQ	QQ	Q <u>6</u> Q Q
UTMN	ZONE NAD 1927		Subsection: 1 = N½
City:			2 = E½ 3 = S½
Street Number:			4 = W½ 5 = NE¼
Street Name: 130th Ave SE			6 = SE ¹ / ₄ 7 = SW ¹ / ₄
Urban Legal Description:			8 = NW ¹ / ₄
SITE DATA			
Total # Architectural Features: 1			
Fieldwork Date: 6/21/2016			
Reconnaissance Survey Inte	nsive Survey		
Project Title & Supervisor: Country Schoolhouse Project			
Report Title & Author(s):			
Additional Information:			
Area of Significance Area of Significance Ecozone	Verified Site	. CR Type	_2_
Recorded By Kathy Will	ner Date I	Recorded	1/25/2017
(First Name & Last Name)			(mm/dd/year)

NDCRS ARCHITECTURAL SITE FORM PAGE 2—Feature Data

Field Code Rainy School		SITS# 32 SL		
Complete one Page	2 <u>for each architectural f</u>	eature at the site.		
Architectural Feature	#1			
Construction Date	Feature Type	9 Condition 4		
Feature Date 3	Context 7	Plan Shape		
Structural System 25	Primary Exterior	26 Style Other Style		
Original Owner's Ethnicity	Secondary Exter	ior Architect/Builder		
Other Information:				
		Stories1		
Window Openings, one sh	outtered,little framing, no glass			
Dating Method(s): Estimat	te .			
Feature Preservation F	Recommendation(s) (Check	k all that apply):		
Contributes to a p	otential district			
No nomination pot	tential			
—Will not contribute to a district				
Potential district—feature would be a contributing element if other properties constitute a district				
Thematic nomination potential				
——Component of a historic site or landscape				
Moved (specify all applicable choices)—a) relocation occurred within a historic period; b) recreates original site, orientation, landscape, & spatial relationships; c) compatible in context —with neighboring structures; d) relocation has damaged eligibility				
Historical associat	ions require further investigation	n		
Recorded By (First Name	Kathy Wilner	Date Recorded1/25/2017		

NDCRS ARCHITECTURAL SITE FORM PAGE 3—Feature Data

Field Code Rainy School		SITS# 32	SL

Complete a Page 3 for each feature.

1. Feature Description, Integrity, Eligibility:

The feature is a one room prairie school, cannot see the foundation. I did not get close to this school. The hip roof of the school and the half hip of the entry have wood shakes with much of the planking showing. Metal capping is here and there at the peak and the hips. There is a tall red brick chimney, with stucco or cement covering some of it, that is held up by cables attached the roof on the north slope. On the south slope and onto the entry roof there is a large bell tower. The base of the tower is finished with wood shakes up to the housing that has four corner posts supporting the roof. All sides of the bell tower are open. The pyramidal roof has wood shade and is topped with a flagpole. Soffits are closed.

There is a wide trim board under the soffits on all sides of the school and entry. The remainder of the siding appears to be 6 inch wood lap with 6 inch corner trim, no paint. There are several double hung window openings, very little framing and no glass. On the north wall are two sets of two windows, the east side has a bank of four, a single window is on the west side of the entry. The entry has a door opening, door is gone, and two smaller window openings. The walls and ceiling (seen from the road) are lather and plaster with much falling in. Conduit on the east side of the entry would suggest electricity.

Recorded By	Kathy Wilner	Date Recorded	1/25/2017
-	(First Name & Last Name)		(mm/dd/year)

NDCRS ARCHITECTURAL SITE FORM PAGE 4—SITE DESCRIPTION

Field Code Rainy School	SITS# 32_SL
Complete one Page 4 for the entire si	<u>te</u> .
2. Owner's Contact Information:	
3. Access (to rural areas):	
	iles to Highway 21. Turn right and drive 6 miles east to about a mile and 1/2 to see the school on the west side
4. Site Area (ft²):	
5. Description of SETTING : There is a farm with lots of trees directly south, and farm fields and pasture other directions.	outtes around with West Rainy Butte to the southeast
Recorded By Kathy Wilner (First Name & Last Name)	Date Recorded 1/25/2017 (mm/dd/year)

NDCRS ARCHITECTURAL SITE FORM PAGE 5—SITE DESCRIPTION

Field Code Rainy School		SITS# 32_	SL	
6. Summary of ALL Site Features & Evaluation of Significance:				
7. References/Comments: Kathy Wilner				
366 43rd Ave SE				
Bowdon ND 58418				
Recorded By (First Name & L	Kathy Wilner	Date Recorded	1/25/2017 (mm/dd/year)	



South Side
Rainy School
6/21/2016
Kathy Wilner
SL

West Side





East Side

Rainy School

East Side

6/21/2016

Kathy Wilner

SL

North Side



b bing maps

Notes

Rainy School

6-21-2016

Kathy wilner

SL





Feature