

NDCRS ARCHITECTURAL SITE FORM PAGE 1

SITS# 32 SN 804

SITE IDENTIFICATION

Field Code Ypsilanti Township School Site Name Ypsilanti Township School

Map Quad Marion NW
Map Quad _____

LTL	TWP	<u>138</u>	R	<u>62</u>	SEC	<u>35</u>	QQQ	<u>8</u>	QQ	<u>8</u>	Q	<u>8</u>
LTL	TWP	_____	R	_____	SEC	_____	QQQ	_____	QQ	_____	Q	_____
LTL	TWP	_____	R	_____	SEC	_____	QQQ	_____	QQ	_____	Q	_____
LTL	TWP	_____	R	_____	SEC	_____	QQQ	_____	QQ	_____	Q	_____

UTM _____ N ZONE _____
UTM _____ E NAD 1927 _____ NAD 1983 _____

City: Ypsilanti

Street Number: _____

Street Name: 94th Ave SE

Urban Legal Description: _____

Subsection:
1 = N $\frac{1}{2}$
2 = E $\frac{1}{2}$
3 = S $\frac{1}{2}$
4 = W $\frac{1}{2}$
5 = NE $\frac{1}{4}$
6 = SE $\frac{1}{4}$
7 = SW $\frac{1}{4}$
8 = NW $\frac{1}{4}$

SITE DATA

Total # **Architectural** Features: 1

Fieldwork Date: 11/4/2014

Reconnaissance Survey Intensive Survey _____

Project Title & Supervisor:
Country Schoolhouse Project

Report Title & Author(s):

Additional Information: _____

SHSND USE

Area of Significance <u>2</u>	Ecozone <u>18</u>	Verified Site <u>1</u>	CR Type <u>2</u>
Area of Significance _____	Ecozone _____	Non-Site _____	
Area of Significance _____			

Recorded By Kathy Wilner Date Recorded 2/21/2015
(First Name & Last Name) (mm/dd/year)

Instructions to complete a digital version of this form: (1) Download a copy to your hard drive; (2) Open the saved blank copy; (3) Fill out the form; (4) Use the Save As command to rename the form appropriately and save; (5) Print and submit to SHSND.

NDCRS ARCHITECTURAL SITE FORM
PAGE 2—Feature Data

Field Code Ypsilanti Township School

SITS# 32 SN

Complete one Page 2 for each architectural feature at the site.

Architectural Feature # 1

Construction Date Feature Type 9 Condition 4
Feature Date 2 Context 7 Plan Shape 5
Structural System 25 Primary Exterior 26 Style Other Style
Original Owner's Ethnicity Secondary Exterior Architect/Builder

Other Information:

Foundation Concrete Stories 1

Roof/Cornice Gable

Window likely double hung, most gone

Dating Method(s): professional estimate

Feature Preservation Recommendation(s) (Check all that apply):

- Individual nomination
Contributes to a potential district
No nomination potential
Will not contribute to a district
Potential district—feature would be a contributing element if other properties constitute a district
Thematic nomination potential
Component of a historic site or landscape
Moved (specify all applicable choices)—a) relocation occurred within a historic period; b) recreates original site, orientation, landscape, & spatial relationships; c) compatible in context with neighboring structures; d) relocation has damaged eligibility
Historical associations require further investigation

Recorded By Kathy Wilner Date Recorded 2/21/2015
(First Name & Last Name) (mm/dd/year)

Instructions to complete a digital version of this form: (1) Download a copy to your hard drive; (2) Open the saved blank copy; (3) Fill out the form; (4) Use the Save As command to rename the form appropriately and save; (5) Print and submit to SHSND.

NDCRS ARCHITECTURAL SITE FORM
PAGE 3—Feature Data

Field Code Ypsilanti Township SchoolSITS# 32 SN**Complete a Page 3 for each feature.****1. Feature Description, Integrity, Eligibility:**

The feature is a wood framed one room prairie school sitting on a concrete foundation. The roof is asphalt shingles on wood sheathing on the west slope of the gable roof and hardly a shingle on the roof on the east. There is metal capping on much of the peak. The east side has many holes. The chimney is gone. The soffits were closed. The building measures 30 feet north to south and 18 feet east to west. The entry measures 4 feet north to south and 6 feet east to west.

There is a wide header under the eaves at the peak ends of the main body of the school as well as the entry porch. The siding is 6 inch wood lap with 4 inch wood corner trim, all with no paint. On the east side there are two vertical boards that might have been added for support. The entire building looks to be falling into itself about the middle of the school. Several siding boards on the lower part of the east and west walls are missing or broken. There are 2 x 4's on the east and west that may have had wires attached inside to keep the school together. The porch has a wide open doorway and the door is broken and lying on the concrete step. The door leads into a shallow entry with a wall directly in front of you as you step in. Doors to either side lead into coat rooms. There are openings into these rooms that have little frame left and not glass. The door into the school are from the left and right coat rooms. There is wainscot in these rooms as well as the main body of the school. Two windows opening are on the north side of the school, three window openings along the west wall, all framing and glass gone. The school room itself has lathe and plaster walls, much of it fallen away. The ceiling has little or nothing left as it too has fallen in. Remnants of the black board can be seen on the east wall. There is light fixture hanging from a few of the ceiling boards indicating electricity.

Recorded By Kathy Wilner Date Recorded 2/21/2015
(First Name & Last Name) (mm/dd/year)

Instructions to complete a digital version of this form: (1) Download a copy to your hard drive; (2) Open the saved blank copy; (3) Fill out the form; (4) Use the Save As command to rename the form appropriately and save; (5) Print and submit to SHSND.

**NDCRS ARCHITECTURAL SITE FORM
PAGE 4—SITE DESCRIPTION**

Field Code Ypsilanti Township School

SITS# 32 SN

Complete one Page 4 for the entire site.

2. Owner's Contact Information:

3. Access (to rural areas):

From Ypsilanti drive east 4 miles on 43rd St SE, turn right and drive south on 94th Ave SE 3 miles. It is on the east side of the road.

4. Site Area (ft²): _____

5. Description of **SETTING**:

Wide open country with fields all ways. Farm sites can be seen at a distance to the west and north.

Recorded By Kathy Wilner Date Recorded 2/21/2015
(First Name & Last Name) (mm/dd/year)

Instructions to complete a digital version of this form: (1) Download a copy to your hard drive; (2) Open the saved blank copy; (3) Fill out the form; (4) Use the Save As command to rename the form appropriately and save; (5) *Print* and submit to SHSND.

**NDCRS ARCHITECTURAL SITE FORM
PAGE 5—SITE DESCRIPTION**

Field Code Ypsilanti Township School

SITS# 32 SN

6. Summary of ALL Site Features & Evaluation of Significance:

7. References/Comments:

Kathy Wilner
366 43rd Ave SE
Bowdon ND 58418

Recorded By Kathy Wilner Date Recorded 2/21/2015
(First Name & Last Name) (mm/dd/year)

Instructions to complete a digital version of this form: (1) Download a copy to your hard drive; (2) Open the saved blank copy; (3) Fill out the form; (4) Use the Save As command to rename the form appropriately and save; (5) Print and submit to SHSND.



South Side

Ypsilanti Township School

11/4/2014

Kathy Wilner

SN

East Side





West Side

Ypsilanti Township School


11/4/2014

Kathy Wilner

SN

North Side





Ypsilanti Township School 11-4-2014 Kathy Wilner SN