NDCRS ARCHITECTURAL SITE FORM

Field Code Schultz School	SITS# 32 SN 825
SITE IDENTIFICATION Map Quad Woodworth	Site Name Schultz School
Map Quad	Site Name
LTLTWP	QQQ QQ Q QQQ QQ Q
NAD 1983, UTM 5223047 N NAD 1983, UTM 477094 E	ZONE 14N Subsection: 1 = N½
City: Woodworth	2 = E½ 3 = S½
Street Number:	$4 = W\frac{1}{2}$ $5 = NE\frac{1}{4}$
Street Name: 56th Ave SE	6 = SE¼ 7 = SW¼
Urban Legal Description:	8 = NW1/4
SITE DATA	
Total # Architectural Features: 1	
Fieldwork Date: 9/2/2018	
Reconnaissance Survey Inter	nsive Survey
Project & Principal Investigator: Country Schoolhouse Project	
Report Title & Author(s):	
Contracting firm or Agency completing the for	m:
Additional Information:	
2100.002	
Area of Significance Area of Significance Ecozone Ecozone Ecozone	9 Verified Site 1 CR Type 2
Kathy Wilner	Date Recorded 1/22/2019
Recorded By (First Name & Last Name)	Date Recorded(mm/dd/year)

NDCRS ARCHITECTURAL SITE FORM PAGE 2—Feature Data

Field Code Schultz School	SITS# 32 SN
Complete one Page 2 <u>for each</u> architectu	ural feature at the site.
Architectural Feature # 1	
Construction Date Feature Ty	rpe X 9 Condition 6
Feature Date 2 Context	7 Plan Shape 5
Structural System 25 Primary Ex	Other Chile
	Exterior N/A Architect/Builder
Other Information:	
Foundation Railroad ties	Stories 1
Roof/Cornice Hip roof with a half hip addition	
Window Double hung, some broken glass, protected	d by plexiglass
Dating Method(s):	
Feature Preservation Recommendation(s) (CIndividual nominationContributes to a potential district	энеск ан тас арргу).
No nomination potential	
Will not contribute to a district	
Potential district—feature would be a contril	buting element if other properties constitute a district
Thematic nomination potential	
Component of a historic site or landscape	
	relocation occurred within a historic period; b) be, & spatial relationships; c) compatible in context as damaged eligibility
Historical associations require further invest	tigation
Kathy Wilner	
Recorded By (First Name & Last Name)	Date Recorded (mm/dd/year)

Instructions to complete a digital version of this form: (1) Download a copy; (2) Open the saved blank copy; (3) Fill out the form; (4) Use the Save As command to rename the form appropriately, and save; (5) **Print** and submit to SHSND.

NDCRS ARCHITECTURAL SITE FORM

PAGE 3	—reature Data	
Field Code Schultz School	SITS# 32 SN	
3 U C 2 C C C C C C C C C C C C C C C C C	700000	_

Complete a Page 3 for each feature.

1. Feature Description, Integrity, Eligibility:

The feature is a one room prairie school moved to the Shultz farm in Wadsworth Township. It is sitting on railroad ties and it being used for storage. The hip roof of the building and the half hip of the addition are covered with metal sheeting. There is not chimney. The soffits are closed with beadboard. The school was newly painted in 2018. The building measures 20 feet east to west and 35 feet north to south with the addition measuring 16 feet by 4 feet.

There is a frieze board just under the eaves on all four sides to start the siding. The remainder of the siding is 6 inch wood lap. There are 5 large, 4 over 4, double hung windows on the east wall of the school. Some of the glass is broken and all 5 are covered with sheets of plexiglass. On the south wall of the school there are two smaller double hung windows. The wall here shows that an entry was persent in the past. The door is a broken wood door with plexiglass on the top half. Another wood door is on the addition on the west, both locked. A small room is in the southwest corner of the building with two door openings, no doors. On the southeast wall there is a row of coat hooks and the remanents of a door frame leading me to think this was a coatroom at one time. The door leading in from the west addition is a 5 panel wood door. There is framing on the west wall from the door to the northwest corner and again on the north wall that outlines where the blackboards were. They have been removed. The walls and ceiling are finished with lathe and plaster with much falling in. There is a picture rail around the entire school room. The floor is tongue and groove hardwood. No wainscot and no evidence of electricity.

Recorded By	the state of the s	Date Recorded 1/22/2019	
terenigan at	(First Name & Last Name)	(mm/dd/year)	

NDCRS ARCHITECTURAL SITE FORM PAGE 4—SITE DESCRIPTION

Field Code Schultz School	SITS# 32 ^{SN}
Complete one Page 4 for the entire site.	
Owner's Contact Information: Conrad Schultz 1720 56th Ave SE Woodworth ND 58496 Erick Schultz 224 4th Ave SE. Jamestown ND 59401	
 Access (to rural areas): This school is located north of Woodworth, following Highwastraight on 56 Ave SE about 1/2 mile to see the farm on you farm yard. 	요즘 하다라요. 그 그림이 나를 마시는 것으로 하는데, 나는 아름다면 그런데 하는데, 이번에 나를 하는데, 가득, 사람이 아픈데 이렇게 되었다.
4. Site Area (ft²):	
 Description of SETTING: The school sits at the west edge of a large farm yard. There building and bins in the immediate area of the school. There on gently rolling land. 	
Kothy Wilner	4/02/2040
Recorded By Kathy Wilner (First Name & Last Name)	Date Recorded 1/22/2019 (mm/dd/year)

NDCRS ARCHITECTURAL SITE FORM

Field Code Schultz School	SITS# 32 SN	
5. Summary of ALL Site Features & Evalu	uation of Significance:	
References/Comments: Kathy Wilner		
366 43rd Ave SE Bowdon ND 58418		
Kathy Wilner	1/22/2019	
(First Name & Last Name)	Date Recorded (mm/dd/year)	

(First Name & Last Name)

(mm/dd/year)



South Side


Shultz School

9/2/2018

Kathy Wilner

SN

West Side





East Side


Schultz School

9/2/2018

Kathy Wilner

SN

North Side



1/8/2019 Google Maps



Schultz School

9/2/2018

Kathy Wilner

SN



Imagery ©2019 Google, Map data ©2019 Google 500 ft