NDCRS 2009

NDCRS ARCHITECTURAL SITE FORM PAGE 1				
	FAGE	SITS# 32	<u>st 192</u>	
SITE IDENTIFICATION				
Field Code Sherbrook#1	Site Name	Sherbrooke #		
Map Quad_ <u>Sherbrooke</u> Map Quad	Site Name			
LTL TWP46 R55 LTL TWP R LTL TWP R LTL TWP R	SEC QQQ _ SEC QQQ _	QQ	Q <u>8</u> Q Q Q	
UTM5252778 UTM595966	_N ZONE _E NAD 1	<u>14N</u> 927 NAD 1983	Subsection: $1 = N\frac{1}{2}$ $2 = E\frac{1}{2}$	
City:			$3 = S^{1/2}$	
Street Number:			$4 = W^{1/2}$ 5 = NE ¹ / ₄	
Street Name: 132nd Ave NE			6 = SE ¹ / ₄ 7 = SW ¹ / ₄	
Urban Legal Description:			8 = NW ¹ / ₄	
SITE DATA				
Total # Architectural Features:	1			
Fieldwork Date:5/16/2016	_			
Reconnaissance Survey 🗹	Intensive Survey			
Project Title & Supervisor: Country Schoolhouse Project				
Report Title & Author(s):				
Additional Information:				
SHSND USE Area of Significance Area of Significance Area of Significance Area of Significance	Verified Site Non-Site	CR Type	2	
	Wilner	_ Date Recorded	1/16/2017	
(First Name & Last Name)			(mm/dd/year)	

NDCRS ARCHITECTURAL SITE FORM PAGE 2—Feature Data				
Field Code Sherbrook #1		SITS# 32_ <u>ST</u>		
Complete one Page 2 <u>for each</u>	<u>architectural feature</u> at th	e site.		
Architectural Feature #1				
Construction Date	Feature Type <u>9</u>	Condition 5		
Feature Date 2	Context_7	Plan Shape 5		
Structural System 25	Primary Exterior <u>26</u>	Style <u>Other Style</u>		
Original Owner's Ethnicity	Secondary Exterior	Architect/Builder		
Other Information:				
Foundation concrete		_Stories		
Roof/Cornice_gable				
Window most appear of	ginal			
Dating Method(s): estimate				

Feature Preservation Recommendation(s) (Check all that apply):

- Individual nomination
- Contributes to a potential district
- ____No nomination potential
-Will not contribute to a district
- ____Potential district—feature would be a contributing element if other properties constitute a district
- ____ Thematic nomination potential
- Component of a historic site or landscape

Moved (specify all applicable choices)—a) relocation occurred within a historic period; b) recreates original site, orientation, landscape, & spatial relationships; c) compatible in context with neighboring structures; d) relocation has damaged eligibility

_____Historical associations require further investigation

Recorded By	Kathy Wilner	Date Recorded	1/16/2017
	(First Name & Last Name)	-	(mm/dd/year)

NDCRS 2009

NDCRS ARCHITECTURAL SITE FORM PAGE 3—Feature Data

Field Code Sherbrook #1

SITS# 32_ST

Complete a Page 3 for each feature.

1. Feature Description, Integrity, Eligibility:

The feature is a one room prairie school sitting on a concrete foundation. This has been moved to the farm for storage and use of a shop. The gable roof of the school and entry is covered with wood shakes and topped with metal capping and finials at each end. There is a short, concrete chimney at the north end of the school. The soffits are open. This building

Siding begins with a wide trim board under the peak ends of the roof and the remainder of the siding is 6 inch wood lap with 4 inch wood corner trim. There is an entry at the north end of the building and the inside of the room is walled with vertical planking. The door to this entry is 5 panel wood and one panel is broken. There is a glass transom above the door. There are three double hung windows on both the east and west sides. On the west side the windows are uncovered and have glas intact. On the east side one is covered and the other two are open. There are decorative cornices on above all the windows on the outside walls. The south wall was opened up and two large sliding doors were installed to give access to the interior of the building. The interior walls and ceiling are finished with beadboard. There is a electric heater on the north wall. The floor is all concrete. Some of the blackboards remain, one between the 1st and 2nd windows on both sides.

Recorded By Kathy Wilner Date Recorded 1/16/2017
(First Name & Last Name)
(mm/dd/year)

NDCRS 2009

NDCRS ARCHITECTURAL SITE FORM PAGE 4—SITE DESCRIPTION

Field Code Sherbrook #1

SITS# 32_ST_____

Complete one Page 4 for the entire site.

2. Owner's Contact Information:

Julison Farm

3. Access (to rural areas):

This school is located on a farm about 1/2 mile north of Center Street on 132nd Ave NE. It is about 9 miles north of Hope.

4. Site Area (ft²):

5. Description of SETTING:

The building is sitting in trees on a farm site. The house is to the west and the farm is surrounded by farm fields and pasture.

Recorded By Kathy Wilner Date Recorded 1/16/2017
(First Name & Last Name) (mm/dd/year)

NDCRS 2009

NDCRS ARCHITECTURAL SITE FORM **PAGE 5—SITE DESCRIPTION**

Field Code Sherbrook #1

SITS# 32_ST____

6. Summary of ALL Site Features & Evaluation of Significance:

7. References/Comments: Kathy Wilner 366 43rd Ave SE Bowdon ND 58418

Recorded By (First Name & Last Name) Kathy Wilner

____ Date Recorded ___

1/16/2017 (mm/dd/year)




North Side

Sherbrooke #1

5/16/2016

Kathy Wilner


ST



South Side



West Side



East Side



b bing	maps
--------	------

Notes
Sherbrooke #1
5/16/2016
Kathy Wilner
ST



b bing

\$ 2016 Microsoft Corporation & 2016 HERE



Feature