NDCRS ARCHITECTURAL SITE FORM PAGE 1

OUT IDENTIFICATION	PAGE 1	SITS# 32_	st 196
SITE IDENTIFICATION Field Code Sherbrooke #3 Map Quad Sherbrooke Map Quad	Site Name	herbrooke #3	3
LTL TWP146 R 55 SEC LTL TWP R SEC LTL TWP R SEC	C QQQ	QQ QQ	Q 6 Q Q
UTMN UTME	ZONE _ NAD 19	027 NAD 1983	Subsection: 1 = N½
City: Hope			$2 = E\frac{1}{2}$ $3 = S\frac{1}{2}$
Street Number:			$4 = W\frac{1}{2}$ $5 = NE\frac{1}{4}$
Street Name: 2nd St NE		_	6 = SE½ 7 = SW¼
Urban Legal Description:	·		8 = NW ¹ / ₄
SITE DATA			
Total # Architectural Features: 1			
Fieldwork Date:5/16/2016			
Reconnaissance Survey Inte	ensive Survey		
Project Title & Supervisor: Country Schoolhouse Project			
Report Title & Author(s):			
Additional Information:			
SHSND USE Area of Significance Ecozone Area of Significance	Verified Site Non-Site		_2_
Recorded By Kathy Wil	ner	Date Recorded	1/17/2017 (mm/dd/year)

NDCRS ARCHITECTURAL SITE FORM PAGE 2—Feature Data

Field Code Sherbrooke #3		SITS# 32_	ST
Complete one Page 2 <u>for ea</u>	ach architectural feature	at the site.	
Architectural Feature #1	_		
Construction Date	Feature Type9	Condition 6	<u> </u>
Feature Date 2	Context 7	Plan Shape _	5
Structural System <u>25</u>	Primary Exterior <u>5</u>	Style <u>Other S</u>	tyle
Original Owner's Ethnicity	Secondary Exterior	Architect/Bui	lder
Other Information:			
Foundation Concrete blocks		Stories1	_
Roof/Cornice Gable			
Window Double hung, most glass			
Dating Method(s): Estimate			
 Thematic nomination poter Component of a historic sit Moved (specify all applicate recreates original site, orie 	rict vould be a contributing elemen ntial e or landscape ole choices)—a) relocation occuration, landscape, & spatial res; d) relocation has damaged e	t if other properties c urred within a historic plationships; c) compa	period; b)
Recorded By Ka	athy Wilner	Date Recorded	1/17/2017 (mm/dd/year)

NDCRS ARCHITECTURAL SITE FORM PAGE 3—Feature Data

Complete a Page 3 for each feature.

1. Feature Description, Integrity, Eligibility:

The feature is a one room prairie school on a concrete block foundation. The gable roof of the school is covered with wood shakes and many of these are missing. There is an entry on the south side and that roof is covered with asphalt shingles. Yet another addition to the north end of the school has asphalt shingles. All have metal capping with finials. Soffits are open. There is a yellow brick chimney at the roof peak at the north end of the school. There are two bathroom vents on each slope of the roof near the north edge of the north addition. There is a vent in the wall of the north addition just under the peak of the roof. The north addition measures 12 feet north to south and 18 feet east to west, the main part of the school measures 26 1/2 feet north to south by 18 feet east to west and the entry is 12 feet by 6 feet.

The siding on all but the north addition is 10 inch composite/fiberboard siding with the north addition having 6 inch wood lap with metal corner capping. There is an old 3 panel wood door with a boarded up window at the top, it is locked. There is also a transom above the door and this is boarded up as well. Decorative cornices can be seen above the door and all the windows. There is a small boarded up window on either side of the north addition. There are three double hung windows on both the east and west walls, all but two are shuttered. There is glass in the two 2 over 2 windows that allowed us to look inside the school. The walls are wallboard panels with wainscot at the lower 1/3. The ceiling is pressed tin. On the north wall of the school there is a space where the blackboards used to be as well as blackboards between the north most and middle windows on each side. The floor is tongue and groove hardwood. The entry is approached by a set of concrete steps. A light over the entry door indicates electricity.

Recorded By	Kathy Wilner	Date Recorded	1/17/2017
(First Na	ame & Last Name)		(mm/dd/year)

Field Code Sherbrooke #3

SITS# 32 ST

NDCRS ARCHITECTURAL SITE FORM PAGE 4—SITE DESCRIPTION

Complete one Pa	ge 4 for the entire site.		
2. Owner's Contact In Wayne Amundson RR1 Box 16 Hope ND 58046	formation:		
3. Access (to rural are	as): e going north on Highway 6 or 132n	d Avo NE 9 miles to Highwa	w 11 or 2nd St NE
	and go about 2 3/4 miles east to see		
4. Site Area (ft²):			
5. Description of SET	TING:		
Fields to the north, so the farm.	outh and west and a farm site to the	east. A line of trees is betwe	een the school and
Recorded By	Kathy Wilner	Date Recorded	1/17/2017 (mm/dd/year)
(, 1131.1	and a coornainoj		(IIIIII aa/yeai)

NDCRS ARCHITECTURAL SITE FORM PAGE 5—SITE DESCRIPTION

Field Code Sherbrooke #	3	SITS# 32	ST
6. Summary of ALL Si	ite Features & Evaluatior	of Significance:	
7. References/Comments:			
Kathy Wilner			
366 43rd Ave SE Bowdon ND 58418			
Recorded By (First Name &	Kathy Wilner Last Name)	Date Recorded	1/17/2017 (mm/dd/year)



South Side

Sherbrooke #3 5/16/2016 Kathy Wilner ST

East Side





West Side

Sherbrooke #3

5/16/2016 Kathy Wilner ST

North Side



Notes
Sherbrooke #3

5/16/2016

Kathy Wilner

ST



