

NDCRS ARCHITECTURAL FORM
PAGE 1

Field Code Rock Lake Township School

SITS# 32 TO 64

Map Quad Rock Lake

Site Name Rock Lake Township School

Map Quad _____

Site Name _____

LTL T. 162 N., R. 66 W., Sec. 14 QQQ 6 of the QQ 6 of the Q 7

LTL T. N., R. W., Sec. QQQ of the QQ of the Q

LTL T. N., R. W., Sec. QQQ of the QQ of the Q

LTL T. N., R. W., Sec. QQQ of the QQ of the Q

NAD 1983 UTM 5410655 Zone 14N

NAD 1983 UTM 487717

City: _____

Subsection

- 1 = N½
- 2 = E½
- 3 = S½
- 4 = W½
- 5 = NE¼
- 6 = SE¼
- 7 = SW¼
- 8 = NW¼

Street Number: _____

Street Name: 99th St NE

Urban Legal Description: _____

Total Number of Architectural Features: 1

Fieldwork Date: 8/10/2020

Reconnaissance Survey

Intensive Survey _____

Project & Principal Investigator:

Country School House Project
Kathy Wilner
366 43rd Ave SE
Bowdon ND 58418

Contracting Firm or Agency Completing the Form:

Additional Information:

SHSND USE
 Component 2 Study Unit 17 Verified Site _____ CR Type 2
 Component _____
 Component _____

Recorded By: Kathy Wilner Date Recorded: 8/13/2020

Form instructions: (1) Download; (2) Save A Copy; (3) Submit a paper copy of the form to the SHSND and upload the PDF version of the form and corresponding GIS shapefiles to the ND SHPO-run FTP site.

NDCRS ARCHITECTURAL FORM
PAGE 2 – Feature Data

Field Code Rock Lake Township **SITS# 32** TO

Complete one Page 2 for each architectural feature at the site.

Architectural Feature # 1

Construction Date _____

Feature Date 1880-1900

Structural System Wood Frame

Original Owner's Ethnicity _____

Feature Type 9 - School; Church school

Context Education

Primary Exterior Wood, Horizontal Siding

Secondary Exterior _____

Condition Fair

Plan Shape Rectangular

Style Other Style

Architect/Builder _____

Foundation Poured Concrete **Stories** 1

Roof/Cornice Gable

Window Double hung, covered, little glass

Dating Method(s) Estimate

Miscellaneous Information _____

Feature Preservation Recommendation(s) (Check all that apply):

Individual nomination

Contributes to a potential district

No nomination potential

Will not contribute to a district

Potential district—feature would be a contributing element if other properties constitute a district

Thematic nomination potential

Component of a historic site or landscape

Moved (specify all applicable choices)—a) relocation occurred within a historic period; b) recreates original site, orientation, landscape, and spatial relationships; c) compatible in context with neighboring structures; d) relocation has damaged eligibility

Historical associations require further investigation

Recorded By: Kathy Wilner **Date Recorded:** 8/13/2020

**NDCRS ARCHITECTURAL FORM
PAGE 3 – Feature Data**Field Code Rock Lake TownshipSITS# 32 TO _____Complete one Page 3 for *each* architectural feature at the site.

1. Feature Description, Integrity, Eligibility:

This feature is a one room paririe school on a poured concrete foundation. The gable roof of this building has wood shakes for cover and many are missing. There are remnants of metal capping along the roof peak and what looks to be the flag pole leans off to the east at the south end of the roof peak. There is a cement chimney located about the middle of the building at the roof peak. The soffits are closed.

A rake board leads to 6 inch wood lap siding with 4 inch wood corner trim. No paint remains on the building. There is an entry door opening with a covered transom opening above it. Stepping into the entry the walls and ceiling are all covered with beadboard. There are three 5 panel wood doors leading into side rooms off the central hall way. Another door opening straight ahead leads into the school itself. That door is leaning against the wall inside the large room. The small room off the entry to the east has a fuel door on the wall in it and it not finished inside except for the north wall. Seams on the outside of the school show where this entry part of the school was added at a later time. The north wall of the fuel storage area is wood lap on what was likely the exterior south wall of the school. The entry area has two small rooms off to the left, each one has a covered window opening. The main room of the school has two double hung windows on the west side, both covered. The walls are covered with grooved wall board while the ceiling has rectangular tiles. There are remnants of light fixtures evidencing electricity at some point. The floor is narrow hard wood boards. There is a black board across the entire width of the school on the north wall as well as another larger board on the north 1/3 of the east wall. More blackboards may have been removed as the outline is present on the east wall.

2. Owner's Contact Information:

Grace Peterson
Rock Lake ND 58365

Recorded By: Kathy Wilner Date Recorded: 8/13/2020

NDCRS ARCHITECTURAL FORM
PAGE 4 – Site Description**Field Code** Rock Lake Township School**SITS# 32** TO _____3. Site Area (ft²):

4. Description of Access and Site Setting:

This building is in a rural setting with farmland all directions. There is an abandoned farm site to the northeast. Driving to this school by heading north out of Rock Lake ND on 67th Ave NE. Go north about 4 miles to 99th St NE. Turn right and go east about 3 1/4 miles to see the school on the north side of the road.

5. Summary of ALL Site Features and Evaluation of Significance:

6. References/Comments:

Information and pictures shared by Lorie Yocum.

Recorded By: Kathy Wilner **Date Recorded:** 8/13/2020

Form instructions: (1) Download; (2) Save A Copy; (3) Submit a paper copy of the form to the SHSND and upload the PDF version of the form and corresponding GIS shapefiles to the ND SHPO-run FTP site.



North Side

Rock Lake Township School

8/10 2020

Kathy Wilner

TO

West Side





South Side

Rock Lake
Township
School

8/10/2020

Kathy
Wilner

TO

East Side





Imagery ©2020 CNES / Airbus, Maxar Technologies, USDA Farm Service Agency, Map data ©2020 200 ft

Feature