

NDCRS ARCHITECTURAL SITE FORM
PAGE 1

SITS# 32 TR Flde

SITE IDENTIFICATION

Field Code Bloomfield #1

Site Name Bloomfield #1

Map Quad Hillsboro

Site Name

Map Quad

LTL TWP 145 R 50 SEC 5 QQQ 7 QQ 8 Q 7
LTL TWP R SEC QQQ QQ Q
LTL TWP R SEC QQQ QQ Q
LTL TWP R SEC QQQ QQ Q

UTM 5251515 N ZONE 14N
UTM 645711 E NAD 1927 NAD 1983

Subsection:
1 = N 1/2
2 = E 1/2
3 = S 1/2
4 = W 1/2
5 = NE 1/4
6 = SE 1/4
7 = SW 1/4
8 = NW 1/4

City: Hillsboro

Street Number:

Street Name: 5th St SW

Urban Legal Description:

SITE DATA

Total # Architectural Features: 1

Fieldwork Date: 5/16/2016

Reconnaissance Survey [checked] Intensive Survey

Project Title & Supervisor:

Country Schoolhouse Project

Report Title & Author(s):

Additional Information:

SHSND USE

Area of Significance 2 Ecozone 15 Verified Site 1 CR Type 2
Area of Significance Non-Site
Area of Significance

Recorded By Kathy Wilner Date Recorded 1/16/2017
(First Name & Last Name) (mm/dd/year)

Instructions to complete a digital version of this form: (1) Download a copy to your hard drive; (2) Open the saved blank copy; (3) Fill out the form; (4) Use the Save As command to rename the form appropriately and save; (5) Print and submit to SHSND.

**NDCRS ARCHITECTURAL SITE FORM**  
**PAGE 2—Feature Data**

Field Code Bloomfield #1SITS# 32 TR

**Complete one Page 2 for each architectural feature at the site.**

Architectural Feature # 1

Construction Date \_\_\_\_\_

Feature Type 9Condition 7Feature Date 2Context 7Plan Shape 5Structural System 25Primary Exterior 26Style Other Style

Original Owner's Ethnicity \_\_\_\_\_

Secondary Exterior \_\_\_\_\_

Architect/Builder \_\_\_\_\_

Other Information:

Foundation Concrete Stories 1Roof/Cornice HipWindow Double hungDating Method(s): Estimate

**Feature Preservation Recommendation(s) (Check all that apply):**

- Individual nomination
- Contributes to a potential district
- No nomination potential
- Will not contribute to a district
- Potential district—feature would be a contributing element if other properties constitute a district
- Thematic nomination potential
- Component of a historic site or landscape
- <sup>c</sup> Moved (specify all applicable choices)—a) relocation occurred within a historic period; b) recreates original site, orientation, landscape, & spatial relationships; c) compatible in context with neighboring structures; d) relocation has damaged eligibility
- Historical associations require further investigation

Recorded By Kathy Wilner Date Recorded 1/16/2017  
(First Name & Last Name) (mm/dd/year)

*Instructions to complete a digital version of this form: (1) Download a copy to your hard drive; (2) Open the saved blank copy; (3) Fill out the form; (4) Use the Save As command to rename the form appropriately and save; (5) Print and submit to SHSND.*

**NDCRS ARCHITECTURAL SITE FORM**  
**PAGE 3—Feature Data**Field Code Bloomfield #1SITS# 32 TR**Complete a Page 3 for each feature.****1. Feature Description, Integrity, Eligibility:**

The feature is a one room prairie school sitting on a concrete foundation. The school was moved to this location to add to a Pioneer Village complex. The school is in great shape. The hip roof covered with asphalt shingles and there are two attic vents near the top of the roof on the west slope. The entry porch is a half hip with asphalt shingles as well. The soffits are closed with beadboard finish and vents on all four sides. There is no chimney. The building measures 38 feet north to south and 22 feet east to west.

A wide trim board runs under the soffits on all four sides of the school. The remainder of the siding is 6 inch wood lap with metal corner capping on the entry corners and no corner trim on the school itself. There is a skirting board with water table at the lowest edge of the exterior walls. The concrete foundation is skirted. There is an entry door at the northeast corner as well as a 5 panel wood door at the front entry. There is a porch leading up to the entry door and it is enclosed on the north and south sides. The entry has a beadboard ceiling, horizontal 6 inch wood lap siding on the school wall and vertical planking on the two side walls. Three concrete steps lead to the wood floored porch. There is a light fixture above the door. There are several double hung windows, all with multipane glass on the top and single glass on the bottom. All intact and with protective storm windows. There are valance curtains on the windows and the bathroom windows have shades that pull from the top. The floor is tongue and groove hardwood. There are bathrooms in the school along with coat rooms, separate for girls and boys. You enter the school and turn right into the large school room. To the left as you go in to the room there are two doors, first is the girls coat room with their bathroom further to the left. Going along that wall (south side of the school) there is the boys coat room with their bathroom. Windows on the south are, from right to left, the entry window, girls coat room, girls bathroom and last window is boys bathroom with another window on the west that is in their coatroom. There is a wall near the north end of the school with doors at either end and this space is library on the east half and storage on the west. There are windows on this wall, one in either room. There are blackboards in the main room of the school and they are on the west wall as well as between doors in on the south wall. No wainscoting. The presence of electricity is again seen by way of light fixtures in the school room.

A school bell has been mounted on a post on the south side of the school.

Recorded By Kathy Wilner Date Recorded 1/16/2017  
(First Name & Last Name) (mm/dd/year)

*Instructions to complete a digital version of this form: (1) Download a copy to your hard drive; (2) Open the saved blank copy; (3) Fill out the form; (4) Use the Save As command to rename the form appropriately and save; (5) Print and submit to SHSND.*

**NDCRS ARCHITECTURAL SITE FORM  
PAGE 4—SITE DESCRIPTION**

Field Code Bloomfield #1

SITS# 32 TR

**Complete one Page 4 for the entire site.**

2. Owner's Contact Information:

Trail County Historical Society  
PO Box 173  
Hillsboro ND 58045

3. Access (to rural areas):

In town Hillsboro at the intersection of 5th St SW and 2nd Ave.SW.

4. Site Area (ft<sup>2</sup>): \_\_\_\_\_

5. Description of **SETTING**:

There are houses to the east and south and Pioneer village to the north and west.

Recorded By Kathy Wilner Date Recorded 1/16/2017  
(First Name & Last Name) (mm/dd/year)

*Instructions to complete a digital version of this form: (1) Download a copy to your hard drive; (2) Open the saved blank copy; (3) Fill out the form; (4) Use the Save As command to rename the form appropriately and save; (5) Print and submit to SHSND.*

**NDCRS ARCHITECTURAL SITE FORM  
PAGE 5—SITE DESCRIPTION**

Field Code Bloomfield #1

SITS# 32 TR

**6. Summary of ALL Site Features & Evaluation of Significance:**

7. References/Comments:

Kathy Wilner  
366 43rd Ave SE  
Bowdon ND 58418

Recorded By Kathy Wilner Date Recorded 1/16/2017  
(First Name & Last Name) (mm/dd/year)

*Instructions to complete a digital version of this form: (1) Download a copy to your hard drive; (2) Open the saved blank copy; (3) Fill out the form; (4) Use the Save As command to rename the form appropriately and save; (5) Print and submit to SHSND.*





South Side

Bloomfield #1

5/16/2016

Kathy Wilner

TR

West Side







East Side

Bloomfield #1

5/16/2016

Kathy Wilner

TR

North Side





bing maps

Notes

Bloomfield #1

5/16/2016

Kathy Wilner

TR



Feature