NDCRS SITE FORM ARCHITECTURAL SITES Page 1

	SITS # 3 2 WA 203
	Field Code J.K.A.Q.Z/ Site Name 4. M. L.E. S.C.H.O.O.L.
	Map Quad C. r.a. fit on 1. No 2. Ed 2. Ed 2.
SITE DATA	LTL Twp R Sec QQQ QQ QQ Q
	City
	Street # Street #
	Street Name Street Name
	# of Features
FEATURE DATA	
SHSND USE	Soil Association La Ecozone Area Signf Land MS Number Soil Association La Ecozone La Area Signf Land MS Number CR Type La Verified Site Ann-Site La ECF La TF State Registry National Register
-	Coder Jeff Kinney Date Coded 3-10-03
	Reconnaissance Survey Intensive Survey
	Manuscript/Report Title:
	Author(s):

NDCRS ARCHITECTURAL SITE FORM page 1A

Field Code JKA-2002-1-1	Feat	ire Number	1	SITS # <u>32W</u>	4
	DESCR	IPTIVE SECTI	ON		
FOUNDATION	STORIES	ROOF TYP		Έ	
brick	1	Hip, trunca	ated		
WINDOW CONDITION	de	DATING M	ETHOD		
Poor, boarded up	145	Informant			
PRESERVATION RECOMM	ENDATION (ch	neck all that ap	pply)		
1) Individual Nomination 3) _X No nomination potential district nomination element if neighbor 6) Thematic nomination	ential 4) <u>></u> ot known at this ring properties	Will not con time: feature v constitute a dis	itribute to d would be a strict	istrict contributing	cape
8) Feature has an imparchitectural relation 9) Moved: A) relocation orientation, landscape and context with neighbor 10) Request comparation in the Historical association in the second context with neighbor 11) Historical association in the second context with neighbor 11) Historical association in the second context with neighbor 11.	onship to the site on occurred with spatial relation poring structure ive study of neigons.	e/complex/farr hin historic per ships. C) com s. D) relocation ghboring prope	nstead riod. B) red npatible in on has dam erties	creates original	·
DESCRIPTION/INTEGRITY/	ELIGIBILITY				
Feature 1, known as the "4 N schoolhouse located in the S a truncated hip roof with ced three windows on each side the north end of the building, with a truncated hip roof. The	SW corner of se ar shingles. Th and they are cu There is a sm	ction 16. This ne exterior is clurrently boarde all entrance of	structure had with hored up. The name the south	nas a brick four rizontal wood s chimney (miss end of the buil	ndation and iiding. It has sing) was on
A local informant, Lillian Lars Larson donated the land for closed in the 1930's and was then used as a township hall	the schoolhous possibly open	e in the early ^a ed again for a	1900's. She few years i	e said that the in the late 1940	school
The structural integrity of the believed to be eligible for nor					nor is it
Urban Legal Description:					
SEE CONTINUATION	SHEET				

NDCRS ARCHITECTURAL SITE FORM Page 3

T:-I-I OI- II/A 0000 4 4	CITC #	2014/4
Field Code JKA-2002-1-1	SITS #_	32VVA

OWNER'S NAME, ADDRESS, PHONE #: Oliver Ordahl, Grafton, ND, (701)352-0933

PROJECT TITLE: Phase I Cultural Resources Investigation of a Proposed Tieback Levee and

Disposal Areas at the City of Grafton, Walsh County, North Dakota

REPORT TITLE: Phase I Cultural Resources Investigation of a Proposed Tieback Levee and

Disposal Areas at the City of Grafton, Walsh County, North Dakota

SITE AREA (in square feet): 2,500 square feet

ACCESS: From the intersection of ND 81 and ND 17 in Grafton, ND, proceed west on ND 17 for approximately 3.9 miles west to the crossroad. The site is located immediately north of this point.

DESCRIPTION: Feature 1, known as the "4 Mile" school is a small rectangular, wood frame, one–room schoolhouse located in the SW corner of section 16. This structure has a brick foundation and a truncated hip roof with cedar shingles. The exterior is clad with horizontal wood siding. It has three windows on each side and they are currently boarded up. The chimney (missing) was on the north end of the building. There is a small entrance on the south end of the building, also with a truncated hip roof. The overall condition of the building is poor.

SUMMARY OF SITE FEATURES AND EVALUATION OF SIGNIFICANCE:

This site consists of a single feature, the one-room schoolhouse known locally as the "4 Mile" schoolhouse. No other out buildings or other features remain at the site. The overall physical condition of the building is poor. The brick foundation is deteriorating and the roof is in poor condition. The windows are in very poor condition and have been boarded up. This site is not believed to be significant and it is not considered to be eligible for nomination to the National Register of Historic Places.

NDCRS SITE FORM

Photograph Form

Field Number_JKA-2002-1-1

SITS #__32WA

Photo I.D. Code: JKA-2002-1/5, 8, 11

Storage Location: JKA, P.O. Box 43, Manvel, ND 58256

Include direction facing, feature number, and photo caption for each submitted

photograph.



Schoolhouse closeup. View to the southwest. (Roll 1, neg. 11)



Schoolhouse overview. View to the northeast. (Roll 1, neg. 8)

NDCRS SITE FORM

Photograph Form

Field Number JKA-2002-1-1

SITS #_32WA

Photo I.D. Code: JKA-2002-1/5, 8, 11

Storage Location: JKA, P.O. Box 43, Manvel, ND 58256

Include direction facing, feature number, and photo caption for each submitted

photograph.



Schoolhouse closeup. View to the northeast. (Roll 1, neg. 5)


NDCRS SITE FORM

Topographic Map

Field Number JKA-2002-1-	-1
--------------------------	----

SITS # 32WA

Photocopy the portion of the 7.5' U.S.G.S. topographic quadrangle that shows the location of the site and the surrounding area. Mark the boundaries of the site on the photocopy. Photocopy of the portion of the topographic quadrangle must be actual size, reduction or enlargements are unacceptable.



NDCRS SITE FORM Sketch Map

Field	#	JKA	=20	02-	1-1
-------	---	-----	-----	-----	-----

SITS #___32WA

Include a north arrow, site boundaries, road or street names, locations of artifacts, features, buildings, structures, objects, and depressions with each item individually numbered and keyed to the Map Key, and road or street name(s).

Map Key: 157/53 Sec. 16 SW1/4, SW1/4, SW1/4

Map Scale: 1 in. = 10 feet

