Component

NDCR	S ARCHITECTURAL FORM	
0.40.41	PAGE 1	UPDATE ♥
Field Code Carter School	SITS# 32 WD	
Map Quad Kenmare Map Quad	Site Name Carter School	
LTL T ¹⁶⁰ N., R ⁸⁸ W., Sec ¹⁷ LTL T N., R W., Sec LTL T N., R W., Sec LTL T N., R W., Sec	QQQ of the QQ of the Q QQQ of the QQ of the Q	1 = N½
NAD _1983	_ Zone	4 = W½ 5 = NE¼ 6 = SE¼ 7 = SW¼ 8 = NW¾
Street Number:49200		<u> </u>
Street Name: US Hwy 52		
Oueet Name.		
Urban Legal Description:		
Project & Principal Investigator: Country School House Project Kathy Wilner 366 43rd Ave SE Bowdon ND 58418	Intensive Survey	
Contracting Firm or Agency Completing the F	form:	
Additional Information:		

Kathy Wilner and Hunter Andes **Date Recorded:** 11/19/2020 Recorded By: _

NDCRS ARCHITECTURAL FORM PAGE 2 – Feature Data

Field Code Carter School	SITS# 32 <u>W</u>	D 1538
Complete one Page 2 for each architectural feature at the site.		
Architectural Feature #8		
Construction Date		
Feature Date		
Structural System Wood Frame		
Original Owner's Ethnicity		
Feature Type 9 - School; Church school		
Context <u>Education</u>		
Primary ExteriorWood, Horizontal Siding		
Secondary Exterior		
Condition <u>Excellent</u>		
Plan Shape Rectangular		
Style Other Style		
Architect/Builder		
	1	
Roof/Cornice Gable	-	
Window Double hung, glass		
Dating Method(s)Estimate		
Miscellaneous Information		
Feature Preservation Recommendation(s) (Check all that apply):		
Individual nomination		
Contributes to a potential district		
No nomination potential		
Will not contribute to a district		
Potential district—feature would be a contributing element if of	ther properties	constitute a district
Thematic nomination potential		
Component of a historic site or landscape		
Moved (specify all applicable choices)—a) relocation occurre site, orientation, landscape, and spatial relationships; c) comprelocation has damaged eligibility		
Historical associations require further investigation		
Recorded By: Kathy Wilner and Hunter Andes Date	Recorded: _	11/19/2020

NDCRS ARCHITECTURAL FORM PAGE 3 – Feature Data

Field (Code	Carter School	SITS# 32 WD	1538
		•	•	

Complete one Page 3 for each architectural feature at the site.

1. Feature Description, Integrity, Eligibility:

The feature is a one room prairie school moved to the current location from Carter Township near Flaxton. The school sits on a poured concrete foundation. It is part of a pioneer village in Kenmare ND. The roof is finished with metal sheeting and there is no exterior chimney. The soffits are closed.

The siding begins with a rake board under the peaked roof ends. The remainder of the siding is 6 inch wood lap with 6 inch wood corner trim. The school is painted white. There is a ramp leading up to the small entry. A 5 panel wood door with a transom window at the top give entry to the school. The floor in the entry and the school is tongue and groove hardwood. There are three double hung, 2 over 2, windows on both the north and south sides of the school with intact glass. A four panel wood door leads from the entry into the school proper. The walls in the school are lathe and plaster with wainscot. The ceiling is finished with beadboard. There are blackboards either side of the stove pipe/chimney on the west wall. There are desks, a stove with pipe hooked up to the remnants of the chimney, maps, books and more furnishings that speak of earlier times in a one room school. This school closed in 1948 and was moved to the village in 1974.

 Owner's Contact Information: Lake County Historical Society 49200 US Hwy 52 Kenmare ND 58746

Recorded By:	Kathy Wilner and Hunter Andes	Date Recorded: 11/19/2020
--------------	-------------------------------	---------------------------

NDCRS ARCHITECTURAL FORM PAGE 4 – Site Description

Field Code Carter S	SCHOOL		SITS# 32 <u>v</u>	VD 1536	
3. Site Area (ft²):					
Society located a	ss and Site Setting: ti ng at the west edge o along highway 52 in Ke buildings to the east a	enmare ND.	It is just to the sou	th of a church ar	nd
5. Summary of ALL Si	ite Features and Evaluati	on of Significar	ce:		
6. References/Comme	ents:				
c					
Recorded By:	Kathy Wilner and Hunt	er Andes	Date Recorded:	11/19/2020	




Southeast Side

Carter School

10/02/2020 Kathy Wilner WD

Southwest Side





Northwest Side

Carter School


10/02/2020

Kathy Wilner

WD

Screen shot from Lake County Historical Society Facebook page.

Northeast Side





Imagery ©2020 Maxar Technologies, USDA Farm Service Agency, Map data ©2020 100 ft

Feature

NDCRS ARCHITECTURAL FORM PAGE 1

- 1	IP	DA	TE	0
		$\boldsymbol{\nu}$		

Field Code Schwartz School	SITS# 32WD	1538
Map Quad Kenmare Map Quad	Site Name Schwartz School	
LTL T N., R 88 _ W., Sec 17 LTL T N., R W., Sec LTL T N., R W., Sec LTL T N., R W., Sec	QQQ 8 of the QQ 6 of the Q 7 QQQ of the QQ of the Q QQQ of the QQ of the Q QQQ of the QQ of the Q	Subsection 1 = N½
NAD 1983 UTM 5396413 NAD 1983 UTM 273614 City: Kenmare Street Number: 49200		5 = NE¼ 6 = SE¼ 7 = SW¼ 8 = NW¾
Street Name: US 52		
Urban Legal Description:		
Total Number of Architectural Features: Fieldwork Date:7/20/2020	1	
Reconnaissance Survey	Intensive Survey	
Project & Principal Investigator: Country School House Project Kathy Wilner 366 43rd Ave SE Bowdon ND 58418		
Contracting Firm or Agency Completing the F	Form:	
Additional Information:		
SHSND USE Component Study Unit Component	Verified Site CR Type	
Recorded By: Kathy Wilner and Hu	inter Andes Date Recorded: 11/	19/2020

NDCRS ARCHITECTURAL FORM PAGE 2 – Feature Data

Field Code Schwartz School	SITS# 32	WD 15	28
Complete one Page 2 for <i>each</i> architectural feature at the site.			
Architectural Feature #21			
Construction Date			
Feature Date			
Structural System Wood Frame			
Original Owner's Ethnicity			
Feature Type 9 - School; Church school			
Context <u>Education</u>			
Primary Exterior Wood, Horizontal Siding			
Secondary Exterior			
Condition <u>Excellent</u>			
Plan Shape Rectangular			
Style Other Style			
Architect/Builder			
D	1		
Roof/CorniceGable			
Window Double hung, glass			
Dating Method(s)Estimate			
Miscellaneous Information			
Feature Preservation Recommendation(s) (Check all that apply)			
Individual nomination			
Contributes to a potential district			
No nomination potential			
Will not contribute to a district			
Potential district—feature would be a contributing element if	other propert	ies cons	titute a district
Thematic nomination potential			
Component of a historic site or landscape			
Moved (specify all applicable choices)—a) relocation occurre site, orientation, landscape, and spatial relationships; c) comrelocation has damaged eligibility			
Historical associations require further investigation			
Recorded By:Kathy Wilner and Hunter Andes Date	Recorded	:	11/19/2020

NDCRS ARCHITECTURAL FORM PAGE 3 – Feature Data

Field Code	Schwartz School	SITS# 32 WD 1538

Complete one Page 3 for each architectural feature at the site.

1. Feature Description, Integrity, Eligibility:

The feature is a one room prairie school moved to this location in 2007 from Spencer Township in Ward County. It is located on a poured concrete foundation. The roof is metal sheeting, installed in 2017. There is no chimney. The soffits are closed. There is a bell tower at the north end of the roof, complete with a bell. The roof of the bell tower is also covered with metal sheeting.

The siding begins with a rake board leading to the 6 inch wood lap siding. 6 inch wood corner trim completes the siding. It was all painted red in 2017. There is an entry at the north end of the school, reached by a ramp to the wood porch. A newer, solid core, door with a window at the upper half gives entry to the school. There are fixed pane windows, two vertical panes of glass each, to either side of the entry door. More windows are located on both the east and west sides of the school. There are three, 2 over 2, double hung windows with intact glass on each side. Decorative cornices are seen at the top of each window inside with wide decorative trim on the sides as well as at the bottom of the windows. Decorative cornices and trim also surround the school room door from the entry. The walls are grooved wall board with a wide trim board at the floor. The floor is hard wood in the entry and then hard wood covered with tile in the school room. The sloped ceiling is also finished with the grooved wall board. Electricity is present. There is a blackboard across the entire southeast wall of the school.

This school is furnished with desks, books, maps and other items that were common in these one room schools.

2. Owner's Contact Information: Lake County Historical Society 49200 US Hwy 52 Kenmare ND 58746

Recorded By:	Kathy Wilner and Hunter Andes	Date Recorded: 11/19/2020	
			_

NDCRS ARCHITECTURAL FORM PAGE 4 – Site Description

Field Code Schwar	tz School		SITS# 32 <u>V</u>	VD 1538	
3. Site Area (ft²):					
in Kenmare The the grounds. The	ss and Site Setting: cated at the pioneer vilue address is 49200 US ere are several building e east side of town.	S Hwy. 52. T	ne school is at the	southeast corne	er of
5. Summary of ALL Si	te Features and Evaluati	on of Significar	ice:		
6. References/Comme	ents:				
Recorded By:	Kathy Wilnerand Hunte	er Andes	Date Recorded:	11/19/2020	



Northwest Side

Schwartz School


7/20/2020

Kathy Wilner

WD

Northeast Side





South West Side

Schwartz School

7/20/2020

Kathy Wilner

WD

North West Side





Imagery ©2020 Maxar Technologies, USDA Farm Service Agency, Map data ©2020 100 ft

Feature.