## NDCRS ARCHITECTURAL SITE FORM PAGE 1

SITS# 32 WD 2173

| SITE IDENTIFICATION                                     | 5.1.5.1.2.2. <u></u>  |
|---|---|
| Field Code Mayland Township School                      | Site Name   |
| Map Quad Caupio NE Map Quad                             | Site Name   |
|   | 26       QQQ 8       QQ 8       Q 7         QQQ       QQ       Q       Q         QQQ       QQ       Q       Q |
| UTMN  | ZONE NAD 1983 Subsection: 1 = N½  |
| City:   | 2 = E½<br>3 = S½  |
| Street Number:  | $4 = W\frac{1}{2}$ $5 = NE\frac{1}{4}$  |
| Street Name: 212th Ave NW                               | 6 = SE½<br>7 = SW½  |
| Urban Legal Description:                                | 8 = NW <sup>1</sup> / <sub>4</sub>  |
| SITE DATA   |   |
| Total # Architectural Features: 1                       |   |
| Fieldwork Date: 6/17/2016                               |   |
| Reconnaissance Survey _ ✓ Intensiv                      | ive Survey  |
| Project Title & Supervisor: Country Schoolhouse Project |   |
| Report Title & Author(s):                               |   |
| Additional Information:                                 | <u>-</u>  |
| SHSND USE Area of Significance                          | Verified Site CR Type   |
| Recorded By Kathy Wilner (First Name & Last Name)       | Date Recorded 1/20/2017 (mm/dd/year)  |

Instructions to complete a digital version of this form: (1) Download a copy to your hard drive; (2) Open the saved blank copy; (3) Fill out the form; (4) Use the Save As command to rename the form appropriately and save; (5) Print and submit to SHSND.

(mm/dd/year)

# NDCRS ARCHITECTURAL SITE FORM PAGE 2—Feature Data

| Field Code Mayland Township School      |  | SITS# 32_                             | SITS# 32 MH          |  |
|---|--|---------------------------------------|----------------------|--|
| Complete one Page 2                     | for each architectural fe  | ature at the site.                    |                      |  |
| Architectural Feature #                 | 1  |                                       |                      |  |
| Construction Date                       | Feature Type9  | Condition 5                           |                      |  |
| Feature Date 2                          | Context 7  | Plan Shape <u></u>                    | 5                    |  |
| Structural System 25                    | Primary Exterior <u>2</u>  | Style Other S                         | tyle                 |  |
| Original Owner's Ethnicity              | Secondary Exterio  | r Architect/Buil                      | der                  |  |
| Other Information:                      |  |                                       |                      |  |
| Foundation Mix of concrete              | and rocks  | Stories1                              | _                    |  |
| Roof/Cornice Gable                      |  |                                       |                      |  |
| Window Double hung, som                 | e glass,   |                                       |                      |  |
| Dating Method(s): Estimate              | 9  |                                       |                      |  |
| Feature Preservation R                  | decommendation(s) (Check   | all that apply):                      |                      |  |
| Contributes to a po                     |  |                                       |                      |  |
| No nomination pote                      |  |                                       |                      |  |
| Will not contribute                     |  |                                       |                      |  |
|   | eature would be a contributing e   | element if other properties co        | onstitute a district |  |
| Thematic nomination                     |  | , , , , , , , , , , , , , , , , , , , |                      |  |
| Component of a his                      | ·  |                                       |                      |  |
| Moved (specify all recreates original s | applicable choices)—a) relocation ite, orientation, landscape, & spaructures; d) relocation has dama | atial relationships; c) compa         |                      |  |
| Historical associati                    | ons require further investigation  |                                       |                      |  |
| Recorded By                             | Kathy Wilner   | Date Recorded                         | 1/20/2017            |  |

Instructions to complete a digital version of this form: (1) Download a copy to your hard drive; (2) Open the saved blank copy; (3) Fill out the form; (4) Use the Save As command to rename the form appropriately and save; (5) Print and submit to SHSND.

(First Name & Last Name)

### NDCRS ARCHITECTURAL SITE FORM PAGE 3—Feature Data

| Field Code Mayland Township School | SITS# 32 <u>MH</u> |
|------------------------------------|--------------------|
|------------------------------------|--------------------|

#### Complete a Page 3 for each feature.

### 1. Feature Description, Integrity, Eligibility:

The feature is a one room prairie school on a concrete and rock foundation/basement. The gable roof of this building has asphalt shingles that are in tough shape with some blown off. Decorative cornice returns can be seen on both the east and west walls, just under the soffits of the roof. The soffits are closed. There is a red and yellow brick chimney near the west end of the peak of the roof. At the east end of the roof is a flag pole. The building measures 29 feet east to west and 18 feet north to south. At the entry to the school there is a large concrete porch with three steps up to the platform. Pipe railings are at the south and north edge of the porch.

There is a wide trim board running under the soffits at the peak ends of the roof with the remainder of the siding being 6 inch wood lap with 6 inch wood corner trim. There are two sets of two double hung windows on the north wall with some intact glass. On the west side tow window opeings have little farming and no glass. One more window is near the west end of the south wall. All have a decorative cornice above the window inside and out. The entry door is plywood and has many holes. It looks like there were sidelights to either side of the door at one point, now filled in with siding. Just inside the door is a stairway to the basement. Other indication of a basement is a fule door on the south side and a couple windows. The interior walls are covered with wallboard with wainscot on the lower third. The ceiling is beadborad with most of a dropped ceiling gone. Blackboards have been removed from the school but the walls shows where they were on the south wall and the east wall between the doors that enter the school from the coat room. The floor is toungue and groove hardwood. There are light fixtures suggesting electricity.

| Recorded By | Kathy Wilner    | Date Recorded | 1/20/2017    |
|-------------|-----------------|---------------|--------------|
| -           | me & Last Name) |               | (mm/dd/year) |

Field Code Mayland Township School

SITS# 32 WD

### NDCRS ARCHITECTURAL SITE FORM PAGE 4—SITE DESCRIPTION

| (First N                      | ame & Last Name)                        |                                  | (mm/dd/year)         |
|-------------------------------|---|----------------------------------|----------------------|
| Recorded By                   | Kathy Wilner                            | Date Recorded                    | 1/20/2017            |
|                               |   |                                  |                      |
|                               |   |                                  |                      |
|                               |   |                                  |                      |
|                               |   |                                  |                      |
|                               |   |                                  |                      |
|                               |   |                                  |                      |
|                               |   |                                  |                      |
|                               |   |                                  |                      |
|                               |   |                                  |                      |
|                               |   |                                  |                      |
|                               |   |                                  |                      |
| There are hills to the s      | south and west, a house and tree        | s to the north west and open fa  | armland to the east. |
| 5. Description of <b>SETT</b> | 'ING:                                   |                                  |                      |
| 4. Site Area (ft²):           |   |                                  |                      |
|                               |   |                                  |                      |
| NW, on the south side         | of Highway 52.                          |                                  |                      |
| This school is located        | along Highway 52, southwest of          | Carpio about 4 miles. It is loca | ated at 212th Ave    |
| 3. Access (to rural area      | as):                                    |                                  |                      |
|                               |   |                                  |                      |
| Barry and Lisa Clute          |   |                                  |                      |
| 2. Owner's Contact Info       | ormation:                               |                                  |                      |
|                               | <b></b>                                 |                                  |                      |
| Complete one Pag              | ge 4 <u>for the entire s<i>ite</i>.</u> |                                  |                      |

## NDCRS ARCHITECTURAL SITE FORM PAGE 5—SITE DESCRIPTION

| Recorded By (First Name 8       | Last Name)              | Date Recorded       | (mm/dd/year) |
|---------------------------------|-------------------------|---------------------|--------------|
| Recorded By                     | Kathy Wilner            | Data Pacarded       | 1/20/2017    |
|                                 |                         |                     |              |
|                                 |                         |                     |              |
| Bowdon ND 58418                 |                         |                     |              |
| Kathy Wilner<br>366 43rd Ave SE |                         |                     |              |
| 7. References/Comments:         |                         |                     |              |
|                                 |                         |                     |              |
|                                 |                         |                     |              |
|                                 |                         |                     |              |
|                                 |                         |                     |              |
|                                 |                         |                     |              |
|                                 |                         |                     |              |
|                                 |                         |                     |              |
|                                 |                         |                     |              |
|                                 |                         |                     |              |
|                                 |                         |                     |              |
|                                 |                         |                     |              |
|                                 |                         |                     |              |
|                                 |                         |                     |              |
|                                 |                         |                     |              |
|                                 |                         |                     |              |
|                                 |                         |                     |              |
|                                 |                         |                     |              |
|                                 |                         |                     |              |
|                                 |                         |                     |              |
|                                 |                         |                     |              |
|                                 |                         |                     |              |
| 6. Summary of ALL Si            | ite Features & Evaluati | on of Significance: |              |
| Fleid Code Mayland Town         | namp denoti             | 3113# 32_           | IVIII        |
| Field Code Mayland Town         | nship School            | SITS# 32_           | MH           |

Instructions to complete a digital version of this form: (1) Download a copy to your hard drive; (2) Open the saved blank copy; (3) Fill out the form; (4) Use the Save As command to rename the form appropriately and save; (5) *Print* and submit to SHSND.



West Side

Mayland Township School

6/17/2016

Kathy Wilner

WD

North Side





East Side

Mayland Township School

6/17/2016

Kathy Wilner

WD

South Side



**b** bing maps

Notes

Mayland Township School

6/17/2016

Kathy Wilner

WD





Feature