×.

	TECTURAL SITE	FORM	
	PAGE 1	SITS# 32_W	IE 231
SITE IDENTIFICATION			
Field Code Whitby School #3	01 11	1 School 7	13
Map Quad <u>Manfred SE</u> Map Quad	Site Name		
		QQ <u>5</u> QQ QQ	
UTMN UTME	ZONE NAD 1927	NAD 1983	1
City: Chaseley ND			$2 = E\frac{1}{2}$ $3 = S\frac{1}{2}$
Street Number: 835			4 = W ¹ / ₂ 5 = NE ¹ / ₄
Street Name: 34th Ave NE			6 = SE¼ 7 = SW¼
Urban Legal Description:			8 = NW ¹ ⁄ ₄
SITE DATA			
Total # Architectural Features:1			
Fieldwork Date: 9/6/2012			
Reconnaissance Survey <u></u> Intens	ive Survey		
Project Title & Supervisor:			
Country Schoolhouse Project			
Report Title & Author(s):			
Additional Information:			
SHSND USE 2 Ecozone 18 Area of Significance Ecozone Area of Significance Ecozone	Verified Site Non-Site	. CR Type	2
Recorded By Kathy Wilne	Date I	Recorded	9/9/2012 (mm/dd/year)

٠

NDCRS	ARCHITECTURAL SITE FORM
	PAGE 2—Feature Data

Field Code Whitby School #3		SITS# 32_	WE
Complete one Page 2 <u>for e</u>	ach architectural feature	at the site.	
Architectural Feature #1			
Construction Date	Feature Type <u>9</u>	Condition 6	<u> </u>
Feature Date 2	Context 7	Plan Shape	5
Structural System <u>25</u>	Primary Exterior <u>26</u>	Style Other S	Style
Original Owner's Ethnicity	Secondary Exterior	_ Architect/Bui	lder
Other Information:			
Foundation railroad ties		Stories1	
Roof/Cornice gable			
Dating Method(s): <u>county history</u> a	and school records		
	mendation(s) (Check all tha	t apply):	
Feature Preservation Recomm	mendation(s) (Check all tha	t apply):	
Feature Preservation Recomm Individual nomination Contributes to a potential o	mendation(s) (Check all tha	t apply):	
Feature Preservation Recomm Individual nomination Contributes to a potential No nomination potential	mendation(s) (Check all tha		onstitute a district
Feature Preservation Recomm Individual nomination Contributes to a potential No nomination potential	mendation(s) (Check all tha district trict would be a contributing element		onstitute a district
Feature Preservation Recommendation	mendation(s) (Check all tha district trict would be a contributing element		onstitute a district
Feature Preservation Recomm Individual nomination Contributes to a potential No nomination potential Will not contribute to a dist Potential district—feature w Thematic nomination potential Moved (specify all applical recreates original site, original	mendation(s) (Check all that district trict would be a contributing element ential ite or landscape ble choices)—a) relocation occu entation, landscape, & spatial rela s; d) relocation has damaged elig	if other properties c rred within a historic ationships; c) compa	period; b)
Contributes to a potential of No nomination potential Will not contribute to a dist Potential district—feature of Thematic nomination potential Component of a historic sit Moved (specify all applicat recreates original site, ories with neighboring structures	mendation(s) (Check all that district trict would be a contributing element ential ite or landscape ble choices)—a) relocation occu entation, landscape, & spatial rela s; d) relocation has damaged elig	if other properties c rred within a historic ationships; c) compa	period; b)

NDCRS 2009

NDCRS ARCHITECTURAL SITE FORM PAGE 3-Feature Data

Field Code Whitby School #3

SITS# 32 WE

Complete a Page 3 for each feature.

1. Feature Description, Integrity, Eligibility:

A one room school that was moved to this location about 8 years ago. Shakes cover the roof with plans by the owner to put metal on it one day. At this point few of the shakes are missing. The chimney is no longer there, torn down at the time of the move. The double hung windows on the south side still have glass in them but are covered on the inside by insulation. The south end of the building has a small, metal addition on it. As you step through the door in the addition you can see the lines of the porch that used to be on the school. The lap siding is gone on that wall showing horizontal wood planks. Outside the building the siding is 6 inch lap wood siding on the south, west and north sides with 4 inch wood trim boards at the corners. On the north side there is another window with a shutter covering it from the outside. Inside the school the original tongue and groove wood floor is still there as well as the stage at the north end of the building. More tongue and groove flooring there. Just to the right, on the east wall, there are still some coat hooks and a shelf above the hooks. It has electricity today and was wired when it was moved to the present location. The school measures 24 feet east to west and 18 feet north to south.

Recorded By Kathy Wilner Date Recorded 9/9/2012
(First Name & Last Name) (mm/dd/year)

NDCRS ARCHITECTURAL SITE FORM PAGE 4—SITE DESCRIPTION

Field Code Whitby School #3

SITS# 32_WE_____

Complete one Page 4 for the entire site.

2. Owner's Contact Information: Henry Heintz 835 34th Ave NE Chaseley ND 58423

3. Access (to rural areas):

At Highway 200 go north on 34th Ave NE 6 1/2 miles. The farm will be on the left (west) side of the road.

4. Site Area (ft²):

5. Description of SETTING:

The school sits in a farm yard with the house to the northeast, large she and a tree line to the south, yard and farmland to the west and animal inclosures and pasture to the east.

Recorded By Kathy Wilner Date Recorded 9/9/2012
(First Name & Last Name) (mm/dd/year)

NDCRS 2009

NDCRS ARCHITECTURAL SITE FORM PAGE 5—SITE DESCRIPTION

Field Code Whitby School #3

SITS# 32_WE_____

6. Summary of ALL Site Features & Evaluation of Significance:

7. References/Comments: Kathy Wilner 366 43rd Ave SE Bowdon ND 58418

Recorded By Kathy Wilner Date Recorded 9/9/2012
(First Name & Last Name) (mm/dd/year)





South Side


Whitby School #3

9/6/2012 Rathy Wilner WE

East Side







NDCRS 2009

I	NDCRS <i>ARCHITECTUI</i> PAGE 2— <i>Feat</i> i	uro Data	
Field O and	FAGE 2-Feat	OFL	DATE
Field Code Complete one Page	2 for each architectural f	SITS# 32 <u>WE</u> _ eature at the site.	9
Architectural Feature			
Construction Date	Feature Type	Condition 1	
Feature Date	Context	Plan Shape _	
Structural System	_ Primary Exterior	Style	
Original Owner's Ethnicit	y Secondary Exteri	or Architect/Buil	der
Other Information: Informed by Kathy Wilner She found in it is now re	er the school was gone, verified th 2012 it had been e corded as 32WE	at with 2009 aerial. Moved to 147- 231	72 Sec 22 a
Foundation		Stories	_
Window			
Roof/Cornice			
Dating Method(s):			
	Recommendation(s) (Check		
Individual nomina	ation		,
Contributes to a	potential district		
No nomination p	otential		
Will not contribut	e to a district		
Potential district-	-feature would be a contributing	element if other properties co	onstitute a district
Thematic nomina	ation potential		
Component of a	historic site or landscape		
recreates origina	all applicable choices)—a) relocat I site, orientation, landscape, & sp structures; d) relocation has dam	patial relationships; c) compa	
Historical associa	ations require further investigatior	1	
Recorded By	Lorna Meidinger	Dete Deserves d	9/15/2010
		Date Recorded	