Area of Significance _____

Area of Significance _

Ecozone _

NDCRS ARCHITECTURAL SITE FORM PAGE 1

	PAGE 1		SITS# 32 WE 402	
SITE IDENTIFICATION			3113# 32	702
Field Code D Heintz School			chool	
Map Quad Chaseley Map Quad		ame		realization deputing with the control of the contro
LTL TWP R LTL TWP R LTL TWP R LTL TWP R	SEC SEC SEC	QQQ 5 QQQ QQQ QQQ	QQ 5 QQ QQ QQ	Q 6 Q Q Q
UTM 5255513 UTM 438132	N E	ZONE 14N NAD 1927	NAD 1983	Subsection: 1 = N½
City: Chaseley				2 = E½ 3 = S½
Street Number: 34th				4 = W½ 5 = NE¼
Street Name: Ave NE 6 = SE¼ 7 = SW¼				
Urban Legal Description:				8 = NW1/4
SITE DATA				
Total # Architectural Features:	1			
Fieldwork Date: 11/02/2018				
Reconnaissance Survey Intensive Survey				
Project Title & Supervisor:				
Country Schoolhouse Project				
Report Title & Author(s):				
Additional Information:				
SHSND USE Area of Significance Ecozone	19	erified Site	_ CR Type	2

Recorded By Kathy Wilner Date Recorded 1/22/2018 (First Name & Last Name) (mm/dd/year)

Non-Site __

NDCRS ARCHITECTURAL SITE FORM PAGE 2—Feature Data

Field Code D Heintz Sc	hool	SITS# 32 WE		
Complete one Page 2 for each architectural feature at the site.				
Architectural Feature #	1			
Construction Date	Feature Type	9 Condition 6		
Feature Date 2	Context 7	Plan Shape 6		
Structural System 25	Primary Exteri	ior 26 Style Other Style		
Original Owner's Ethnicity _	Secondary Ex	terior Architect/Builder		
Other Information:				
Foundation Concrete pad		Stories 1		
Roof/Cornice Hip				
	the remainder are smaller, f	fixed pane replacement windows		
Dating Method(s): Estimate				
Feature Preservation Re	ecommendation(s) (Ch	eck all that apply):		
Individual nomination	on			
Contributes to a pot	ential district			
No nomination pote	ntial			
Will not contribute to a district				
Potential district—feature would be a contributing element if other properties constitute a district				
Thematic nomination potential				
Component of a historic site or landscape				
Moved (specify all applicable choices)—a) relocation occurred within a historic period; b) recreates original site, orientation, landscape, & spatial relationships; c) compatible in context —with neighboring structures; d) relocation has damaged eligibility				
Historical associations require further investigation				
Recorded By(First Name 8	Kathy Wilner	Date Recorded 1/22/2018 (mm/dd/year)		

NDCRS ARCHITECTURAL SITE FORM PAGE 3—Feature Data

Field Code D Heintz School	SITS# 32 VVE
Tiola odac	

Complete a Page 3 for each feature.

1. Feature Description, Integrity, Eligibility:

The feature is a one room prairie school that sits on a concrete pad. It was moved to this location for use as a storage shed. The hip roof is covered with asphalt shingles. There is a newer, concrete chimney on the north slope of the roof. The soffits are open. The square building measures 24 by 24 feet.

The siding is 6 inch wood lap with 4 inch wood corner trim. The building is painted red with white trim on the corners and around the windows. On the east side there is a wood entry door with two fixed pane windows either side. They are not original to the school. On the south side there is one double hung window window and a sliding door. The west and north walls both have two windows openings, two are covered (one on each side) and two are replacement, fixed pane windows. All glass intact. The floor in a small room in the southeast corner of the building has tongue and groove hardwood, the remainder of the flooring in the building is concrete. The walls and ceiling are mostly lathe, nearly all of the plaster has either fallen off or been removed. The ceiling is metal sheeting. there are no blackboards, wainscot or electricity. Story has it that the school was at one time used as a teacherage.

Recorded By	Kathy Wilner	Date Recorded 1/22/2018
	/First Name & Last Name)	(mm/dd/yoan)

NDCRS ARCHITECTURAL SITE FORM PAGE 4—SITE DESCRIPTION

Field Code D Heintz	School	SITS# 32 VVE
Complete one Page	4 for the entire site.	
 Owner's Contact Inforr Dorothy Heintz Parkview Rd Winterville GA. 30683 	mation:	
3. Access (to rural areas) Located in Chaseley, abo	: out 1 miles north of Highway	<i>t</i> 200.
4. Site Area (ft²):		
was used as a general s	moved to this location to be	e used for storage. It sits behind a large house that other crumbling house to the north, a field and e south.
Recorded By	Kathy Wilner	Date Recorded 1/22/2018 (mm/dd/year)

NDCRS ARCHITECTURAL SITE FORM PAGE 5—SITE DESCRIPTION

Field Code D Heintz Scho	ool		SITS# 32	E
6. Summary of ALL Site	Features & E	Evaluation of	Significance:	
7. References/Comments:				
Kathy Wilner 366 43rd Ave SE				
Bowdon ND 58418				
Recorded By (First Name & La	Kathy Wilne	er	Date Recorded 1/2	2/2018



East Side


D Heintz School

11/2/2017

Kathy Wilner

WE

South Side



1/22/2018 Google Maps




D Heintz School

11/02/2017

Kathy Wilner

WE





West Side

D Heintz School

11/02/2017

Kathy Wilner

WE

