# NDCRS ARCHITECTURAL SITE FORM PAGE 1

SITS# 32 WI 2/82

SITE IDENTIFICATION			
Field Code Pleasant Valley Twsp School			
Map Quad Tiona SE Map Quad	Site Name		
LTL TWP R SEC LTL TWP R SEC		QQ	Q <u>6</u> Q Q Q
UTMN UTME	ZONE NAD 1927 _	NAD 1983	1
City:			2 = E½ 3 = S½
Street Number:			4 = W½ 5 = NE¼
Street Name: 100th Ave NW			6 = SE¼ 7 = SW¼
Urban Legal Description:	dissance variation grate and many distributions of which hymnica distributions are and design that		8 = NW1/4
SITE DATA			
Total # Architectural Features: 1	approximation in		
Fieldwork Date: 8/22/2016			
Reconnaissance Survey ✓ Inten	sive Survey		
Project Title & Supervisor:			
Country Schoolhouse Project			
Report Title & Author(s):			
Additional Information:			
SHSND USE Area of Significance Area of Significance Ecozone Ecozone	Verified Site	CR Type	_2_
Recorded By Kathy Wiln	er Dat	e Recorded	2/4/2017
(First Name & Last Name)			(mm/dd/year)

# NDCRS ARCHITECTURAL SITE FORM PAGE 2—Feature Data

Field Code Pleasant Valley	SITS# 32WI				
Complete one Page 2 <u>for each architectural feature</u> at the site.					
Architectural Feature # _	1				
Construction Date	Feature Type9	Condition 4			
Feature Date 3	Context 7	Plan Shape 2			
Structural System 25	Primary Exterior 26	Style Other Style			
Original Owner's Ethnicity	Secondary Exterior	Architect/Builder			
Other Information:					
Foundation Poured concrete		Stories 1.0			
Roof/Cornice Hip, half hip, gal	ble, mansard on entry, pyramidal be	ell tower			
Window Openings, no glass, I	ittle framing				
Dating Method(s): Estimate					
Individual nominationContributes to a poterNo nomination potentiWill not contribute to a	ial a district	at apply):  It if other properties constitute a district			
Thematic nomination	potential				
——Component of a histor	ric site or landscape				
Moved (specify all applicable choices)—a) relocation occurred within a historic period; b) recreates original site, orientation, landscape, & spatial relationships; c) compatible in context —with neighboring structures; d) relocation has damaged eligibility  —Historical associations require further investigation					
Recorded By	Kathy Wilner	Date Recorded 2/4/2017 (mm/dd/year)			

### NDCRS ARCHITECTURAL SITE FORM PAGE 3—Feature Data

Fiel	d	Cod	e P	leasant	Val	ley T	wsp	School	

SITS	# 32	W	/1
	300 32		

#### Complete a Page 3 for each feature.

### 1. Feature Description, Integrity, Eligibility:

The feature is a one room prairie school on a poured concrete foundation. The hip roof of the main body, half hip of the south addition, mansard base/roof on the entry, the pyramidal roof of the bell tower and gable roof of the porch are all covered with wood shakes. There is metal capping and some finials. the bell tower is above the entry and there is a tall mansard roof that is the base for the top of the tower which is held up by 4 corner posts. At the peak there is a flagpole. The soffits are closed. The building measures 24 feet north to south and 30 feet east to west with the entry and porch measureing 12 feet by 8 feet and the south addition is 8 feet by 21 feet.

There is a wide trim board under the soffits on all sides of the school as well as the gable end of the porch. The remainder of the siding is 6 inch wood lap with 6 inch wood corner trim. The porch on the south side has a door opening leading to a 5 panel wood entry door. Just to the right of the entry are coatrooms and toilets. The main room of the school can be reached from a door straight in from the entry or another door at the southeast corner from the coatrooms. The interior walls are covered with lathe and plaster that is in tough shape. The walls have a picture railing trim on all walls. The ceiling is lathe and plaster which has been covered with wallboard, some of this falling into the school. The floor is tongue and groove hardwood and there are holes. There are three windows openings in south addition, two double hung on the south wall and another on the west wall, no glass and little framing. There are three window openings on the north side and 4 on the east side, all large double hung, little framing, with transom window openings above all these windows. No glass anywhere. Blackboards have been removed, they used to hang on the west wall and the south wall of the school room between the doors. Wiring and fixtures suggest electricity.

Recorded By	Kathy Wilner	Date Recorded	2/4/2017	
•	(First Name & Last Name)		(mm/dd/year)	

# NDCRS ARCHITECTURAL SITE FORM PAGE 4—SITE DESCRIPTION

Field Code Pleasant Valley Twsp School	SITS# 32_WI
Complete one Page 4 <u>for the entire site</u> .	
2. Owner's Contact Information:	
Pleasant Valley Township	
3. Access (to rural areas):	
Tioga, south on Highway 40 to Highway 2, east 4 miles miles to see the school on the west side of the road.	to 100th Ave NW, turn right and drive south 2 1/
4. Site Area (ft²):	
5. Description of <b>SETTING</b> :	
There is a farm to the north east and crop land and pas	sture all directions.
Recorded By Kathy Wilner (First Name & Last Name)	Date Recorded 2/4/2017 (mm/dd/year)

# NDCRS ARCHITECTURAL SITE FORM PAGE 5—SITE DESCRIPTION

Field Code Pleasant Valley	Twsp School	SITS# 32_	wı	
6. Summary of ALL Site Features & Evaluation of Significance:				
7. References/Comments:				
Kathy Wilner 366 43rd Ave SE				
Bowdon ND 58418				
Recorded By	Kathy Wilner	_ Date Recorded	2/4/2017	



East Side

Pleasant Valley Township School 8/22/2016

Kathy Wilner

WI



North Side



South Side

Pleasant Valley Township School 8/22/2016

Kathy Wilner

WI








Notes

Pleasant View Township School

8/22/2016

Kathy Wilner

WI





Feature