.

. . .

2.2

.

Field Code Judson School				
SITE IDENTIFICATION		SITS# 32 WI <u>2342</u>		
Map Quad Williston East	Site Name Judson School			
Map Quad	Site Name			
LTLTWP R SE LTLTWP R SE	EC 36 QQQ 8 QQ 8 Q 7 EC QQQ QQ QQ Q Q 0 0 EC QQQ QQ QQ Q Q 0 0 EC QQQ QQ QQ Q Q Q 0			
NAD 1983, UTM 5339903 N NAD 1983, UTM 602191 E	1 = N½	r		
City: Williston	$2 = E\frac{1}{2}$ $3 = S\frac{1}{2}$			
Street Number:	$4 = W \frac{1}{2}$ 5 = NE ¹ / ₄			
Street Name: 2nd Ave West	6 = SE¼ 7 = SW¼			
Urban Legal Description:	8 = NW¼			
SITE DATA				
Total # Architectural Features: 1				
Fieldwork Date: 6/12/2018				
Reconnaissance Survey 👱 Int	ntensive Survey			
Project & Principal Investigator: Country Schoolhouse Project				
Report Title & Author(s):				
Contracting firm or Agency completing the	form:			
Additional Information:				
SHSND USE Ecozone Area of Significance Ecozone Area of Significance Ecozone Area of Significance Ecozone	∠l Verified Site ⊥ CR Type ∠			
Recorded By Kathy Wilner	Date Recorded 1/22/2019			
(First Name & Last Name)	Date Recorded(mm/dd/year)	-		

Field Code Judson School		SITS# 32 ^{WI}	
Complete one Page 2 for ea	ch architectural featur	re at the site.	
Architectural Feature #1			
Construction Date	Feature Type 9	Condition 7	
Feature Date	Context 7	Plan Shape 5	_
Structural System 25	Primary Exterior 26	Style Other Style	
Original Owner's Ethnicity ———	Secondary Exterior	A Architect/Builder	
Other Information:			
Foundation Poured concrete		Stories 1	
Roof/Cornice Hip, small dormer			
Window Double hung, glass			
Dating Method(s):			

Feature Preservation Recommendation(s) (Check all that apply):

- Individual nomination
- Contributes to a potential district
- ____No nomination potential
- ____Will not contribute to a district

____Potential district—feature would be a contributing element if other properties constitute a district

____ Thematic nomination potential

Component of a historic site or landscape

Moved (specify all applicable choices)—a) relocation occurred within a historic period; b) recreates original site, orientation, landscape, & spatial relationships; c) compatible in context with neighboring structures; d) relocation has damaged eligibility

_____Historical associations require further investigation

Recorded By	Kathy Wilner	Date Recorded	1/22/2019
	(First Name & Last Name)		(mm/dd/year)

NDCRS ARCHITECTURAL SITE FORM PAGE 3—Feature Data

Field Code Judson School

SITS# 32 WI

Complete a Page 3 for each feature.

1. Feature Description, Integrity, Eligibility:

The feature is a one room prairie school on a foundation of poured concrete foundation. This school was moved from Judson Township west of Williston. The hip roof is covered with asphalt shingles as it the dormer roof. The dormer is on the east facing slope of the roof and a window opening is boarded up. There is a concrete block chimney, with a stove pipe sticking out the top, to the north of the dormer. The soffits are closed with beadboard finish. The building measures 24 feet north to south and 30 feet east to west.

A frieze board runs under the eaves on all side of the school. The siding is 4 inch wood lap with 4 inch corner trim. There is a wood porch at the northeast corner of the school, tucked under the buildig roof. the north side of the porch has a railing with a cornerpost supporting the roof. Entry is through a 5 pane wood door which is kept locked when no one is around. There is one small double hung window on the east wall, this lights up the entry/coatroom. There are four larger double hung windows on the north side as well as two more on the west side. All the windows have glass. The interior door is another 5 panel wood door. The interior of the school room is undergoing some renovation as they has water damage. The ceiing and walls were lathe and plaster and they are replacing some of the damage with sheetrock. There is a plate rail in line with the tops of the windows. The window trim is dark and well kept. A wide mop board finishes the walls. There are blackboard along the entire south wall and it corners to the east wall over to the entry door. The chimney inside is to the right of the door as you walk into the room and just beyond that is a large cupboard. All other furnishings are in storage. The floor is tongue and groove fir. Light fixtures indicate electricity.

The school was built in 1914 and closed in 1950.

Recorded By	Kathy Wilner	Date Recorded 1/22/2019
	(First Name & Last Name)	(mm/dd/year)

NDCRS ARCHITECTURAL SITE FORM PAGE 4—SITE DESCRIPTION

Field Code Judson School

SITS# 32^{WI}

Complete one Page 4 for the entire site.

2. Owner's Contact Information: The Frontier Museum PO Box 285 Williston ND 58802

3. Access (to rural areas):

In Williston, north side, go to 2nd Ave West which parallels the Can Am Hwy. It is located south of 65th St E. The school is west of 2nd Ave West and on the grounds right in front of Museum School #2.

- 4. Site Area (ft²): _____
- 5. Description of SETTING:

This building is set in a Frontier Village with buildings east, north and south with trees directly west.

Recorded By	Kathy Wilner	Date Recorded 1/22/2019
	(First Name & Last Name)	(mm/dd/year)

NDCRS ARCHITECTURAL SITE FORM PAGE 5—SITE DESCRIPTION

Field Code Judson School

SITS# 32

6. Summary of ALL Site Features & Evaluation of Significance:

	References/Comments: Kathy Wilner
18	366 43rd Ave SE
10	Bowdon ND 58418


Recorded By	Kathy Wilner	Date Recorded	1/22/2019	
	(First Name & Last Name)		(mm/dd/year)	





Imagery ©2019 Google, Map data ©2019 Google 100 ft

Feature




North Side

Judson School

6/12/2018

Kathy Wilner

WI



West Side




East Side

Judson School

6/12/2018

Kathy Wilner

WI



South Side